# PHILCO



# 1938 CHANGES IN MODELS



# Since Publication of Each Service Bulletin

Grouped under each model and arranged according to Run No. Covers changes from January 1st to May 1st, 1938.

The following page contains complete listings of all major changes—involving changes in circuit, part numbers or anything of interest to the serviceman—in Philco models current at the time of printing. These are all the changes which have been made since the date of publication of the last printing of the Philco Service Bulletin on each model; the number of the Bulletin is given in each case for reference.

Ownership of this sheet in addition to Service Bulletins, gives the serviceman a complete record on each model; thus he will not be inconvenienced at finding, when servicing a current set, that it differs from that shown in the original Service Bulletin.

The Model, Code and Run Numbers are stamped on the rear of the chassis.

### Model 38-4

Service Bulletin 281

Run 5

The two condensers, Part No. 30-1097, which were connected in parallel with the new air padder (16), Part No. 31-6206, in Run 3 receivers, are removed beginning with Run 5. In place of these condensers, a Thermal Compensator, Part No. 31-6227 is connected in parallel with the air padder. The air padder (16), Part No. 31-6206 has also been relocated and is now mounted between the 6U7G R. F. tube and the 6F6G output tube. The Thermal Compensator, Part No. 31-6227, is also mounted in the same position with the thermostatic plate facing the power transformer.

The oscillator transformer (15) was chossed from Part No. 32-3631.

The oscillator transformer (15) was changed from Part No. 32-2631 to Part No. 32-2894. Connection No. 1 of the new transformer has been increased in length for soldering to the air padder in the new location.

#### Model 38-7 (Codes 121, 124)

Service Bulletin 280

#### REPLACEMENT PART DIFFERENCES BETWEEN CODES 121, 124

Schem	No.	Description	Part No. Code 121	Part No. Code 124
(32) (38) (45) (47)	Resistor ( Condenser Electrolyti Condenser Cable (Por	(.01 mfd. tubular) 51000 ohms ½ watt) (.006 mfd. tubular) c Condenser (.015, .015 mfd.) wer)	30-4479 33-351339 30-4467 30-2219 3793-DG L-2778	30-4201 (.001 mfd.) 33-340339 30-4479 (.01 mfd.) 30-2228 3793-ODG L-2183 41-3345

### Model 38-7 (Codes 121, 124)

Service Bulletin 280

#### Models 38-8-38-9 (Code 121)

Service Bulletin 280

Run 7-38-7; Run 7-38-8; Run 5-38-9

Resistor (9) Part No. 33-370339, 70,000 ohms changed to 40,000 ohms Part No. 33-340339. This change made to improve the oscillator circuit performance.

Run 6-38-7 (121-124); Run 6-38-8 (121); Run 4-38-9 (121):

In order to prevent oscillation, condenser (14) was removed from the rear of the chassis and mounted in back of the volume control. No change in the circuit, rearrangement of parts only.

# Model 38-10 (Codes 121, 124)

Service Bulletin 283

CIRCUIT DIFFERENCE BETWEEN CODES 121 AND 124

	Schem	No. Description	Code 121	Code 124
(45) (47)		Condenser (Electrolytic 12 mfd.) Condenser (.015 mfd. Dual Bakelite)	30-2210 3793-DG	30-2131 3793-ODG
	3	Cable (Power	L-2778 L-2840	L-2183 L-2980

# Model 38-10 (Codes 121, 124)

Service Bulletin 283

Resistor (11) Part No. 33-370339, 70,000 ohms changed to 40,000 ohms, Part No. 33-340339. This change made to improve the oscillator circuit performance,

# Model 38-14 (Codes 121, 124)

Service Bulletin 288

Run 4, Code 121

To eliminate hum modulation, Electrolytic Condenser (32), Part No. 30-2246, 16 mfd., was changed to Part No. 30-2237, 40 mfd. The electrolytic condenser (32) in code 124 receivers is changed from Part No. 30-2277, 16 mfd., to Part No. 30-2256, 40 mfd.

Run 3, Code 121; Run 2, Code 124

Oscillator Blocking Condenser (8) 250 mmfd. Part No. 30-1032, changed to 50 mmfd., Part No. 30-1029.

#### Model 38-33 (Code 121)

Service Bulletin 292

CIRCUIT CHANGE IN SCREEN VOLTAGE SUPPLY

Beginning with Run 3 Resistor (20) Part No. 33-280339 was changed to 20,000 ohms, Part No. 33-320339. This new Resistor (20000) was removed from the 90 volt wire and reconnected to the 135 volt wire of the battery cable. The battery cable assembly was also changed from Part No. 41-3203 to Part No. 41-3402.

#### Model 38-623

Beginning with Run 2, Resistor (42) Part No. 33-280339 was changed to 20,000 ohms, Part No. 33-320339. The new resistor (20000) was removed from the 90 volt wire of the battery cable. The battery cable assembly was also changed from Part No. 41-3198 to Part No. 41-3394.

#### Model 38-624 (Codes 121, 125)

The following circuit changes were made to reduce electrical hum, beginning with Run 6 receivers.

Schem	No.		Descri	pti	on	Old Part No.	New Part No.
(36) (47)	Resistor Resistor	(1	megohm,	1/2 1/2	watt)	33-510339 33-510339	33-475339 33-540339

In sets prior to Run 6, the 20 ohm filament Resistor (38) on the diagram was located in the power unit adjacent to the On-Off Switch. This resistor, beginning with Run 6, is located in the I. F. unit near the Volume Control.

# Model 37-620 (Code 125)

Service Bulletin 251A

#### Model 37-630 (Codes 125, 126)

CORF. Schen	RECTION 1. No.	Listed as	Should be	
(69) (70)	R. F. Range Switch		42-1283 42-1282	

#### Model 38-116 (Code 125)

Service Bulletin 286A

CORRECTION: Schematic Diagram and Parts List

Schem. No.	Part No.	Corrected Part No.
(43) Resistor (40,000 ohms, 1 watt)	33-340439	33-240439