


PHILCO

Service Bulletin — No. 120B


Location of Compensating Condensers, Models 70 and 90



Model 70

(Above Serial No. B-22,000)

Adjust I.F. compensating condensers at 260 K.C.



Model 90

(Serial Nos. B-32,001 to B-35,000 and above B-53,100)

Adjust I.F. compensating condensers and coupling condenser at ~~175~~ 260 K.C.

PHILCO

Service Department