

PHILCO

REG. U.S. PAT. OFF.

RADIO PARTS

LIST PRICES

Arranged According to Part Numbers



AUGUST 1, 1941

PHILCO RADIO AND TELEVISION CORPORATION
PARTS AND SERVICE DIVISION

This price list supersedes and cancels all previous price lists and all prices appearing in other service department publications or printed matter.

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|----------|--------------|----------|-------------|----------|--------------|----------|--------------|
| 13100 | .15 | 2850 | 5.50 | 3653 | 4.10 | 4234 | 7.00 |
| 13148 | .35 | 2903 | pr. 1.20 | 3675 | .60 | 4235 | 4.50 |
| 13163 | .30 | 3012 | .05 | 3744-A | 1.80 | 4255 | .02 |
| 13166 | .15 | 3014 | .03 | 3744-B | 1.50 | 4264 | .60 |
| 13167 | .25 | 3025A | .40 | 3744-C | 2.10 | 4268 | 13.50 |
| 14100 | .20 | 3045 | per 100 .60 | 3752 | 8.00 | 4273 | .04 |
| 16201 | .75 | 3047 | .10 | 3753 | 17.00 | 4276 | .25 |
| 16304 | .20 | 3073 | 7.50 | 3754 | 7.50 | 4277 | .02 |
| 20106 | .15 | 3075A | 1.50 | 3755 | 15.50 | 4286 | .01 |
| 20113 | .15 | 3075B | 1.50 | 3762 | 1.15 | 4289-A | .10 |
| 20156 | per 100 .25 | 3076 | 1.40 | 3763 | .35 | 4318 | .02 |
| 21101 | .10 | 3077 | 3.60 | 3764 | .25 | 4319 | .05 |
| 21102 | .20 | 3078 | 3.00 | 3775-B | .85 | 4383-A | .12 |
| 23103 | .05 | 3082 | .20 | 3777 | .20 | 4401-B | .90 |
| 33110 | 2.75 | 3086 | .70 | 3790 | 1.55 | 4401-E | 2.40 |
| 40168 | .70 | 3087 | .45 | 3793-SG | .35 | 4401-F | 2.40 |
| 40169 | .70 | 3088 | 2.00 | 3793-ODG | .40 | 4401-G | .90 |
| 41118 | 1.25 | 3093 | per 100 .75 | 3793-ODU | .40 | 4407 | .50 |
| 41119 | 1.00 | 3096 | .60 | 3793-OSU | .35 | 4408 | .40 |
| 43118 | 1.25 | 3098 | .02 | 3794 | .20 | 4416 | .20 |
| 49115 | 1.45 | 3106 | 10.00 | 3864 | .75 | 4418 | 2.25 |
| 60110 | 4.75 | 3116 | .45 | 3865 | 1.20 | 4428-A | .50 |
| 77107 | .10 | 3117 | .75 | 3869 | 16.25 | 4434 | .18 |
| 80568 | .50 | 3151 | .08 | 3870 | 7.50 | 4436 | per 100 1.50 |
| 90100 | .50 | 3164 | .20 | 3872 | 2.50 | 4441-A | 13.20 |
| 90101 | .15 | 3232 | 1.95 | 3879 | 1.00 | 4443 | .30 |
| 90230 | .45 | 3241 | 2.75 | 3884-A | 1.10 | 4446 | 7.00 |
| 90236 | 1.50 | 3242 | 2.75 | 3884-C | 1.20 | 4447 | 14.85 |
| 90237 | .20 | 3253 | .45 | 3884-N | 1.10 | 4461 | .45 |
| 90242 | .30 | 3256A | 4.25 | 3884-P | 1.30 | 4462 | .75 |
| 90245 | .20 | 3269 | 3.00 | 3884-S | 1.00 | 4463 | 1.80 |
| 90430 | 5.50 | 3271 | 7.50 | 3884-T | .70 | 4475 | .01 |
| | | 3278 | 20.00 | 3884-U | 1.10 | 4485 | 1.80 |
| 2524 | 2.25 | 3283 | .02 | 3884-V | 1.20 | 4486 | .02 |
| 2525 | 2.50 | 3398 | .10 | 3884-X | 1.00 | 4504 | 12.00 |
| 2526 | 2.25 | 3399 | 1.50 | 3884-Y | .80 | 4513 | 1.00 |
| 2528 | 1.40 | 3400 | 7.50 | 3892-A | .15 | 4514 | 1.50 |
| 2535 | 1.30 | 3401 | 14.00 | 3903-DU | .30 | 4519 | .15 |
| 2538 | per 100 2.00 | 3422 | 3.00 | 3903-LU | .30 | 4520 | .25 |
| 2544 | 1.75 | 3435A | .20 | 3903-ODG | .30 | 4522 | .75 |
| 2550 | 1.75 | 3463 | .09 | 3903-ODU | .30 | 4531 | .30 |
| 2551 | 1.25 | 3464A | .45 | 3903-OSG | .25 | 4532 | .50 |
| 2557 | 1.35 | 3472 | 4.25 | 3903-OSU | .25 | 4535 | .75 |
| 2562 | 1.85 | 3479 | .55 | 3910 | .20 | 4539 | .30 |
| 2564 | 1.25 | 3484 | ft. .17 | 3914 | .02 | 4540 | .05 |
| 2565 | 1.50 | 3484A | .50 | 3915 | .02 | 4543 | 20.50 |
| 2580 | 1.00 | 3501 | .55 | 4014 | .40 | 4546 | .30 |
| 2585 | 1.25 | 3406A | 1.80 | 4016-A | .20 | 4566 | .25 |
| 2588 | 2.00 | 3506-B | 1.30 | 4020-A | .25 | 4567 | .09 |
| 2589 | 2.00 | 3512 | 1.50 | 4027-A | .20 | 4568 | 1.10 |
| 2590 | 1.50 | 3515 | 13.50 | 4029 | .04 | 4569 | 1.30 |
| 2598 | 1.25 | 3518 | 3.30 | 4042 | .02 | 4587 | .15 |
| 2614 | 2.40 | 3528 | 1.20 | 4056 | 1.00 | 4705 | 1.20 |
| 2616 | .03 | 3537 | 3.15 | 4057 | .95 | 4712 | .08 |
| 2646 | 1.45 | 3557 | .70 | 4058 | 5.70 | 4737 | 10.00 |
| 2651 | 1.80 | 3559 | per 100 .50 | 4059 | .35 | 4748 | 1.65 |
| 2660 | 1.00 | 3579-A | .10 | 4062 | .95 | 4749 | 4.50 |
| 2660 | 1.00 | 3580-A | .15 | 4067 | 6.60 | 4771 | .30 |
| 2673 | 1.50 | 3583 | .60 | 4076-A | .02 | 4784 | 35.00 |
| 2675 | .03 | 3615-K | .40 | 4089 | 38.50 | 4785 | 38.00 |
| 2675 | .03 | 3615-Y | .40 | 4091 | .30 | 4786 | 22.50 |
| 2694 | 1.20 | 3615-Z | .40 | 4092 | .01 | 4813 | 7.00 |
| 2702 | .05 | 3615-AG | .35 | 4093 | 1.40 | 4817 | 2.30 |
| 2706 | 1.50 | 3615-AS | .40 | 4094 | 1.80 | 4819 | 1.80 |
| 2707 | 4.80 | 3615-XG | .40 | 4098 | 1.45 | 4824 | .85 |
| 2749B | .50 | 3615-YU | .40 | 4100 | 21.00 | 4831 | .12 |
| 2764A | 1.00 | 3615-ODG | .40 | 4107 | 12.50 | 4851 | .30 |
| 2766 | 1.75 | 3615-ODU | .40 | 4108 | .18 | 4853 | 11.50 |
| 2766 | 1.75 | 3615-OSG | .35 | 4118 | .60 | 4855 | .18 |
| 2768 | 2.00 | 3615-OSU | .35 | 4120 | 2.50 | 4858 | .90 |
| 2799 | 2.70 | 3628 | .20 | 4121 | .20 | 4860 | 5.10 |
| 2848 | 1.75 | 3651 | 11.75 | 4124 | .75 | 4861 | .25 |
| | | 3652 | 12.50 | 4141 | 1.80 | 4862 | 2.00 |
| | | | | 4142 | .25 | 4864 | .70 |
| | | | | 4168 | per 100 1.80 | 4871-A | .75 |
| | | | | 4169 | per 100 1.20 | 4878 | 10.00 |
| | | | | 4182-A | .90 | 4885 | .10 |
| | | | | 4182-B | 1.50 | 4886 | 1.80 |
| | | | | 4200-A | 5.70 | 4897 | per 100 .50 |
| | | | | 4209-B | .50 | 4916 | 1.20 |
| | | | | 4211 | .06 | 4938 | 7.50 |
| | | | | 4212B | .75 | 4939 | 12.20 |
| | | | | 4230 | 1.00 | 4948 | .20 |
| | | | | 4231 | 1.80 | 4952 | 2.25 |
| | | | | 4232 | 2.50 | 4953 | .70 |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | |
|----------|------------|----------|------------|----------|------------|----------|------------|-----|
| 4954 | .03 | 5878 | .25 | 6658 | 1.50 | 7625-F | .30 | |
| 4961 | .25 | 5886 | .30 | 6669 | .50 | 7625-DG | .30 | |
| 4962 | .90 | 5906 | 1.76 | 6672 | 7.50 | 7625-SG | .25 | |
| 4986 | 13.00 | 5923 | 2.40 | 6673 | 10.50 | 7625-SU | .25 | |
| 4989-E | .40 | 5924 | 2.15 | 6694 | 1.20 | 7625-ODU | .30 | |
| 4989-L | .40 | 5930 | 1.75 | 6700 | .25 | 7652 | 1.80 | |
| 4989-W | .40 | 5973 | .10 | 6702 | .50 | 7653-D | .35 | |
| 4989-AA | .40 | 5982 | .40 | 6705 | 1.15 | 7653-DG | .40 | |
| 4989-AG | .40 | 6008 | .50 | 6706 | 1.55 | 7653-ODU | .40 | |
| 4989-CU | .40 | 6009 | .40 | 6712 | 1.50 | 7653-OSG | .35 | |
| 4989-FG | .40 | 6015 | 1.00 | 6716 | .20 | 7653-OSU | .35 | |
| 4989-HG | .40 | 6021 | .25 | 6717 | .02 | 7675-E | 22.00 | |
| 4989-SU | .35 | 6022 | .30 | 6773 | .30 | 7688 | .20 | |
| 4989-OFU | .40 | 6029 | 1.00 | 6780 | 1.50 | 7696 | .35 | |
| 4989-ODG | .40 | 6030 | .70 | 6804 | 5.50 | 7739 | 3.00 | |
| 4989-ODU | .40 | 6031 | .14 | 6805 | 8.50 | 7741 | .25 | |
| 4989-OSG | .35 | 6035 | .25 | 6806 | 8.00 | 7762-DG | .30 | |
| 4990 | .15 | 6036 | .45 | 6807 | .40 | 7762-DU | .30 | |
| 5009 | .25 | 5039 | .05 | 6808 | .25 | 7762-FU | .30 | |
| 5039 | 1.80 | 6042 | per 100 | 1.80 | 6811 | .07 | 7762-SG | .25 |
| 5051 | .04 | 6043 | .30 | 6822 | per 100 | 1.50 | 7762-OEU | .30 |
| 5053 | .35 | 6044 | .03 | 6826 | .25 | 7762-OSU | .25 | |
| 5056 | 2.25 | 6072 | 6.25 | 6833 | 1.00 | 7847 | .95 | |
| 5058 | per 100 | 6073 | 6.75 | 6853 | .40 | 7852 | .25 | |
| 5084 | .15 | 6091 | pr. | 6892 | 1.45 | 7852 | .30 | |
| 5095 | .10 | 6109 | 1.45 | 6893 | 1.85 | 7932 | .05 | |
| 5110 | .30 | 6111 | per 100 | .90 | 6895 | 3.00 | 7933 | .06 |
| 5117 | 6.50 | 6122 | per 100 | 3.50 | 6898 | .25 | 7941 | .12 |
| 5118 | 7.50 | 6128 | 1.20 | 6977 | .20 | 7942 | .25 | |
| 5120 | .20 | 6129 | 1.20 | 6985 | 5.00 | 7993 | .30 | |
| 5125 | .75 | 6206 | per 100 | .60 | 6986 | 5.85 | 7998 | .30 |
| 5167 | 1.75 | 6221 | per 100 | 1.00 | 7017 | .65 | 8000 | .12 |
| 5168 | .70 | 6223 | per 100 | 2.30 | 7018 | .50 | 8004 | .03 |
| 5170 | 1.45 | 6287-D | .40 | 7019 | .40 | 8005 | .10 | |
| 5171 | 1.00 | 6287-G | .40 | 7020 | .40 | 8022 | 1.30 | |
| 5178 | .25 | 6287-M | .40 | 7021 | .40 | 8035-T | .25 | |
| 5189 | .03 | 6287-S | .40 | 7022 | .40 | 8035-EU | .30 | |
| 5215 | .25 | 6287-CU | .40 | 7049 | 1.00 | 8035-SG | .25 | |
| 5232 | 1.80 | 6287-SG | .35 | 7050 | 1.00 | 8035-SU | .25 | |
| 5266 | 4.25 | 6287-SU | .35 | 7065 | .85 | 8035-ODG | .30 | |
| 5267 | 6.00 | 6287-ODG | .40 | 7074 | 4.50 | 8035-ODU | .30 | |
| 5311 | .25 | 6287-ODU | .40 | 7076 | 5.20 | 8046 | 3.50 | |
| 5314 | 2.10 | 6298 | 1.50 | 7078 | .12 | 8047 | 5.00 | |
| 5315 | 2.25 | 6299 | 1.50 | 7096 | 1.50 | 8048 | 4.85 | |
| 5316 | .20 | 6307 | 2.00 | 7122 | .45 | 8054 | 1.00 | |
| 5317 | 1.80 | 6308 | 2.50 | 7123 | .12 | 8055 | .25 | |
| 5318 | 1.20 | 6336 | 31.50 | 7139 | .35 | 8056 | .05 | |
| 5357 | .05 | 6337 | 37.00 | 7155 | .30 | 8095 | 1.10 | |
| 5362 | 6.25 | 6338 | 31.50 | 7172 | .12 | 8133 | .12 | |
| 5363 | 8.50 | 6345 | 4.25 | 7173 | .03 | 8147 | .03 | |
| 5364 | 6.25 | 6351 | .80 | 7217 | .20 | 8166 | .90 | |
| 5365 | .50 | 6352 | .80 | 7227 | .05 | 8170 | 1.00 | |
| 5382 | .45 | 6355 | 3.00 | 7239 | 1.80 | 8171 | 3.00 | |
| 5386 | .02 | 6356 | 3.00 | 7250 | .25 | 8174-B | .40 | |
| 5440 | .50 | 6359 | .60 | 7283 | 1.50 | 8174-DG | .30 | |
| 5459 | .50 | 6413 | .20 | 7296-G | .40 | 8174-DU | .30 | |
| 5462 | .50 | 6415 | 1.00 | 7296-H | .30 | 8174-SG | .25 | |
| 5477 | .20 | 6416 | .45 | 7296-DG | .30 | 8174-SU | .25 | |
| 5478 | .20 | 6435 | .25 | 7296-SG | .25 | 8205-B | .35 | |
| 5479 | .10 | 6438 | 1.50 | 7296-SU | .25 | 8220 | 4.10 | |
| 5561 | 2.00 | 6440 | .10 | 7296-ODU | .30 | 8255 | .30 | |
| 5563 | 9.50 | 6441 | per 100 | .55 | 7301 | .45 | 8257 | .30 |
| 5594 | 7.00 | 6442 | .80 | 7322 | 1.45 | 8311 | .20 | |
| 5595 | 9.75 | 6443 | .20 | 7331 | .05 | 8317-DU | .30 | |
| 5635 | .35 | 6444 | .10 | 7408 | 2.10 | 8317-SU | .25 | |
| 5643 | 1.80 | 6451 | .30 | 7409 | .40 | 8317-ODG | .30 | |
| 5649 | .30 | 6452 | .20 | 7417 | .10 | 8317-OSG | .25 | |
| 5650 | .70 | 6453 | 1.50 | 7421 | 3.25 | 8318-DU | .40 | |
| 5662 | 3.25 | 6454 | 4.50 | 7422 | 6.50 | 8318-ODG | .40 | |
| 5667 | .50 | 6455 | 8.75 | 7423 | 3.10 | 8318-OSG | .35 | |
| 5676 | .05 | 6457 | 6.50 | 7440 | .80 | 8318-OSU | .35 | |
| 5716 | 15.00 | 6458 | 7.50 | 7441 | .90 | 8319-SU | .35 | |
| 5718 | .30 | 6497 | 3.50 | 7442-B | .25 | 8320-DG | .30 | |
| 5724 | 1.00 | 6498 | .45 | 7442-DG | .30 | 8320-DU | .30 | |
| 5725 | 1.95 | 6499 | 1.00 | 7442-SG | .25 | 8320-SG | .25 | |
| 5732 | 1.80 | 6508 | .05 | 7442-OSU | .25 | 8320-SU | .25 | |
| 5760 | per 100 | 6511 | .20 | 7465 | .15 | 8322-SU | .25 | |
| 5783 | .60 | 6554 | 5.25 | 7467 | 1.05 | 8323-B | .40 | |
| 5785 | 3.25 | 6557 | 6.00 | 7505 | .07 | 8324-DU | .30 | |
| 5786 | 9.25 | 6582 | 2.15 | 7525 | 1.80 | 8325-DU | .30 | |
| 5792 | .35 | 6584 | .30 | 7535 | 2.70 | 8325-SU | .25 | |
| 5796 | 1.50 | 6585 | .60 | 7552 | 2.70 | 8326-SG | .35 | |
| 5858 | .20 | 6600 | .60 | 7556 | .95 | 8326-OSU | .35 | |
| 5863 | .25 | 6602 | 1.50 | 7558 | 1.10 | 8327-DU | .40 | |
| 5877 | .35 | 6608 | .09 | 7625-D | .40 | 8328-SU | .35 | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 02625 | 1.90 | 03945 | 1.30 | 05189 | 1.00 | 06766 | .50 |
| 02634 | .30 | 04000-A | .30 | 05190 | .40 | 06798 | 1.40 |
| 02641 | 8.25 | 04000-B | .50 | 05191 | .20 | 06802 | .35 |
| 02651 | .25 | 04000-C | .30 | 05213 | 1.00 | 06817 | .35 |
| 02665 | 12.00 | 04000-D | .30 | 05239 | 1.20 | 06886 | .10 |
| 02674 | 12.00 | 04000-E | .30 | 05299 | 1.50 | 06887 | 1.00 |
| 02677 | 3.00 | 04000-F | .50 | 05324 | 1.20 | 06888 | 1.00 |
| 02720 | .35 | 04000-H | .40 | 05365 | .95 | 06914 | 1.00 |
| 02722 | .30 | 04000-J | .40 | 05366 | .75 | 06915 | .80 |
| 02728 | .40 | 04000-K | .25 | 05386 | 2.25 | 06916 | 1.20 |
| 02744 | 4.25 | 04000-L | .25 | 05390 | .10 | 06920 | .15 |
| 02745 | 4.25 | 04000-M | .40 | 05418 | .65 | 06923 | .20 |
| 02761 | 4.25 | 04000-P | .20 | 05419 | 4.20 | 06924 | .20 |
| 02763 | 7.25 | 04000-R | .80 | 05433 | .80 | 06931 | 3.60 |
| 02795 | 4.25 | 04000-S | .65 | 05437 | .80 | 06932 | 1.00 |
| 02803 | 4.25 | 04000-T | .65 | 05438 | .80 | 06941 | 6.50 |
| 02813 | 7.50 | 04000-V | .20 | 05439 | 1.10 | 06993 | 7.50 |
| 02819 | 7.25 | 04000-X | .40 | 05530 | .35 | | |
| 02824 | .10 | 04000-Y | .15 | 05552 | 1.00 | 27-2116 | .05 |
| 02836 | .20 | 04011 | .30 | 05569 | 1.20 | 27-4007 | .10 |
| 02861 | 1.10 | 04022 | .30 | 05612 | 2.40 | 27-4008 | .03 |
| 02887 | 1.00 | 04023 | .30 | 05616 | 1.50 | 27-4014 | .05 |
| 02942 | 2.25 | 04031 | .45 | 05622 | 1.20 | 27-4018 | .40 |
| 02984 | .90 | 04164 | 6.00 | 05624 | 4.00 | 27-4022 | .40 |
| 03001 | 7.50 | 04185 | .80 | 05646 | 1.50 | 27-4023 | 1.20 |
| 03009 | 1.30 | 04186 | 1.50 | 05667 | 1.50 | 27-4024 | .18 |
| 03011 | 1.00 | 04190 | 1.20 | 05688 | 1.10 | 27-4030 | .65 |
| 03013 | .90 | 04198 | .50 | 05691 | 1.80 | 27-4032 | .25 |
| 03014 | .80 | 04308 | 6.30 | 05697 | 1.20 | 27-4037 | .10 |
| 03015 | .80 | 04309 | 6.00 | 05698 | 1.20 | 27-4039 | .25 |
| 03016 | 1.00 | 04317 | 1.60 | 05707 | 6.00 | 27-4042 | .10 |
| 03024 | 1.00 | 04319 | 1.10 | 05723 | .18 | 27-4043 | .15 |
| 03029 | 1.20 | 04320 | 1.10 | 05724 | 1.50 | 27-4045 | .10 |
| 03031 | 1.25 | 04339 | 1.20 | 05726 | 1.20 | 27-4051 | .10 |
| 03038 | 1.10 | 04342 | 1.20 | 05740 | 5.10 | 27-4052 | .10 |
| 03039 | 1.20 | 04343 | 6.50 | 05794 | 3.00 | 27-4056 | .25 |
| 03040 | 1.10 | 04344 | .15 | 05811 | .40 | 27-4058 | .10 |
| 03063 | .10 | 04348 | 1.10 | 05829 | 4.80 | 27-4071 | .25 |
| 03064 | .10 | 04352 | 1.60 | 05831 | 1.00 | 27-4072 | .25 |
| 03076 | 6.00 | 04353 | 1.60 | 05832 | 1.00 | 27-4075 | .25 |
| 03077 | 6.00 | 04354 | 1.30 | 05834 | 1.50 | 27-4076 | .25 |
| 03082 | .90 | 04356 | 1.60 | 05848 | .80 | 27-4079 | .30 |
| 03083 | .80 | 04357 | .75 | 05849 | .80 | 27-4080 | .30 |
| 03084 | .80 | 04358 | .10 | 05886 | 4.80 | 27-4083 | .18 |
| 03086 | .45 | 04360 | .60 | 05901 | 1.20 | 27-4084 | .18 |
| 03091 | 1.10 | 04390 | .45 | 05902 | 1.00 | 27-4086 | .12 |
| 03092 | 1.20 | 04407 | 1.20 | 05903 | 1.00 | 27-4088 | .12 |
| 03103 | .02 | 04408 | 1.20 | 05970 | 1.20 | 27-4089 | .25 |
| 03137 | .75 | 04409 | 1.20 | 05975 | 1.00 | 27-4091 | .10 |
| 03143 | 1.50 | 04416 | 2.70 | 05982 | 5.10 | 27-4092 | .50 |
| 03257 | .60 | 04508 | 1.50 | 05983 | 1.00 | 27-4098 | .10 |
| 03263 | 1.20 | 04509 | .80 | 05984 | .80 | 27-4100 | .25 |
| 03283 | 1.10 | 04559 | 1.20 | 05985 | .80 | 27-4109 | 1.50 |
| 03284 | 1.10 | 04731 | .50 | 05986 | 5.00 | 27-4112 | .01 |
| 03298 | 1.65 | 04733 | 5.10 | 05987 | 1.00 | 27-4113 | .20 |
| 03320 | 1.10 | 04757 | .50 | 05988 | .90 | 27-4115 | .20 |
| 03321 | .90 | 04787 | .75 | 05989 | .80 | 27-4116 | .08 |
| 03322 | .60 | 04790 | 5.10 | 05992 | .45 | 27-4117 | .40 |
| 03325 | 1.00 | 04830 | .90 | 06006 | 3.00 | 27-4119 | .04 |
| 03327 | 1.20 | 04832 | .45 | 06088 | 1.50 | 27-4120 | .15 |
| 03334 | .10 | 04834 | .15 | 06091 | .45 | 27-4121 | 2.25 |
| 03344 | .60 | 04835 | .35 | 06100 | 1.80 | 27-4122 | .10 |
| 03345 | 1.10 | 04836 | .40 | 06144 | 5.00 | 27-4124 | .10 |
| 03360 | .80 | 04941 | 6.60 | 06146 | .60 | 27-4127 | .10 |
| 03388 | 2.60 | 04959 | .90 | 06256 | 3.90 | 27-4128 | .08 |
| 03430 | .12 | 04979 | .70 | 06350 | 1.10 | 27-4129 | .08 |
| 03437 | .05 | 04981 | .70 | 06358 | .40 | 27-4139 | .10 |
| 03455 | 1.50 | 04982 | .50 | 06574 | 1.00 | 27-4140 | .10 |
| 03459 | 1.50 | 04983 | .60 | 06577 | 4.80 | 27-4146 | .10 |
| 03489 | 2.10 | 04997 | .60 | 06578 | .10 | 27-4150 | .01 |
| 03589 | 2.70 | 05003 | 4.20 | 06609 | 5.10 | 27-4153 | .35 |
| 03624 | 1.20 | 05016 | .25 | 06617 | 1.60 | 27-4155 | .30 |
| 03661 | .40 | 05093 | .60 | 06619 | .75 | 27-4159 | .30 |
| 03662 | .65 | 05094 | .80 | 06620 | 1.40 | 27-4163 | .30 |
| 03692 | 3.90 | 05095 | .80 | 06621 | 1.00 | 27-4167 | .70 |
| 03734 | 2.40 | 05098 | 5.10 | 06622 | 1.60 | 27-4169 | .10 |
| 03751 | 3.60 | 05109 | .50 | 06624 | .90 | 27-4174 | .50 |
| 03809 | 5.40 | 05117 | .25 | 06662 | .90 | 27-4176 | .15 |
| 03814 | .10 | 05118 | .25 | 06680 | .12 | 27-4179 | .15 |
| 03882 | 1.30 | 05150 | .70 | 06697 | .55 | 27-4187 | .10 |
| 03886 | 1.50 | 05153 | .50 | 06698 | .75 | 27-4188 | .05 |
| 03887 | 1.80 | 05154 | 4.80 | 06702 | 4.80 | 27-4193 | .40 |
| 03893 | .35 | 05174 | .50 | 06713 | .55 | 27-4197 | .08 |
| 03915 | 1.30 | 05183 | 1.80 | 06729 | .30 | 27-4198 | .03 |
| 03938 | .04 | 05185 | 1.00 | 06764 | .50 | 27-4199 | .06 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|--------------|----------|--------------|----------|------------|----------|--------------|
| 27-4200 | .10 | 27-4375 | .10 | 27-4792 | .70 | 27-4793 | 1.50 |
| 27-4201 | .04 | 27-4377 | .15 | 27-4617 | .40 | 27-4794 | .50 |
| 27-4202 | .08 | 27-4379 | .10 | 27-4618 | .25 | 27-4795 | .40 |
| 27-4203 | .40 | 27-4384 | .10 | 27-4619 | .20 | 27-4804 | .15 |
| 27-4206 | .10 | 27-4385 | .55 | 27-4622 | .05 | 27-4805 | .05 |
| 27-4207 | .10 | 27-4390 | .05 | 27-4627 | .10 | 27-4810 | .15 |
| 27-4208 | .10 | 27-4398 | .03 | 27-4632 | .15 | 27-4809 | .10 |
| 27-4212 | .15 | 27-4399 | .15 | 27-4637 | .20 | 27-4810 | .10 |
| 27-4219 | .10 | 27-4400 | .10 | 27-4638 | .35 | 27-4812 | .10 |
| 27-4220 | .02 | 27-4401 | .15 | 27-4639 | .30 | 27-4814 | .10 |
| 27-4225 | .10 | 27-4407 | .20 | 27-4640 | .15 | 27-4815 | .10 |
| 27-4227 | .20 | 27-4410 | .10 | 27-4652 | .15 | 27-4817 | per 100 2.50 |
| 27-4228 | .20 | 27-4411 | .10 | 27-4654 | .45 | 27-4818 | .06 |
| 27-4229 | .20 | 27-4412 | .10 | 27-4656 | .45 | 27-4820 | .10 |
| 27-4233 | .20 | 27-4413 | .10 | 27-4658 | .40 | 27-4821 | 1.00 |
| 27-4234 | .20 | 27-4414 | .10 | 27-4659 | .25 | 27-4822 | 1.50 |
| 27-4235 | .20 | 27-4415 | .10 | 27-4660 | .25 | 27-4824 | .10 |
| 27-4242 | .10 | 27-4425 | .20 | 27-4661 | .25 | 27-4826 | .10 |
| 27-4243 | .10 | 27-4426 | .10 | 27-4662 | .25 | 27-4827 | .10 |
| 27-4245 | .20 | 27-4427 | .10 | 27-4663 | .30 | 27-4828 | .10 |
| 27-4246 | .20 | 27-4428 | .15 | 27-4665 | .20 | 27-4829 | .15 |
| 27-4247 | .20 | 27-4430 | .10 | 27-4666 | .20 | 27-4831 | .10 |
| 27-4248 | .10 | 27-4431 | .10 | 27-4667 | .20 | 27-4832 | 1.25 |
| 27-4249 | .10 | 27-4432 | .35 | 27-4668 | .20 | 27-4833 | 1.35 |
| 27-4250 | .60 | 27-4436 | .15 | 27-4669 | .25 | 27-4835 | .15 |
| 27-4252 | .15 | 27-4437 | .10 | 27-4671 | .15 | 27-4836 | .10 |
| 27-4254 | .25 | 27-4439 | .20 | 27-4673 | .25 | 27-4842 | .75 |
| 27-4258 | .35 | 27-4442 | .50 | 27-4674 | .10 | 27-4843 | .20 |
| 27-4260 | .50 | 27-4444 | .40 | 27-4676 | .02 | 27-4844 | .10 |
| 27-4261 | .25 | 27-4456 | .15 | 27-4678 | .10 | 27-4846 | 2.00 |
| 27-4265 | per 100 1.25 | 27-4457 | .15 | 27-4679 | .03 | 27-4848 | .10 |
| 27-4269 | .15 | 27-4493 | .03 | 27-4682 | .55 | 27-4852 | .10 |
| 27-4270 | .05 | 27-4495 | .45 | 27-4683 | .03 | 27-4854 | .05 |
| 27-4275 | .20 | 27-4499 | .20 | 27-4685 | .15 | 27-4855 | .60 |
| 27-4276 | .20 | 27-4501 | .02 | 27-4687 | .35 | 27-4860 | .10 |
| 27-4278 | .20 | 27-4503 | .05 | 27-4688 | .35 | 27-4862 | .15 |
| 27-4279 | .20 | 27-4504 | .05 | 27-4689 | .15 | 27-4863 | .10 |
| 27-4282 | .10 | 27-4508 | .25 | 27-4690 | .35 | 27-4866 | .10 |
| 27-4284 | .10 | 27-4514 | .04 | 27-4691 | .15 | 27-4868 | .10 |
| 27-4285 | .15 | 27-4515 | .20 | 27-4692 | .35 | 27-4872 | .20 |
| 27-4287 | .05 | 27-4518 | .20 | 27-4693 | .30 | 27-4876 | .15 |
| 27-4288 | .15 | 27-4521 | .10 | 27-4694 | .40 | 27-4885 | .10 |
| 27-4291 | .10 | 27-4522 | .75 | 27-4695 | .35 | 27-4891 | .10 |
| 27-4297 | .03 | 27-4524 | .20 | 27-4696 | .08 | 27-4893 | .15 |
| 27-4299 | .20 | 27-4525 | .10 | 27-4697 | .10 | 27-4896 | .15 |
| 27-4300 | 1.10 | 27-4526 | .15 | 27-4701 | .10 | 27-4899 | .15 |
| 27-4302 | .10 | 27-4529 | .10 | 27-4702 | .10 | 27-4900 | 1.50 |
| 27-4307 | per 100 1.20 | 27-4531 | .20 | 27-4703 | .25 | 27-4903 | per 100 1.25 |
| 27-4308 | .10 | 27-4532 | .01 | 27-4705 | .15 | 27-4907 | 1.75 |
| 27-4309 | .15 | 27-4533 | .25 | 27-4710 | .50 | 27-4913 | 2.00 |
| 27-4313 | .25 | 27-4534 | .25 | 27-4713 | .10 | 27-4914 | .25 |
| 27-4314 | .04 | 27-4535 | .20 | 27-4715 | .10 | 27-4924 | .15 |
| 27-4317 | .05 | 27-4538 | .10 | 27-4725 | .10 | 27-4926 | .10 |
| 27-4318 | .12 | 27-4540 | .02 | 27-4727 | .05 | 27-4927 | .10 |
| 27-4321 | .10 | 27-4543 | .05 | 27-4728 | .02 | 27-4933 | .35 |
| 27-4325 | .02 | 27-4545 | .02 | 27-4731 | .10 | 27-4936 | .15 |
| 27-4326 | .10 | 27-4546 | .25 | 27-4732 | .10 | 27-4938 | .15 |
| 27-4330 | .10 | 27-4547 | .20 | 27-4733 | .10 | 27-4940 | .15 |
| 27-4331 | .10 | 27-4548 | .15 | 27-4737 | .15 | 27-4942 | .15 |
| 27-4332 | .10 | 27-4549 | .05 | 27-4739 | .10 | 27-4943 | 1.75 |
| 27-4333 | .10 | 27-4550 | per 100 1.25 | 27-4747 | .07 | 27-4950 | .15 |
| 27-4335 | .05 | 27-4552 | .05 | 27-4749 | .10 | 27-4952 | .10 |
| 27-4336 | .20 | 27-4561 | .25 | 27-4750 | .35 | 27-4953 | .30 |
| 27-4339 | .35 | 27-4564 | .10 | 27-4753 | .20 | 27-4954 | .30 |
| 27-4340 | .35 | 27-4570 | .03 | 27-4754 | .15 | 27-4955 | 1.75 |
| 27-4341 | .30 | 27-4571 | .04 | 27-4759 | .15 | 27-4962 | 2.25 |
| 27-4342 | .10 | 27-4572 | .10 | 27-4762 | .25 | 27-4963 | 1.25 |
| 27-4343 | .45 | 27-4574 | .05 | 27-4763 | .40 | 27-4965 | 1.00 |
| 27-4344 | .45 | 27-4577 | .60 | 27-4764 | .30 | 27-4969 | 1.25 |
| 27-4345 | .02 | 27-4580 | .20 | 27-4765 | .30 | 27-4970 | .10 |
| 27-4347 | .10 | 27-4581 | .05 | 27-4766 | .30 | 27-4971 | .15 |
| 27-4352 | .30 | 27-4582 | .20 | 27-4767 | .15 | 27-4972 | .15 |
| 27-4353 | .50 | 27-4583 | .10 | 27-4771 | .03 | 27-4976 | .50 |
| 27-4354 | .65 | 27-4585 | .04 | 27-4772 | .45 | 27-4983 | .75 |
| 27-4355 | .65 | 27-4596 | .03 | 27-4773 | .20 | 27-4985 | 1.75 |
| 27-4356 | .45 | 27-4597 | .40 | 27-4777 | .10 | 27-4987 | .15 |
| 27-4357 | .10 | 27-4598 | .03 | 27-4781 | .10 | 27-4997 | .25 |
| 27-4358 | .05 | 27-4599 | .04 | 27-4782 | .10 | 27-4999 | .25 |
| 27-4359 | .02 | 27-4604 | .10 | 27-4783 | .10 | 27-5001 | .15 |
| 27-4360 | .08 | 27-4608 | .03 | 27-4784 | .10 | 27-5006 | .30 |
| 27-4363 | .15 | 27-4610 | .02 | 27-4785 | .10 | 27-5008 | .50 |
| 27-4365 | .15 | 27-4611 | .25 | 27-4786 | .10 | 27-5010 | .15 |
| 27-4367 | .15 | 27-4612 | .15 | 27-4787 | .10 | 27-5017 | .01 |
| 27-4371 | .10 | 27-4613 | .15 | 27-4788 | .10 | 27-5019 | .20 |
| 27-4373 | .10 | 27-4615 | .10 | 27-4789 | .15 | 27-5020 | .65 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|--------------|----------|--------------|----------|--------------|----------|--------------|
| 27-5022 | .30 | 27-5240 | .30 | 27-5495 | per 100 .50 | 27-5629 | per 100 .75 |
| 27-5023 | .15 | 27-5243 | .15 | 27-5496 | per 100 .50 | 27-5630 | .40 |
| 27-5024 | .30 | 27-5244 | .70 | 27-5498 | .50 | 27-5631 | .05 |
| 27-5027 | .30 | 27-5245 | .50 | 27-5499 | .50 | 27-5633 | .05 |
| 27-5028 | 1.00 | 27-5247 | .30 | 27-5500 | .50 | 27-5635 | .60 |
| 27-5030 | .35 | 27-5248 | .50 | 27-5501 | .30 | 27-5636 | .35 |
| 27-5031 | .15 | 27-5249 | .60 | 27-5502 | .60 | 27-5637 | .50 |
| 27-5034 | .25 | 27-5250 | 1.00 | 27-5503 | .50 | 27-5638 | .05 |
| 27-5038 | .30 | 27-5252 | .10 | 27-5506 | .40 | 27-5639 | .40 |
| 27-5040 | .30 | 27-5261 | per 100 .70 | 27-5507 | .40 | 27-5642 | .60 |
| 27-5041 | .30 | 27-5264 | .35 | 27-5508 | 1.00 | 27-5643 | per 100 .75 |
| 27-5042 | .25 | 27-5266 | .50 | 27-5511 | .50 | 27-5645 | .50 |
| 27-5044 | .65 | 27-5269 | .50 | 27-5512 | .50 | 27-5647 | .01 |
| 27-5048 | .13 | 27-5271 | 1.00 | 27-5513 | 1.00 | 27-5648 | .01 |
| 27-5051 | .20 | 27-5272 | .60 | 27-5515 | .40 | 27-5650 | .40 |
| 27-5053 | .20 | 27-5273 | .20 | 27-5516 | .50 | 27-5651 | .50 |
| 27-5054 | .20 | 27-5276 | .20 | 27-5517 | .60 | 27-5652 | .50 |
| 27-5066 | .15 | 27-5278 | .25 | 27-5518 | .35 | 27-5653 | .50 |
| 27-5070 | .30 | 27-5280 | .15 | 27-5519 | .40 | 27-5654 | .50 |
| 27-5073 | .20 | 27-5283 | .90 | 27-5520 | .50 | 27-5655 | 1.00 |
| 27-5077 | .25 | 27-5285 | .50 | 27-5524 | per 100 .75 | 27-5657 | .50 |
| 27-5078 | .40 | 27-5287 | .40 | 27-5526 | per 100 .75 | 27-5658 | 1.00 |
| 27-5081 | .20 | 27-5292 | .50 | 27-5528 | per 100 .75 | 27-5660 | per 100 .75 |
| 27-5086 | .10 | 27-5361 | .40 | 27-5530 | per 100 1.00 | 27-5661 | per 100 .75 |
| 27-5095 | .15 | 27-5317 | per 100 .35 | 27-5535 | 1.00 | 27-5662 | per 100 .75 |
| 27-5096 | .10 | 27-5320 | .10 | 27-5536 | .50 | 27-5663 | .45 |
| 27-5097 | .25 | 27-5327 | .60 | 27-5537 | 1.00 | 27-5664 | .05 |
| 27-5098 | .25 | 27-5330 | .60 | 27-5538 | .50 | 27-5665 | per 100 1.00 |
| 27-5100 | .15 | 27-5333 | .60 | 27-5539 | .40 | 27-5666 | per 100 1.00 |
| 27-5102 | .15 | 27-5339 | .25 | 27-5540 | .30 | 27-5667 | .45 |
| 27-5103 | .30 | 27-5340 | 1.75 | 27-5541 | .20 | 27-5668 | .50 |
| 27-5104 | .15 | 27-5341 | .80 | 27-5542 | .50 | 27-5672 | .50 |
| 27-5105 | .10 | 27-5347 | .20 | 27-5543 | .30 | 27-5673 | 1.00 |
| 27-5107 | .40 | 27-5348 | .20 | 27-5545 | .60 | 27-5678 | .60 |
| 27-5108 | .10 | 27-5349 | .12 | 27-5549 | .10 | 27-5679 | .75 |
| 27-5112 | .15 | 27-5352 | .60 | 27-5551 | .40 | 27-5682 | .60 |
| 27-5115 | .40 | 27-5353 | .90 | 27-5552 | .40 | 27-5684 | .50 |
| 27-5120 | per 100 1.50 | 27-5356 | 1.25 | 27-5553 | .50 | 27-5686 | per 100 .75 |
| 27-5121 | .25 | 27-5357 | 1.25 | 27-5554 | .50 | 27-5687 | per 100 .75 |
| 27-5122 | .30 | 27-5358 | 1.25 | 27-5555 | .50 | 27-5690 | 1.00 |
| 27-5123 | .40 | 27-5361 | .40 | 27-5556 | .50 | 27-5691 | .60 |
| 27-5125 | .30 | 27-5364 | .60 | 27-5559 | .50 | 27-5693 | .50 |
| 27-5126 | .35 | 27-5370 | .25 | 27-5561 | .50 | 27-5694 | 1.00 |
| 27-5127 | .40 | 27-5375 | .65 | 27-5562 | .30 | 27-5695 | .75 |
| 27-5130 | .30 | 27-5376 | .35 | 27-5563 | 1.00 | 27-5696 | .75 |
| 27-5131 | .30 | 27-5377 | .50 | 27-5565 | .50 | 27-5699 | .50 |
| 27-5134 | .25 | 27-5379 | .35 | 27-5566 | .60 | 27-5700 | .60 |
| 27-5136 | .30 | 27-5397 | .30 | 27-5568 | .50 | 27-5713 | .50 |
| 27-5137 | .15 | 27-5399 | .15 | 27-5569 | 1.00 | 27-5717 | 1.00 |
| 27-5139 | .25 | 27-5400 | .20 | 27-5570 | .50 | 27-5729 | .50 |
| 27-5140 | .30 | 27-5403 | .40 | 27-5571 | .50 | 27-5732 | .50 |
| 27-5145 | .10 | 27-5404 | 1.00 | 27-5572 | .50 | 27-5733 | .50 |
| 27-5152 | .30 | 27-5406 | .40 | 27-5573 | .50 | 27-5736 | 1.00 |
| 27-5159 | .10 | 27-5408 | .25 | 27-5574 | .40 | 27-5737 | per 100 .75 |
| 27-5160 | .20 | 27-5409 | .25 | 27-5578 | .50 | 27-5738 | .01 |
| 27-5161 | .10 | 27-5412 | .40 | 27-5579 | .50 | 27-5744 | 1.25 |
| 27-5162 | .20 | 27-5413 | .40 | 27-5580 | .50 | 27-5745 | 1.00 |
| 27-5163 | .25 | 27-5416 | .40 | 27-5583 | 1.25 | 27-5751 | 1.25 |
| 27-5165 | .30 | 27-5417 | .40 | 27-5584 | .20 | 27-5753 | 1.00 |
| 27-5166 | .10 | 27-5420 | .40 | 27-5585 | .20 | 27-5757 | .75 |
| 27-5167 | .20 | 27-5421 | 1.00 | 27-5586 | 1.00 | 27-5759 | 1.00 |
| 27-5168 | .20 | 27-5422 | 1.00 | 27-5587 | .50 | 27-5762 | .75 |
| 27-5170 | .30 | 27-5426 | .40 | 27-5588 | 1.00 | 27-5778 | .75 |
| 27-5171 | .10 | 27-5427 | .40 | 27-5590 | .40 | 27-5781 | .05 |
| 27-5172 | .25 | 27-5428 | 1.25 | 27-5591 | .40 | 27-5783 | .05 |
| 27-5183 | .30 | 27-5431 | .10 | 27-5592 | .40 | 27-5797 | .50 |
| 27-5184 | .40 | 27-5433 | per 100 1.25 | 27-5593 | .30 | 27-5800 | .75 |
| 27-5186 | .01 | 27-5434 | .30 | 27-5604 | .40 | 27-5802 | .50 |
| 27-5188 | .20 | 27-5449 | .40 | 27-5606 | 1.00 | 27-6000 | .15 |
| 27-5193 | .15 | 27-5452 | 1.00 | 27-5607 | 1.00 | 27-6001 | .15 |
| 27-5194 | .10 | 27-5457 | .40 | 27-5608 | .05 | 27-6006 | .10 |
| 27-5196 | .45 | 27-5460 | per 100 .50 | 27-5609 | .60 | 27-6010 | .90 |
| 27-5197 | .20 | 27-5466 | .50 | 27-5610 | .10 | 27-6012 | .10 |
| 27-5198 | .30 | 27-5469 | 1.25 | 27-5612 | .50 | 27-6013 | .11 |
| 27-5203 | .50 | 27-5471 | 1.25 | 27-5613 | .25 | 27-6018 | .10 |
| 27-5204 | .35 | 27-5472 | .30 | 27-5614 | .50 | 27-6020 | .11 |
| 27-5205 | .50 | 27-5474 | .50 | 27-5616 | .20 | 27-6030 | .08 |
| 27-5206 | .30 | 27-5480 | .40 | 27-5617 | .50 | 27-6034 | .10 |
| 27-5207 | .80 | 27-5481 | .50 | 27-5618 | .50 | 27-6035 | .11 |
| 27-5208 | 1.00 | 27-5482 | per 100 .50 | 27-5619 | .35 | 27-6036 | .11 |
| 27-5209 | .70 | 27-5486 | per 100 .60 | 27-5621 | .60 | 27-6037 | .11 |
| 27-5210 | .15 | 27-5487 | per 100 .50 | 27-5623 | per 100 .75 | 27-6039 | 1.70 |
| 27-5211 | .15 | 27-5491 | per 100 .75 | 27-5625 | per 100 .75 | 27-6042 | .10 |
| 27-5213 | .70 | 27-5492 | per 100 .60 | 27-5627 | .01 | 27-6043 | .08 |
| 27-5214 | .50 | 27-5494 | per 100 .60 | 27-5628 | .01 | 27-6044 | .10 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | |
|----------|------------|----------|------------|----------|------------|----------|------------|------|
| 27-6047 | .10 | 27-7133 | .02 | 27-8496 | .02 | 27-9387 | .60 | |
| 27-6049 | .10 | 27-7152 | .35 | 27-8498 | .15 | 27-9388 | .60 | |
| 27-6052 | .11 | 27-7164 | .07 | 27-8517 | .05 | 27-9391 | .01 | |
| 27-6053 | .11 | 27-7182 | .30 | 27-8530 | .01 | 27-9397 | .05 | |
| 27-6054 | .15 | 27-7194 | .01 | 27-8580 | .03 | 27-9413 | 1.00 | |
| 27-6057 | .11 | 27-7204 | 1.50 | 27-8593 | .10 | 27-9415 | .25 | |
| 27-6058 | .11 | 27-7205 | .02 | 27-8656 | .08 | 27-9418 | 1.00 | |
| 27-6061 | .11 | 27-7242 | .75 | 27-8657 | .02 | 27-9424 | .03 | |
| 27-6062 | .11 | 27-7325 | .10 | 27-8668 | .02 | 27-9431 | .85 | |
| 27-6066 | .15 | 27-7331 | .02 | 27-8677 | .02 | 27-9432 | .01 | |
| 27-6067 | .15 | 27-7442 | .50 | 27-8681 | .03 | 27-9437 | .03 | |
| 27-6073 | 2.50 | 27-7453 | .04 | 27-8697 | .01 | 27-9446 | 1.50 | |
| 27-6080 | .10 | 27-7467 | .50 | 27-8716 | .03 | 27-9447 | 1.00 | |
| 27-6086 | .11 | 27-7474 | .18 | 27-8770 | .05 | 27-9448 | .75 | |
| 27-6087 | .11 | 27-7517 | .60 | 27-8800 | .03 | 27-9449 | 1.00 | |
| 27-6089 | .12 | 27-7567 | 1.25 | 27-8806 | .90 | 27-9450 | .75 | |
| 27-6090 | .10 | 27-7602 | .06 | 27-8808 | .20 | 27-9451 | .75 | |
| 27-6094 | .45 | 27-7613 | .01 | 27-8822 | .05 | 27-9455 | .01 | |
| 27-6095 | .45 | 27-7637 | 1.30 | 27-8828 | .08 | 27-9465 | 1.50 | |
| 27-6096 | .45 | 27-7671 | .06 | 27-8838 | .06 | 27-9471 | .01 | |
| 27-6099 | .15 | 27-7729 | 1.10 | 27-8857 | .02 | 27-9472 | .03 | |
| 27-6103 | .15 | 27-7741 | .50 | 27-8882 | 1.50 | 27-9500 | 1.15 | |
| 27-6105 | .25 | 27-7753 | .50 | 27-8883 | .01 | 27-9511 | .10 | |
| 27-6107 | .11 | 27-7755 | .07 | 27-8893 | .10 | 27-9512 | .10 | |
| 27-6108 | .15 | 27-7757 | .10 | 27-8904 | 1.00 | 27-9515 | 1.00 | |
| 27-6110 | .15 | 27-7807 | .50 | 27-8905 | .07 | 27-9521 | .02 | |
| 27-6111 | .15 | 27-7810 | .03 | 27-8906 | .10 | 27-9545 | .10 | |
| 27-6112 | .15 | 27-7830 | .02 | 27-8909 | .75 | 27-9549 | .45 | |
| 27-6113 | .20 | 27-7831 | .40 | 27-8910 | .25 | 27-9559 | .10 | |
| 27-6114 | .20 | 27-7835 | .40 | 27-8944 | .30 | 27-9563 | .50 | |
| 27-6115 | .07 | 27-7836 | .06 | 27-8945 | .04 | 27-9564 | .30 | |
| 27-6119 | .10 | 27-7887 | .60 | 27-8950 | .10 | 27-9569 | 1.00 | |
| 27-6120 | .15 | 27-7903 | .05 | 27-8977 | .01 | 27-9578 | 1.50 | |
| 27-6121 | .15 | 27-7933 | .01 | 27-8981 | .02 | 27-9597 | 1.00 | |
| 27-6123 | .15 | 27-7948 | .02 | 27-8986 | .10 | 27-9612 | .10 | |
| 27-6124 | .15 | 27-7980 | .01 | 27-8987 | .02 | 27-9614 | .55 | |
| 27-6126 | .10 | 27-8008 | .55 | 27-8988 | .02 | 27-9615 | .15 | |
| 27-6127 | .15 | 27-8009 | .55 | 27-9018 | .10 | 27-9616 | .10 | |
| 27-6128 | .15 | 27-8036 | .01 | 27-9024 | .40 | 27-9617 | .10 | |
| 27-6129 | .20 | 27-8071 | .25 | 27-9025 | .02 | 27-9618 | .10 | |
| 27-6130 | .15 | 27-8101 | .05 | 27-9049 | .80 | 27-9621 | .35 | |
| 27-6131 | .15 | 27-8112 | .05 | 27-9057 | .02 | 27-9655 | .45 | |
| 27-6133 | .15 | 27-8113 | .07 | 27-9077 | .01 | 27-9659 | .10 | |
| 27-6135 | .15 | 27-8114 | .06 | 27-9091 | .15 | 27-9661 | .30 | |
| 27-6137 | .15 | 27-8117 | .04 | 27-9099 | .12 | 27-9664 | .10 | |
| 27-6138 | .15 | 27-8122 | .05 | 27-9107 | .10 | 27-9689 | .02 | |
| 27-6139 | .10 | 27-8140 | .01 | 27-9174 | .05 | 27-9690 | .20 | |
| 27-6141 | .15 | 27-8199 | .05 | 27-9175 | .10 | 27-9705 | .02 | |
| 27-6143 | .15 | 27-8203 | .02 | 27-9184 | .75 | 27-9770 | .85 | |
| 27-6145 | .10 | 27-8205 | .50 | 27-9185 | .15 | 27-9776 | .20 | |
| 27-6146 | .30 | 27-8207 | .50 | 27-9206 | .02 | 27-9782 | .10 | |
| 27-6147 | .30 | 27-8225 | .03 | 27-9213 | .10 | 27-9784 | .20 | |
| 27-6148 | .30 | 27-8228 | .01 | 27-9217 | .10 | 27-9785 | .20 | |
| 27-6150 | .10 | 27-8236 | .01 | 27-9218 | .05 | 27-9786 | .15 | |
| 27-6151 | .15 | 27-8255 | .25 | 27-9222 | .03 | 27-9787 | .20 | |
| 27-6153 | .10 | 27-8257 | .04 | 27-9224 | .01 | 27-9788 | .25 | |
| 27-6154 | .10 | 27-8258 | .60 | 27-9225 | .01 | 27-9789 | .25 | |
| 27-6156 | .15 | 27-8298 | .05 | 27-9245 | .03 | 27-9800 | .20 | |
| 27-6157 | .15 | 27-8299 | .06 | 27-9254 | .04 | 27-9817 | .20 | |
| 27-6158 | .15 | 27-8300 | .06 | 27-9258 | .50 | 27-9819 | .20 | |
| 27-6159 | .15 | 27-8301 | .02 | 27-9263 | .01 | 27-9828 | .30 | |
| 27-6160 | .15 | 27-8310 | .02 | 27-9275 | .05 | 27-9838 | .02 | |
| 27-6161 | .15 | 27-8311 | .01 | 27-9299 | .10 | 27-9861 | .02 | |
| 27-6162 | .15 | 27-8312 | .01 | 27-9314 | .15 | 27-9867 | .25 | |
| 27-6163 | .15 | 27-8313 | .01 | 27-9315 | .02 | 27-9870 | .15 | |
| 27-6164 | .15 | 27-8318 | .50 | 27-9320 | .15 | 27-9875 | .03 | |
| 27-6166 | .10 | 27-8324 | .02 | 27-9321 | .60 | 27-9879 | .20 | |
| 27-6167 | .15 | 27-8329 | .40 | 27-9324 | .10 | 27-9898 | .20 | |
| 27-6168 | .15 | 27-8349 | .05 | 27-9327 | .10 | 27-9907 | .15 | |
| 27-6173 | .15 | 27-8351 | .01 | 27-9328 | .15 | 28-1019 | .03 | |
| 27-6174 | .15 | 27-8351 | .01 | 27-9329 | .02 | 28-1021 | .04 | |
| 27-6177 | .15 | 27-8361 | .02 | 27-9330 | .02 | 28-1022 | .40 | |
| 27-6180 | .10 | 27-8366 | .01 | 27-9333 | .07 | 28-1039 | .08 | |
| 27-6181 | .15 | 27-8368 | .01 | 27-9334 | .25 | 28-1107 | .10 | |
| 27-6182 | .15 | 27-8389 | .20 | 27-9337 | .03 | 28-1110 | .04 | |
| 27-7019 | .02 | 27-8397 | .01 | 27-9343 | .02 | 28-1128 | .85 | |
| 27-7020 | .04 | 27-8398 | .30 | 27-9349 | 1.00 | 28-1195 | .06 | |
| 27-7021 | .02 | 27-8399 | .08 | 27-9353 | .15 | 28-1230 | .04 | |
| 27-7023 | .01 | 27-8410 | .50 | 27-9356 | .20 | 28-1246 | .15 | |
| 27-7036 | .25 | 27-8428 | .50 | 27-9358 | .40 | 28-1263 | .10 | |
| 27-7072 | .02 | 27-8429 | 2.50 | 27-9363 | .10 | 28-1269 | .03 | |
| 27-7073 | .02 | 27-8460 | .20 | 27-9368 | .10 | 28-1270 | .02 | |
| 27-7122 | per 100 | 7.50 | 27-8480 | .10 | 27-9377 | .05 | 28-1272 | 1.50 |
| 27-7131 | .05 | 27-8492 | .10 | 27-9378 | .15 | 28-1331 | .10 | |
| 27-7132 | per 100 | .40 | 27-8495 | .02 | 27-9382 | 1.50 | | |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | | |
|----------|------------|-------------|------------|--------------|-------------|----------|------------|---------|------|
| 28-1354 | per 100 | 1.00 | 28-2837 | .10 | 28-3898 | .03 | 28-4757 | per 100 | .55 |
| 28-1361 | .10 | 28-2897 | .03 | 28-3899 | .75 | 28-4807 | per 100 | .50 | |
| 28-1403 | per 100 | 1.25 | 28-2937 | .04 | 28-3900 | .03 | 28-4815 | .01 | |
| 28-1451 | .15 | 28-2944 | .03 | 28-3904 | .01 | 28-4817 | .25 | | |
| 28-1456 | per 100 | .75 | 28-2947 | .10 | 28-3917 | per 100 | .40 | | |
| 28-1493 | .05 | 28-2992 | .05 | 28-3927FA-3 | .01 | 28-4819 | .35 | | |
| 28-1541 | .30 | 28-2993 | .15 | 28-3976 | per 100 | .75 | 28-4824 | per 100 | 1.25 |
| 28-1584 | .20 | 28-3004 | .30 | 28-3982FA-3 | .01 | 28-4836 | .10 | | |
| 28-1629 | per 100 | .80 | 28-3012 | .15 | 28-3988 | .45 | 28-4840 | 1.50 | |
| 28-1644 | per 100 | 1.00 | 28-3014 | .05 | 28-4030 | per 100 | .75 | 28-4849 | .05 |
| 28-1648 | .25 | 28-3016 | .35 | 28-4031 | .45 | 28-4869 | 1.00 | | |
| 28-1653 | per 100 | 1.50 | 28-3061 | .07 | 28-4067 | .20 | 28-4871 | .05 | |
| 28-1657 | .05 | 28-3102 | .10 | 28-4077 | .25 | 28-4872 | .02 | | |
| 28-1660 | .10 | 28-3129 | .04 | 28-4117 | per 100 | .40 | 28-4874 | .30 | |
| 28-1686 | .15 | 28-3130 | .10 | 28-4118 | .25 | 28-4893 | .75 | | |
| 28-1738 | .01 | 28-3131 | per 100 | .60 | 28-4119 | .05 | 28-4917 | 1.75 | |
| 28-1767 | .80 | 28-3155 | .01 | 28-4122 | .02 | 28-4920 | .05 | | |
| 28-1790 | .35 | 28-3163 | .50 | 28-4127 | .85 | 28-4926 | .02 | | |
| 28-1791 | .30 | 28-3164 | .50 | 28-4136 | per 100 | .40 | 28-4929 | .03 | |
| 28-1792 | .25 | 28-3165 | .50 | 28-4143 | .70 | 28-4930 | .15 | | |
| 28-1808 | .07 | 28-3245 | .05 | 28-4147 | .01 | 28-4944 | .10 | | |
| 28-1815 | .15 | 28-3266 | .10 | 28-4151 | .02 | 28-4984 | .20 | | |
| 28-1820 | .10 | 28-3278 | .15 | 28-4156 | 2.00 | 28-5002 | .02 | | |
| 28-1843 | .25 | 28-3282 | .65 | 28-4160 | .01 | 28-5003 | .03 | | |
| 28-1849 | .10 | 28-3301 | .02 | 28-4166 | .15 | 28-5030 | .03 | | |
| 28-1891 | .70 | 28-3320 | per 100 | 1.00 | 28-4184 | .02 | 28-5031 | .12 | |
| 28-1942 | .05 | 28-3323 | .05 | 28-4186 | per 100 | .75 | 28-5039 | .05 | |
| 28-1956 | .10 | 28-3326 | per 100 | .75 | 28-4187 | .01 | 28-5055 | .05 | |
| 28-1957 | .10 | 28-3338 | .03 | 28-4243 | .10 | 28-5059 | .05 | | |
| 28-1974 | .05 | 28-3339 | .06 | 28-4246 | .03 | 28-5070 | .07 | | |
| 28-1989 | .10 | 28-3400 | .02 | 28-4251 | .80 | 28-5071 | .08 | | |
| 28-1991 | .10 | 28-3412 | .45 | 28-4279 | per 100 | .75 | 28-5072 | .04 | |
| 28-2033 | .02 | 28-3429 | .20 | 28-4299 | .03 | 28-5078 | .55 | | |
| 28-2042 | .06 | 28-3430 | .25 | 28-4316 | 1.20 | 28-5079 | .60 | | |
| 28-2043 | per 100 | .25 | 28-3431 | .25 | 28-4324 | .02 | 28-5080 | .70 | |
| 28-2049 | per 100 | 2.50 | 28-3432 | .25 | 28-4342 | .02 | 28-5089 | .03 | |
| 28-2051 | .03 | 28-3433 | .25 | 28-4351 | .01 | 28-5107 | .10 | | |
| 28-2089 | per 100 | .50 | 28-3434 | .30 | 28-4355 | .08 | 28-5109 | .10 | |
| 28-2094 | .10 | 28-3439 | per 100 | 2.50 | 28-4366 | .10 | 28-5114 | per 100 | 1.75 |
| 28-2114 | .04 | 28-3444 | .30 | 28-4380 | .04 | 28-5118 | .10 | | |
| 28-2170 | .60 | 28-3461 | .06 | 28-4394 | .01 | 28-5119 | .10 | | |
| 28-2195 | .02 | 28-3462 | .08 | 28-4411 | .12 | 28-5128 | .90 | | |
| 28-2198 | per 100 | 1.00 | 28-3463 | .05 | 28-4417 | .05 | 28-5139 | 1.00 | |
| 28-2214 | per 100 | .40 | 28-3509 | 1.00 | 28-4426 | .25 | 28-5149 | .10 | |
| 28-2221 | 1.25 | 28-3538 | .12 | 28-4445 | 1.15 | 28-5150 | .05 | | |
| 28-2222 | .05 | 28-3545 | .01 | 28-4468 | .05 | 28-5153 | .02 | | |
| 28-2223 | .05 | 28-3553 | .60 | 28-4474 | .05 | 28-5162 | .05 | | |
| 28-2246 | .10 | 28-3557 | .07 | 28-4483 | .05 | 28-5185 | .15 | | |
| 28-2250 | .10 | 28-3584 | .35 | 28-4485 | .10 | 28-5189 | per 100 | 1.50 | |
| 28-2257 | .01 | 28-3587 | .07 | 28-4492FC-1 | .30 | 28-5201 | .20 | | |
| 28-2258 | .01 | 28-3597 | .95 | 28-4500 | per 100 | .50 | 28-5202 | .10 | |
| 28-2281 | .10 | 28-3626 | .65 | 28-4507 | .25 | 28-5225 | .10 | | |
| 28-2312 | .40 | 28-3638 | .15 | 28-4508FA-7 | .50 | 28-5229 | .30 | | |
| 28-2317 | .02 | 28-3655 | .05 | 28-4509FA-19 | .15 | 28-5240 | .02 | | |
| 28-2318 | .01 | 28-3656 | .02 | 28-4513 | .10 | 28-5242 | .05 | | |
| 28-2345 | per 100 | 1.25 | 28-3661 | .15 | 28-4516 | per 100 | 2.50 | 28-5248 | .20 |
| 28-2482 | .10 | 28-3675 | .15 | 28-4539FA-19 | .15 | 28-5254 | per 100 | .50 | |
| 28-2488 | per 100 | .90 | 28-3688 | .45 | 28-4548FA-3 | .10 | 28-5256 | per 100 | 1.50 |
| 28-2496 | 1.00 | 28-3689 | .45 | 28-4552 | .02 | 28-5265 | .10 | | |
| 28-2503 | .10 | 28-3690 | .35 | 28-4559 | .25 | 28-5274 | .02 | | |
| 28-2605 | .10 | 28-3692 | .45 | 28-4561 | .10 | 28-5277 | .03 | | |
| 28-2606 | per 100 | .50 | 28-3698 | .04 | 28-4563 | .05 | 28-5319 | .10 | |
| 28-2624 | 1.80 | 28-3703 | .20 | 28-4577 | .15 | 28-5323 | .60 | | |
| 28-2647 | .50 | 28-3711 | .10 | 28-4606 | .03 | 28-5371 | .60 | | |
| 28-2650 | per 100 | .45 | 28-3717 | .25 | 28-4608 | .75 | 28-5372 | .07 | |
| 28-2655 | .05 | 28-3734 | .20 | 28-4609 | .35 | 28-5376 | .02 | | |
| 28-2669 | per 100 | .75 | 28-3753 | .01 | 28-4610 | .15 | 28-5388 | .05 | |
| 28-2670 | per 100 | .75 | 28-3757 | .60 | 28-4630 | .25 | 28-5390 | .15 | |
| 28-2699 | .05 | 28-3759 | .50 | 28-4650 | .20 | 28-5403 | .15 | | |
| 28-2711 | .10 | 28-3762FC-5 | .75 | 28-4664 | .70 | 28-5404 | 1.25 | | |
| 28-2725 | .03 | 28-3784FC-8 | .90 | 28-4666 | .03 | 28-5414 | .20 | | |
| 28-2726 | .10 | 28-3786 | .30 | 28-4667 | .06 | 28-5425 | .35 | | |
| 28-2727 | .02 | 28-3788 | .10 | 28-4675 | .75 | 28-5435 | per 100 | .75 | |
| 28-2751 | .50 | 28-3789 | .15 | 28-4677 | .02 | 28-5468 | .25 | | |
| 28-2756 | .10 | 28-3806 | .01 | 28-4678 | .10 | 28-5471 | .10 | | |
| 28-2757 | .10 | 28-3808 | .02 | 28-4680 | .06 | 28-5474 | .15 | | |
| 28-2773 | .05 | 28-3809 | .15 | 28-4684 | .03 | 28-5475 | .15 | | |
| 28-2781 | per 100 | .35 | 28-3831 | .35 | 28-4685 | .01 | 28-5477 | per 100 | 1.50 |
| 28-2782 | .10 | 28-3832 | .06 | 28-4687 | .03 | 28-5478 | per 100 | 1.00 | |
| 28-2796 | per 100 | .35 | 28-3842 | .01 | 28-4696 | .10 | 28-5482 | .95 | |
| 28-2813 | 2.00 | 28-3843 | .05 | 28-4711 | per 100 | 2.00 | 28-5483 | .90 | |
| 28-2815 | .01 | 28-3844 | .10 | 28-4724 | .02 | 28-5505 | .03 | | |
| 28-2820 | .40 | 28-3887 | 1.60 | 28-4752 | .02 | 28-5514 | per 100 | .90 | |
| 28-2826 | .10 | 28-3888 | .01 | 28-4755 | .01 | 28-5515 | .10 | | |
| | | | | | | 28-5529 | .50 | | |
| | | | | | | 28-5530 | .15 | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|-------------|--------------|-------------|--------------|-------------|--------------|--------------|--------------|
| 28-5531 | .80 | 28-6231 | per 100 2.50 | 28-6768 | .20 | 28-7262 | 1.25 |
| 28-5537 | per 100 1.25 | 28-6258 | .02 | 28-6772 | .05 | 28-7264FA-8 | .20 |
| 28-5546 | .75 | 28-6278 | .15 | 28-6773 | .15 | 28-7266 | .12 |
| 28-5549 | .08 | 28-6291 | per 100 2.60 | 28-6774 | .06 | 28-7270 | 1.50 |
| 28-5560 | .10 | 28-6292 | .03 | 28-6778 | .15 | 28-7273 | .50 |
| 28-5564 | .15 | 28-6298 | .04 | 28-6788FA-3 | .10 | 28-7275 | .75 |
| 28-5583 | .02 | 28-6307 | .05 | 28-6788FA-8 | .20 | 28-7284FA-8 | .30 |
| 28-5588 | per 100 .60 | 28-6308 | .10 | 28-6795 | .20 | 28-7286 | .10 |
| 28-5599 | 1.15 | 28-6345 | .03 | 28-6798 | .10 | 28-7288 | .25 |
| 28-5602 | .10 | 28-6365 | .02 | 28-6802FA-8 | .20 | 28-7288 FA8 | .30 |
| 28-5608 | .02 | 28-6367 | .01 | 28-6812 | .20 | 28-7289 | .30 |
| 28-5609 | .02 | 28-6374 | .04 | 28-6813 | .02 | 28-7291 | 1.25 |
| 28-5610 | .05 | 28-6378 | .05 | 28-6816 | .10 | 28-7294 | .15 |
| 28-5615 | .10 | 28-6383 | .10 | 28-6823 | .10 | 28-7309 | .10 |
| 28-5620 | .10 | 28-6396 | .05 | 28-6824FA-7 | .25 | 28-7316 FC56 | 2.75 |
| 28-5621 | .10 | 28-6397 | .15 | 28-6825 | .25 | 28-7326 | .30 |
| 28-5636FA-3 | .04 | 28-6410 | .03 | 28-6833 | .10 | 28-8003 | .65 |
| 28-5650 | .10 | 28-6414 | .05 | 28-6834 | .25 | 28-8006 | 1.35 |
| 28-5661 | .75 | 28-6416 | .02 | 28-6838 | .10 | 28-8007 | 1.35 |
| 28-5663 | per 100 .90 | 28-6421 | .02 | 28-6839 | .01 | 28-8008 | .13 |
| 28-5665 | .02 | 28-6423 | .05 | 28-6848 | .10 | 28-8009 | per 100 .50 |
| 28-5686 | per 100 .80 | 28-6426 | .15 | 28-6849 | .07 | 28-8010 | .65 |
| 28-5704FA-3 | .04 | 28-6427 | .15 | 28-6854 | .25 | 28-8011 | .65 |
| 28-5705 | .25 | 28-6428 | .10 | 28-6882 | .01 | 28-8012 | .80 |
| 28-5728 | .05 | 28-6432 | .20 | 28-6886 | per 100 1.25 | 28-8013 | .80 |
| 28-5739FA-3 | .02 | 28-6435 | .15 | 28-6887 | .15 | 28-8014 | .40 |
| 28-5742 | .30 | 28-6437 | per 100 .60 | 28-6908 | .05 | 28-8020 | 2.25 |
| 28-5744FA-3 | .20 | 28-6470 | .10 | 28-6914 | .02 | 28-8021 | 2.25 |
| 28-5746 | .10 | 28-6477 | .04 | 28-6916 | .15 | 28-8022 | 1.00 |
| 28-5753FA-3 | .01 | 28-6481 | 1.00 | 28-6924 | .05 | 28-8023 | 1.00 |
| 28-5754 | .02 | 28-6493 | .02 | 28-6928 | .25 | 28-8024 | 4.40 |
| 28-5756 | .10 | 28-6496 | .30 | 28-6929 | .05 | 28-8025 | 4.40 |
| 28-5758 | .10 | 28-6503 | .05 | 28-6935 | .35 | 28-8026 | per 100 1.45 |
| 28-5764 | .20 | 28-6504 | .10 | 28-6936 | .01 | 28-8036 | .35 |
| 28-5781 | .20 | 28-6506 | .40 | 28-6939 | .15 | 28-8037 | .35 |
| 28-5790 | .03 | 28-6507 | .03 | 28-6941 | per 100 1.50 | 28-8038 | .40 |
| 28-5810 | .01 | 28-6509 | .03 | 28-6946 | .02 | 28-8039 | .40 |
| 28-5812 | .02 | 28-6519 | .15 | 28-6993 | .20 | 28-8046 | 1.90 |
| 28-5814 | .02 | 28-6527 | .02 | 28-6994 | per 100 1.50 | 28-8054 | .30 |
| 28-5848 | .01 | 28-6528 | .20 | 28-7009 | .06 | 28-8055 | .30 |
| 28-5852 | .10 | 28-6534 | .15 | 28-7010 | .10 | 28-8061 | .05 |
| 28-5853 | .15 | 28-6540 | .10 | 28-7015 | 1.20 | 28-8062 | 1.10 |
| 28-5859 | .05 | 28-6542 | .10 | 28-7017 | .06 | 28-8063 | 1.10 |
| 28-5860 | .05 | 28-6545 | .15 | 28-7021 | .75 | 28-8064 | 3.00 |
| 28-5888 | .10 | 28-6552 | .80 | 28-7064 | .35 | 28-8065 | 3.00 |
| 28-5897 | .01 | 28-6554 | .02 | 28-7108 | .75 | 28-8068 | 1.20 |
| 28-5899 | 2.00 | 28-6555 | .03 | 28-7111 | .07 | 28-8069 | 1.20 |
| 28-5927 | .01 | 28-6558FA-3 | .15 | 28-7128 | .06 | 28-8071 | .07 |
| 28-5929 | .75 | 28-6558FA-8 | .25 | 28-7129 | .10 | 28-8073 | .75 |
| 28-5934 | .10 | 28-6565 | .65 | 28-7134 | .10 | 28-8075 | .75 |
| 28-5941 | .10 | 28-6575FA-8 | .06 | 28-7146 | .30 | 28-8077 | .65 |
| 28-5946 | .75 | 28-6581 | .20 | 28-7152FA-3 | .10 | 28-8079 | .65 |
| 28-5969 | .10 | 28-6582 | .20 | 28-7158 | .10 | 28-8081 | .45 |
| 28-5970 | .10 | 28-6586 | .10 | 28-7159 | .25 | 28-8083 | .80 |
| 28-5972 | .05 | 28-6592 | .05 | 28-7160 | 1.10 | 28-8085 | 1.90 |
| 28-5974 | .01 | 28-6594 | .40 | 28-7165 | 1.10 | 28-8089 | 1.00 |
| 28-5986 | .05 | 28-6595 | .40 | 28-7172 | .10 | 28-8090 | .80 |
| 28-5990 | .80 | 28-6597 | .08 | 28-7173 | .10 | 28-8091 | .65 |
| 28-5991 | .03 | 28-6607 | .15 | 28-7176 | .10 | 28-8092 | 1.00 |
| 28-5998 | .15 | 28-6610 | .15 | 28-7178 | .10 | 28-8093 | .80 |
| 28-6019 | .15 | 28-6611 | .10 | 28-7180 | .10 | 28-8098 | 3.00 |
| 28-6031 | per 100 1.50 | 28-6618FA-8 | .25 | 28-7185 | .10 | 28-8099 | 1.20 |
| 28-6032 | .03 | 28-6624 | .03 | 28-7187FA-3 | .12 | 28-8100 | .90 |
| 28-6036 | per 100 3.60 | 28-6633 | .15 | 28-7191 | .05 | 28-8101 | 3.00 |
| 28-6053 | per 100 .70 | 28-6635 | .06 | 28-7195 | .20 | 28-8102 | 1.20 |
| 28-6060 | .03 | 28-6638 | per 100 2.50 | 28-7196 | 1.00 | 28-8103 | .90 |
| 28-6075 | .03 | 28-6641 | .05 | 28-7198 | .15 | 28-8106 | 1.10 |
| 28-6085 | .15 | 28-6646 | .12 | 28-7203 | .15 | 28-8107 | 1.10 |
| 28-6088 | .03 | 28-6649 | .10 | 28-7207 | .05 | 28-8113 | 1.10 |
| 28-6094 | .01 | 28-6661 | .03 | 28-7209 | .50 | 28-8114 | 1.10 |
| 28-6102 | .04 | 28-6662 | .20 | 28-7210 | .30 | 28-8117 | 1.10 |
| 28-6145 | per 100 1.50 | 28-6666 | .10 | 28-7211 | .25 | 28-8119 | 1.10 |
| 28-6158 | .05 | 28-6672 | .25 | 28-7212 | .25 | 28-8127 | 1.20 |
| 28-6161 | .05 | 28-6673 | .02 | 28-7214 | .20 | 28-8128 | 1.20 |
| 28-6163 | .07 | 28-6674 | .04 | 28-7215 | .20 | 28-8129 | 1.20 |
| 28-6165 | per 100 1.50 | 28-6675 | .10 | 28-7230 | .20 | 28-8130 | 1.20 |
| 28-6168 | .05 | 28-6684 | .10 | 28-7231 | .65 | 28-8131 | .65 |
| 28-6176 | .50 | 28-6688 | .05 | 28-7242 | .60 | 28-8132 | .65 |
| 28-6177 | .06 | 28-6705 | .15 | 28-7249 | .20 | 28-8133 | .80 |
| 28-6179 | per 100 1.50 | 28-6709 | .10 | 28-7250 | .10 | 28-8135 | 3.00 |
| 28-6187 | per 100 .20 | 28-6727 | .04 | 28-7255 | .35 | 28-8136 | 3.00 |
| 28-6203 | .20 | 28-6735 | .10 | 28-7256 | .30 | 28-8137 | 1.00 |
| 28-6205 | .20 | 28-6754 | .15 | 28-7260 | .12 | 28-8138 | 1.00 |
| 28-6216 | .01 | 28-6756 | .20 | 28-7261 | .12 | 28-8139 | 1.25 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|--------------|----------|--------------|----------|-------------|----------|--------------|
| 28-8141 | 1.25 | 28-8325 | 1.45 | 28-8620 | 1.15 | 28-8795 | 1.40 |
| 28-8146 | 1.00 | 28-8328 | per 100 3.50 | 28-8623 | per 100 .70 | 28-8798 | 1.00 |
| 28-8155 | .80 | 28-8329 | .05 | 28-8624 | per 100 .50 | 28-8802 | 3.00 |
| 28-8156 | .80 | 28-8331 | 1.15 | 28-8625 | 2.65 | 28-8805 | 1.00 |
| 28-8157 | .80 | 28-8332 | 1.00 | 28-8627 | 2.65 | 28-8806 | 1.00 |
| 28-8158 | .80 | 28-8338 | 1.00 | 28-8628 | 2.20 | 28-8813 | 1.00 |
| 28-8161 | .65 | 28-8339 | 1.00 | 28-8629 | .04 | 28-8814 | 1.00 |
| 28-8162 | .65 | 28-8341 | 1.00 | 28-8630 | .02 | 28-8815 | 1.00 |
| 28-8163 | .80 | 28-8348 | .02 | 28-8631 | .02 | 28-8816 | 1.00 |
| 28-8164 | .80 | 28-8349 | .10 | 28-8642 | 2.00 | 28-8817 | 1.00 |
| 28-8169 | 1.35 | 28-8350 | .10 | 28-8646 | .02 | 28-8820 | per 100 4.50 |
| 28-8177 | .95 | 28-8351 | .02 | 28-8647 | .02 | 28-8821 | .80 |
| 28-8180 | 3.00 | 28-8352 | .05 | 28-8649 | 3.50 | 28-8822 | .90 |
| 28-8181 | 1.25 | 28-8354 | 1.25 | 28-8650 | 3.50 | 28-8823 | .90 |
| 28-8182 | 1.25 | 28-8355 | 1.40 | 28-8652 | .01 | 28-8824 | .90 |
| 28-8185 | 1.40 | 28-8356 | 1.25 | 28-8653 | .03 | 28-8825 | .90 |
| 28-8188 | 1.00 | 28-8358 | 1.25 | 28-8656 | .70 | 28-8826 | .90 |
| 28-8189 | 4.00 | 28-8359 | 1.25 | 28-8657 | .80 | 28-8832 | .02 |
| 28-8194 | .03 | 28-8360 | 1.25 | 28-8658 | .03 | 28-8837 | .30 |
| 28-8196 | .80 | 28-8366 | .02 | 28-8660 | .65 | 28-8839 | .05 |
| 28-8197 | .80 | 28-8369 | .90 | 28-8662 | .90 | 28-8840 | .02 |
| 28-8198 | 1.00 | 28-8370 | .90 | 28-8665 | .02 | 28-8841 | .01 |
| 28-8199 | 1.50 | 28-8371 | 1.45 | 28-8666 | .80 | 28-8842 | .90 |
| 28-8200 | 1.50 | 28-8374 | 1.30 | 28-8667 | .80 | 28-8843 | .90 |
| 28-8201 | 2.20 | 28-8376 | 1.20 | 28-8668 | .80 | 28-8844 | .90 |
| 28-8202 | 2.20 | 28-8377 | 1.20 | 28-8670 | .90 | 28-8845 | .90 |
| 28-8204 | .65 | 28-8380 | .01 | 28-8672 | .90 | 28-8846 | .90 |
| 28-8205 | .65 | 28-8384 | 1.35 | 28-8674 | .80 | 28-8847 | .80 |
| 28-8206 | 1.25 | 28-8386 | .01 | 28-8675 | .90 | 28-8848 | .90 |
| 28-8208 | 2.00 | 28-8394 | 1.25 | 28-8676 | .80 | 28-8849 | .90 |
| 28-8209 | 2.00 | 28-8396 | 1.55 | 28-8677 | .90 | 28-8850 | .90 |
| 28-8211 | 3.50 | 28-8397 | 1.80 | 28-8678 | .90 | 28-8852 | .90 |
| 28-8212 | 3.50 | 28-8398 | 1.25 | 28-8679 | .80 | 28-8853 | .90 |
| 28-8214 | 1.15 | 28-8399 | 1.25 | 28-8680 | 1.00 | 28-8861 | .05 |
| 28-8215 | 1.15 | 28-8402 | 3.10 | 28-8681 | 1.00 | 28-8864 | 1.00 |
| 28-8216 | .02 | 28-8403 | 3.10 | 28-8683 | .90 | 28-8868 | per 100 .50 |
| 28-8217 | 1.10 | 28-8416 | .02 | 28-8684 | 1.00 | 28-8871 | 1.00 |
| 28-8218 | 2.20 | 28-8434 | .05 | 28-8686 | 1.00 | 28-8872 | .03 |
| 28-8219 | 2.20 | 28-8436 | 1.15 | 28-8688 | .90 | 28-8874 | .01 |
| 28-8221 | 2.50 | 28-8437 | 1.00 | 28-8690 | .90 | 28-8878 | 2.20 |
| 28-8222 | 2.50 | 28-8439 | 1.15 | 28-8695 | .90 | 28-8879 | 2.20 |
| 28-8223 | 1.45 | 28-8440 | 1.15 | 28-8696 | .90 | 28-8882 | .05 |
| 28-8224 | per 100 2.50 | 28-8441 | 1.15 | 28-8699 | .90 | 28-8900 | .02 |
| 28-8226 | 1.25 | 28-8442 | 1.00 | 28-8700 | 2.00 | 28-8903 | .05 |
| 28-8227 | 1.15 | 28-8445 | 1.25 | 28-8701 | 2.00 | 28-8908 | .01 |
| 28-8228 | .80 | 28-8446 | 1.25 | 28-8702 | 1.10 | 28-8909 | .01 |
| 28-8229 | .02 | 28-8462 | 2.00 | 28-8704 | 2.00 | 28-8910 | per 100 1.50 |
| 28-8230 | 1.10 | 28-8464 | 2.85 | 28-8707 | .03 | 28-8913 | .05 |
| 28-8232 | .03 | 28-8468 | 1.40 | 28-8709 | .90 | 28-8915 | .03 |
| 28-8241 | 1.00 | 28-8478 | 1.25 | 28-8710 | .90 | 28-8918 | .10 |
| 28-8242 | .90 | 28-8479 | 1.25 | 28-8714 | .90 | 28-8919 | .04 |
| 28-8245 | .03 | 28-8483 | 1.25 | 28-8717 | 1.40 | 28-8922 | .05 |
| 28-8246 | 2.00 | 28-8484 | 1.25 | 28-8719 | 1.40 | 28-8925 | .05 |
| 28-8247 | 2.50 | 28-8485 | 1.20 | 28-8727 | 1.20 | 28-8927 | .02 |
| 28-8248 | 3.00 | 28-8486 | 1.20 | 28-8733 | .01 | 28-8931 | .05 |
| 28-8249 | 3.50 | 28-8487 | 1.20 | 28-8736 | .05 | 28-8933 | .15 |
| 28-8250 | .90 | 28-8491 | 1.35 | 28-8738 | 1.10 | 28-8934 | .10 |
| 28-8252 | .02 | 28-8492 | 1.35 | 28-8739 | 1.10 | 28-8935 | .10 |
| 28-8253 | 2.50 | 28-8494 | 1.15 | 28-8740 | 1.00 | 28-8936 | .15 |
| 28-8256 | per 100 .70 | 28-8496 | .05 | 28-8747 | .90 | 28-8943 | .05 |
| 28-8260 | 1.15 | 28-8497 | 1.90 | 28-8751 | .05 | 28-8944 | .05 |
| 28-8261 | per 100 .70 | 28-8498 | .10 | 28-8756 | .02 | 28-8945 | .05 |
| 28-8263 | .75 | 28-8535 | .90 | 28-8757 | .01 | 28-8946 | .05 |
| 28-8268 | .70 | 28-8544 | .80 | 28-8758 | .01 | 28-8947 | .10 |
| 28-8269 | .70 | 28-8552 | 1.00 | 28-8761 | .04 | 28-8949 | .01 |
| 28-8272 | 1.00 | 28-8553 | 1.00 | 28-8762 | 1.00 | 28-8952 | .05 |
| 28-8279 | 2.20 | 28-8554 | 1.00 | 28-8763 | 1.00 | 28-8953 | .03 |
| 28-8281 | .80 | 28-8592 | 1.10 | 28-8764 | 1.00 | 28-8954 | .05 |
| 28-8285 | 1.20 | 28-8595 | 1.00 | 28-8765 | 1.00 | 28-8955 | .01 |
| 28-8289 | 1.35 | 28-8599 | 1.00 | 28-8774 | .06 | 28-8958 | .05 |
| 28-8299 | 2.35 | 28-8600 | 1.30 | 28-8775 | .04 | 28-8961 | .01 |
| 28-8305 | 4.60 | 28-8601 | .04 | 28-8779 | 1.00 | 28-8962 | .03 |
| 28-8306 | 4.80 | 28-8602 | .02 | 28-8780 | .90 | 28-8963 | .03 |
| 28-8310 | 1.50 | 28-8604 | .02 | 28-8781 | .90 | 28-8964 | .05 |
| 28-8314 | 1.00 | 28-8606 | 1.30 | 28-8782 | 1.00 | 28-8965 | .05 |
| 28-8315 | 1.00 | 28-8607 | 1.30 | 28-8783 | 1.00 | 28-8966 | .02 |
| 28-8316 | 1.20 | 28-8608 | 1.65 | 28-8784 | 1.00 | 28-8968 | .01 |
| 28-8317 | 1.00 | 28-8609 | 1.65 | 28-8785 | 1.50 | 28-8970 | .01 |
| 28-8318 | 1.00 | 28-8610 | .03 | 28-8786 | 1.50 | 28-8971 | .15 |
| 28-8319 | 1.00 | 28-8611 | .01 | 28-8787 | 1.50 | 28-8972 | .02 |
| 28-8320 | 1.00 | 28-8612 | 1.00 | 28-8790 | .90 | 28-8973 | .20 |
| 28-8322 | 1.65 | 28-8615 | .25 | 28-8791 | .90 | 28-8974 | .15 |
| 28-8323 | 1.65 | 28-8616 | 1.00 | 28-8792 | .90 | 28-8976 | .25 |
| 28-8324 | 1.45 | 28-8619 | 1.50 | 28-8793 | 1.80 | 28-8978 | .25 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 28-8980 | .25 | 30-1095 | .20 | 30-2013 | 1.60 | 30-2127 | 1.60 |
| 28-8981 | .20 | 30-1096 | .40 | 30-2014 | 1.50 | 30-2128 | 1.80 |
| 28-8982 | .40 | 30-1097 | .15 | 30-2015 | 2.00 | 30-2129 | 1.65 |
| 28-8983 | .40 | 30-1099 | .25 | 30-2017 | 2.35 | 30-2130 | 2.15 |
| 28-8984 | .40 | 30-1101 | .15 | 30-2021 | 1.00 | 30-2131 | 2.00 |
| | | 30-1102 | .20 | 30-2023 | 1.00 | 30-2132 | .70 |
| 30-1000 | .25 | 30-1103 | .20 | 30-2024 | 1.00 | 30-2134 | 1.80 |
| 30-1001 | .60 | 30-1104 | .40 | 30-2025 | 1.20 | 30-2138 | 1.75 |
| 30-1002 | .60 | 30-1105 | .20 | 30-2026 | 1.25 | 30-2140 | 2.75 |
| 30-1004 | .25 | 30-1106 | .15 | 30-2030 | 1.60 | 30-2143 | 1.25 |
| 30-1005 | .20 | 30-1107 | .20 | 30-2038 | 1.15 | 30-2144 | 1.00 |
| 30-1006 | .15 | 30-1108 | .15 | 30-2041 | .70 | 30-2145 | 1.75 |
| 30-1007 | .25 | 30-1109 | .55 | 30-2042 | .70 | 30-2147 | 1.85 |
| 30-1008 | .15 | 30-1110 | .45 | 30-2043 | .85 | 30-2148 | 2.00 |
| 30-1010 | .15 | 30-1111 | .45 | 30-2044 | 1.05 | 30-2149 | 1.60 |
| 30-1011 | .15 | 30-1112 | .30 | 30-2046 | 1.75 | 30-2151 | .80 |
| 30-1012 | .15 | 30-1113 | .30 | 30-2048 | 1.10 | 30-2152 | 1.75 |
| 30-1013 | .20 | 30-1114 | .20 | 30-2049 | 1.15 | 30-2154 | 3.25 |
| 30-1014 | .20 | 30-1115 | .40 | 30-2051 | .80 | 30-2157 | 1.30 |
| 30-1015 | .25 | 30-1116 | .45 | 30-2052 | .95 | 30-2158 | .75 |
| 30-1016 | .45 | 30-1117 | .15 | 30-2053 | 1.05 | 30-2159 | 1.85 |
| 30-1017 | .45 | 30-1118 | .20 | 30-2054 | 1.20 | 30-2160 | 2.00 |
| 30-1018 | .60 | 30-1119 | .20 | 30-2055 | .85 | 30-2161 | 1.60 |
| 30-1019 | .70 | 30-1120 | .15 | 30-2056 | 1.00 | 30-2162 | 1.50 |
| 30-1020 | .45 | 30-1121 | .30 | 30-2057 | 1.05 | 30-2163 | 2.00 |
| 30-1026 | .40 | 30-1122 | .30 | 30-2058 | 1.25 | 30-2164 | 1.00 |
| 30-1027 | .25 | 30-1123 | .30 | 30-2059 | .95 | 30-2166 | 1.60 |
| 30-1030 | .15 | 30-1125 | .35 | 30-2060 | 1.15 | 30-2167 | 1.50 |
| 30-1031 | .15 | 30-1128 | .15 | 30-2061 | 1.25 | 30-2169 | 1.75 |
| 30-1033 | .15 | 30-1130 | .15 | 30-2062 | 2.00 | 30-2170 | 1.50 |
| 30-1034 | .20 | 30-1131 | .30 | 30-2063 | .75 | 30-2171 | 1.75 |
| 30-1035 | .20 | 30-1132 | .20 | 30-2064 | .90 | 30-2173 | 1.25 |
| 30-1036 | .20 | 30-1134 | .55 | 30-2065 | 1.90 | 30-2176 | 1.50 |
| 30-1037 | .25 | 30-1135 | .30 | 30-2066 | .95 | 30-2177 | 1.75 |
| 30-1039 | .20 | 30-1136 | .30 | 30-2067 | .80 | 30-2183 | 2.00 |
| 30-1040 | .20 | 30-1138 | .40 | 30-2068 | 1.50 | 30-2191 | .75 |
| 30-1041 | .20 | 30-1139 | .30 | 30-2069 | 1.60 | 30-2192 | 2.25 |
| 30-1042 | .35 | 30-1140 | .30 | 30-2072 | 2.50 | 30-2194 | 1.20 |
| 30-1043 | .65 | 30-1141 | .15 | 30-2073 | 2.35 | 30-2198 | 1.00 |
| 30-1044 | .15 | 30-1142 | .25 | 30-2075 | 1.00 | 30-2200 | 1.50 |
| 30-1045 | .20 | 30-1143 | .15 | 30-2076 | 1.25 | 30-2201 | 1.70 |
| 30-1046 | .20 | 30-1154 | .20 | 30-2077 | 5.75 | 30-2203 | 1.60 |
| 30-1048 | .20 | 30-1155 | .15 | 30-2078 | 2.45 | 30-2205 | 1.05 |
| 30-1049 | .25 | 30-1156 | .60 | 30-2079 | 2.00 | 30-2206 | 1.50 |
| 30-1050 | .50 | 30-1157 | .35 | 30-2080 | 1.85 | 30-2210 | 1.25 |
| 30-1052 | .20 | 30-1173 | .30 | 30-2083 | 1.45 | 30-2211 | 1.10 |
| 30-1053 | .15 | 30-1174 | .30 | 30-2084 | 1.00 | 30-2212 | 1.05 |
| 30-1054 | .40 | 30-1175 | .35 | 30-2085 | .95 | 30-2213 | 1.75 |
| 30-1055 | .40 | 30-1176 | .35 | 30-2086 | .90 | 30-2217 | 1.70 |
| 30-1056 | .20 | 30-1177 | .35 | 30-2087 | .85 | 30-2219 | 1.60 |
| 30-1057 | .35 | 30-1178 | .35 | 30-2089 | .65 | 30-2220 | .95 |
| 30-1058 | .55 | 30-1179 | .35 | 30-2091 | 1.60 | 30-2221 | .95 |
| 30-1059 | .15 | 30-1181 | .35 | 30-2092 | 1.60 | 30-2222 | .95 |
| 30-1060 | .30 | 30-1182 | .35 | 30-2094 | 1.40 | 30-2226 | 3.00 |
| 30-1061 | .45 | 30-1183 | .60 | 30-2095 | 1.20 | 30-2228 | 2.50 |
| 30-1062 | .30 | 30-1185 | .45 | 30-2096 | 1.00 | 30-2230 | 1.70 |
| 30-1063 | .30 | 30-1186 | .35 | 30-2097 | 1.10 | 30-2232 | 2.25 |
| 30-1064 | .30 | 30-1187 | .60 | 30-2098 | .90 | 30-2234 | 1.50 |
| 30-1065 | .15 | 30-1188 | .35 | 30-2099 | 2.80 | 30-2235 | 1.20 |
| 30-1067 | .15 | 30-1191 | .45 | 30-2100 | 2.50 | 30-2236 | .90 |
| 30-1068 | .15 | 30-1192 | .35 | 30-2101 | 2.25 | 30-2237 | 1.00 |
| 30-1069 | .30 | 30-1193 | .35 | 30-2102 | 2.00 | 30-2239 | 2.00 |
| 30-1070 | .20 | 30-1194 | .35 | 30-2103 | .80 | 30-2241 | 1.50 |
| 30-1071 | .55 | 30-1195 | .45 | 30-2104 | 1.45 | 30-2243 | 1.50 |
| 30-1073 | .20 | 30-1196 | .35 | 30-2105 | 2.00 | 30-2245 | .95 |
| 30-1074 | .25 | 30-1197 | .35 | 30-2106 | 1.05 | 30-2246 | .75 |
| 30-1076 | .20 | 30-1198 | .35 | 30-2107 | 1.60 | 30-2247 | 2.25 |
| 30-1077 | .20 | 30-1199 | .30 | 30-2108 | 1.15 | 30-2249 | 1.75 |
| 30-1078 | .25 | 30-1200 | .35 | 30-2109 | 2.50 | 30-2251 | 1.75 |
| 30-1079 | .20 | 30-1201 | .35 | 30-2110 | 2.00 | 30-2256 | 1.75 |
| 30-1080 | .20 | 30-1202 | .30 | 30-2111 | .80 | 30-2257 | 1.50 |
| 30-1081 | .25 | 30-1203 | .40 | 30-2112 | 2.00 | 30-2259 | 2.00 |
| 30-1082 | .20 | 30-1205 | .35 | 30-2113 | .95 | 30-2261 | 1.00 |
| 30-1083 | .15 | 30-1208 | .35 | 30-2114 | 1.85 | 30-2263 | 1.75 |
| 30-1084 | .45 | 30-1210 | .35 | 30-2115 | 2.40 | 30-2265 | 1.60 |
| 30-1085 | .40 | 30-2001 | 1.15 | 30-2116 | 2.40 | 30-2268 | 1.75 |
| 30-1086 | .20 | 30-2002 | 1.30 | 30-2117 | 1.25 | 30-2270 | 2.25 |
| 30-1087 | .25 | 30-2003 | .90 | 30-2120 | 1.10 | 30-2271 | 1.60 |
| 30-1088 | .15 | 30-2004 | 2.00 | 30-2121 | 2.50 | 30-2275 | 1.55 |
| 30-1090 | .20 | 30-2005 | 1.80 | 30-2122 | 1.85 | 30-2277 | 1.25 |
| 30-1091 | .20 | 30-2007 | .80 | 30-2123 | 1.80 | 30-2279 | .85 |
| 30-1092 | .25 | 30-2008 | 1.80 | 30-2124 | .75 | 30-2284 | 1.30 |
| 30-1093 | .25 | 30-2010 | 1.80 | 30-2125 | 1.25 | 30-2291 | 1.80 |
| 30-1094 | .45 | 30-2012 | .90 | 30-2126 | 1.65 | 30-2293 | 1.00 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 30-2294 | 2.20 | 30-2435 | 1.20 | 30-4048 | .60 | 30-4334 | .15 |
| 30-2296 | 1.90 | 30-2436 | 1.75 | 30-4053 | .85 | 30-4335 | .20 |
| 30-2298 | 2.10 | 30-2437 | 1.10 | 30-4063 | .85 | 30-4336 | .20 |
| 30-2311 | 1.20 | 30-2438 | .75 | 30-4065 | 1.50 | 30-4340 | .25 |
| 30-2315 | 1.60 | 30-2445 | 1.60 | 30-4069 | .75 | 30-4343 | .75 |
| 30-2316 | 1.60 | 30-2446 | 1.20 | 30-4070 | .75 | 30-4344 | .50 |
| 30-2317 | 1.60 | 30-2447 | 1.20 | 30-4076 | .45 | 30-4350 | .75 |
| 30-2319 | 1.30 | 30-2449 | 1.25 | 30-4077 | 1.00 | 30-4351 | .75 |
| 30-2323 | 1.60 | 30-2452 | 1.15 | 30-4078 | .75 | 30-4352 | .75 |
| 30-2327 | .70 | 30-2453 | .75 | 30-4081 | .50 | 30-4355 | 2.25 |
| 30-2328 | .75 | 30-2454 | 1.50 | 30-4087 | .85 | 30-4356 | 1.20 |
| 30-2329 | .95 | 30-2455 | 1.40 | 30-4093 | .60 | 30-4357 | 1.30 |
| 30-2330 | .90 | 30-2456 | 1.10 | 30-4094 | .45 | 30-4358 | .15 |
| 30-2331 | .85 | 30-2457 | 1.10 | 30-4095 | .35 | 30-4373 | .20 |
| 30-2332 | 1.00 | 30-2458 | 1.00 | 30-4096 | .50 | 30-4374 | 1.25 |
| 30-2333 | 1.00 | 30-2459 | .60 | 30-4102 | .50 | 30-4375 | 1.00 |
| 30-2334 | .70 | 30-2463 | 1.10 | 30-4103 | .85 | 30-4377 | .50 |
| 30-2335 | 1.35 | 30-2464 | .75 | 30-4104 | 1.35 | 30-4378 | .75 |
| 30-2336 | 2.00 | 30-2465 | .85 | 30-4112 | .15 | 30-4379 | .75 |
| 30-2337 | .70 | 30-2466 | .85 | 30-4114 | .20 | 30-4381 | .30 |
| 30-2338 | .80 | 30-2467 | .95 | 30-4115 | .20 | 30-4382 | .75 |
| 30-2339 | .90 | 30-2468 | 1.40 | 30-4117 | .35 | 30-4384 | .50 |
| 30-2340 | .80 | 30-2469 | .55 | 30-4119 | .15 | 30-4388 | .35 |
| 30-2341 | .90 | 30-2470 | 1.50 | 30-4123 | .15 | 30-4399 | .75 |
| 30-2342 | 1.00 | 30-2471 | .70 | 30-4124 | .15 | 30-4404 | .50 |
| 30-2345 | 1.20 | 30-2472 | 1.00 | 30-4125 | .15 | 30-4405 | .80 |
| 30-2346 | .90 | 30-2473 | .55 | 30-4126 | 1.15 | 30-4410 | 1.00 |
| 30-2348 | 1.15 | 30-2474 | .70 | 30-4127 | .75 | 30-4412 | .35 |
| 30-2356 | 1.25 | 30-2475 | 1.20 | 30-4135 | 2.25 | 30-4415 | 1.10 |
| 30-2359 | .40 | 30-2476 | .90 | 30-4136 | .75 | 30-4419 | .30 |
| 30-2360 | 1.05 | 30-2477 | .80 | 30-4138 | .75 | 30-4420 | .35 |
| 30-2361 | 1.00 | 30-2478 | .50 | 30-4140 | .80 | 30-4423 | .15 |
| 30-2363 | .95 | 30-2479 | .85 | 30-4144 | 1.30 | 30-4426 | .35 |
| 30-2364 | 1.00 | 30-2480 | 1.35 | 30-4146 | .25 | 30-4427 | .50 |
| 30-2366 | 1.25 | 30-2481 | .80 | 30-4147 | .50 | 30-4428 | .35 |
| 30-2367 | .85 | 30-2488 | 1.75 | 30-4150 | .70 | 30-4429 | .50 |
| 30-2368 | 1.50 | 30-2491 | 1.00 | 30-4151 | 1.00 | 30-4444 | .15 |
| 30-2370 | .85 | 30-2492 | 1.30 | 30-4155 | .85 | 30-4445 | .15 |
| 30-2371 | .90 | 30-2494 | 1.15 | 30-4167 | 1.15 | 30-4446 | .25 |
| 30-2372 | 1.45 | 30-2495 | .60 | 30-4169 | .15 | 30-4447 | .20 |
| 30-2373 | 1.25 | 30-2496 | .65 | 30-4170 | .20 | 30-4453 | .25 |
| 30-2374 | 2.50 | 30-2497 | 1.20 | 30-4172 | .50 | 30-4454 | .20 |
| 30-2377 | 1.00 | 30-2498 | 1.50 | 30-4173 | 1.10 | 30-4455 | .20 |
| 30-2380 | 1.40 | 30-2499 | 1.00 | 30-4174 | .60 | 30-4456 | .15 |
| 30-2382 | 1.00 | 30-2500 | .40 | 30-4175 | .50 | 30-4462 | .50 |
| 30-2385 | 1.15 | 30-2501 | 1.25 | 30-4176 | .50 | 30-4465 | .25 |
| 30-2386 | 1.35 | 30-2502 | .85 | 30-4177 | .20 | 30-4466 | 1.40 |
| 30-2387 | 1.45 | 30-2503 | 1.00 | 30-4180 | .75 | 30-4469 | .20 |
| 30-2388 | .75 | 30-2504 | 1.25 | 30-4181 | .50 | 30-4470 | 1.40 |
| 30-2391 | 1.10 | 30-2506 | 1.35 | 30-4184 | .50 | 30-4473 | 4.00 |
| 30-2394 | .90 | 30-2507 | 1.15 | 30-4185 | .20 | 30-4474 | .50 |
| 30-2396 | .50 | 30-2508 | .75 | 30-4186 | .75 | 30-4475 | .75 |
| 30-2400 | 1.20 | 30-2509 | 1.35 | 30-4189 | .75 | 30-4477 | .50 |
| 30-2401 | .50 | 30-2510 | 1.15 | 30-4190 | .75 | 30-4478 | 1.20 |
| 30-2402 | 1.30 | 30-2511 | 1.25 | 30-4191 | .25 | 30-4481 | .15 |
| 30-2403 | 1.00 | 30-2512 | 1.45 | 30-4192 | .75 | 30-4486 | .25 |
| 30-2404 | 1.00 | 30-2513 | 1.10 | 30-4196 | .75 | 30-4490 | .75 |
| 30-2405 | 1.00 | 30-2515 | 1.05 | 30-4201 | .25 | 30-4491 | .35 |
| 30-2406 | .80 | 30-2517 | 1.00 | 30-4204 | .75 | 30-4493 | 1.75 |
| 30-2408 | .85 | 30-2519 | 1.00 | 30-4210 | .50 | 30-4494 | 2.50 |
| 30-2409 | .65 | 30-2522 | .60 | 30-4211 | .75 | 30-4495 | .30 |
| 30-2410 | .80 | 30-2524 | 1.35 | 30-4212 | .50 | 30-4498 | .25 |
| 30-2411 | .55 | 30-2526 | 1.15 | 30-4217 | 1.15 | 30-4500 | .50 |
| 30-2412 | 1.15 | 30-2528 | 1.40 | 30-4220 | .80 | 30-4501 | 1.15 |
| 30-2413 | .95 | 30-2529 | 1.30 | 30-4227 | .35 | 30-4504 | .15 |
| 30-2415 | .50 | 30-2530 | 1.30 | 30-4229 | .80 | 30-4505 | .25 |
| 30-2417 | .40 | 30-4000 | 1.20 | 30-4232 | .50 | 30-4508 | .25 |
| 30-2418 | .45 | 30-4003 | .75 | 30-4238 | .50 | 30-4509 | .35 |
| 30-2419 | .55 | 30-4004 | .75 | 30-4241 | 1.25 | 30-4510 | 2.25 |
| 30-2420 | .60 | 30-4007 | .50 | 30-4243 | .75 | 30-4511 | 1.60 |
| 30-2421 | .65 | 30-4013 | 1.00 | 30-4251 | .50 | 30-4512 | .35 |
| 30-2422 | .45 | 30-4017 | 1.80 | 30-4253 | 1.20 | 30-4513 | 2.25 |
| 30-2423 | .50 | 30-4018 | .50 | 30-4258 | .50 | 30-4514 | .15 |
| 30-2424 | .75 | 30-4020 | .15 | 30-4289 | .25 | 30-4515 | .15 |
| 30-2425 | .55 | 30-4023 | 1.20 | 30-4298 | 1.00 | 30-4516 | .15 |
| 30-2426 | .60 | 30-4024 | .20 | 30-4306 | .50 | 30-4517 | .15 |
| 30-2427 | .75 | 30-4026 | 3.60 | 30-4310 | .20 | 30-4518 | .15 |
| 30-2428 | .90 | 30-4027 | .80 | 30-4311 | .65 | 30-4519 | .15 |
| 30-2429 | 1.00 | 30-4028 | .75 | 30-4313 | .75 | 30-4521 | .35 |
| 30-2430 | .75 | 30-4029 | .75 | 30-4317 | .20 | 30-4522 | .35 |
| 30-2431 | 1.05 | 30-4033 | .75 | 30-4318 | .50 | 30-4525 | .35 |
| 30-2432 | 1.05 | 30-4039 | .25 | 30-4326 | .75 | 30-4527 | .20 |
| 30-2433 | 1.30 | 30-4042 | .20 | 30-4327 | .15 | 30-4529 | .15 |
| 30-2434 | 1.05 | 30-4044 | .75 | 30-4332 | .75 | 30-4530 | .25 |
| 30-2434 | 1.05 | 30-4047 | .60 | 30-4333 | .75 | 30-4531 | .20 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 30-4536 | .25 | 31-1066 | .50 | 31-1513 | .75 | 31-1967 | .75 |
| 30-4537 | 1.00 | 31-1067 | 1.75 | 31-1514 | .65 | 31-1968 | .75 |
| 30-4538 | .70 | 31-1070 | .30 | 31-1518 | 9.00 | 31-1969 | 7.35 |
| 30-4545 | 2.20 | 31-1071 | .45 | 31-1522 | 4.65 | 31-1971 | 6.00 |
| 30-4547 | 1.65 | 31-1083 | 6.00 | 31-1523 | 8.35 | 31-1975 | .65 |
| 30-4549 | 1.25 | 31-1085 | .60 | 31-1525 | 5.35 | 31-1984 | 8.65 |
| 30-4551 | .35 | 31-1089 | 3.35 | 31-1526 | 5.35 | 31-1986 | 25.00 |
| 30-4552 | .30 | 31-1095 | .45 | 31-1527 | 4.00 | 31-1989 | 3.65 |
| 30-4554 | 2.00 | 31-1098 | 4.00 | 31-1530 | 6.90 | 31-2015 | 8.00 |
| 30-4555 | .15 | 31-1110 | 6.00 | 31-1534 | 1.00 | 31-2025 | 6.65 |
| 30-4557 | 1.60 | 31-1117 | 6.85 | 31-1540 | 5.00 | 31-2032 | 6.65 |
| 30-4560 | .30 | 31-1122 | 5.35 | 31-1542 | 5.35 | 31-2035 | 9.35 |
| 30-4561 | 1.50 | 31-1143 | 3.35 | 31-1550 | .15 | 31-2038 | 8.00 |
| 30-4562 | .40 | 31-1149 | 7.35 | 31-1555 | 6.00 | 31-2039 | 6.65 |
| 30-4564 | .50 | 31-1153 | 8.35 | 31-1557 | .15 | 31-2040 | 6.65 |
| 30-4565 | .35 | 31-1155 | .45 | 31-1563 | 1.30 | 31-2048 | 15.00 |
| 30-4567 | .35 | 31-1162 | 1.25 | 31-1571 | 5.00 | 31-2052 | 7.35 |
| 30-4568 | 2.25 | 31-1168 | 4.80 | 31-1575 | .40 | 31-2053 | .75 |
| 30-4571 | .25 | 31-1171 | 6.65 | 31-1580 | .05 | 31-2055 | 1.00 |
| 30-4572 | .15 | 31-1182 | 7.35 | 31-1594 | 5.45 | 31-2056 | 1.25 |
| 30-4576 | .30 | 31-1183 | .15 | 31-1600 | .15 | 31-2057 | 3.35 |
| 30-4577 | .15 | 31-1184 | .50 | 31-1608 | 6.65 | 31-2059 | 3.35 |
| 30-4578 | .15 | 31-1186 | .45 | 31-1618 | 10.00 | 31-2072 | 1.00 |
| 30-4579 | .15 | 31-1190 | 3.65 | 31-1619 | 9.35 | 31-2075 | 3.65 |
| 30-4580 | .15 | 31-1192 | 6.00 | 31-1626 | .20 | 31-2076 | 7.35 |
| 30-4581 | .15 | 31-1193 | .10 | 31-1635 | 7.65 | 31-2082 | .10 |
| 30-4582 | .15 | 31-1205 | .50 | 31-1643 | .55 | 31-2086 | .08 |
| 30-4583 | .15 | 31-1206 | 1.25 | 31-1674 | .70 | 31-2089 | 1.00 |
| 30-4584 | .15 | 31-1207 | .50 | 31-1679 | 4.35 | 31-2094 | 4.00 |
| 30-4585 | .15 | 31-1209 | .75 | 31-1680 | 5.65 | 31-2095 | 5.35 |
| 30-4586 | .20 | 31-1213 | 6.65 | 31-1682 | 5.00 | 31-2096 | .10 |
| 30-4587 | .25 | 31-1214 | 7.00 | 31-1683 | 4.65 | 31-2097 | .50 |
| 30-4588 | .25 | 31-1218 | 11.50 | 31-1692 | .40 | 31-2098 | .50 |
| 30-4589 | .35 | 31-1230 | 5.35 | 31-1705 | 5.00 | 31-2100 | 6.00 |
| 30-4590 | .25 | 31-1234 | .30 | 31-1724 | .15 | 31-2107 | .20 |
| 30-4591 | .15 | 31-1241 | .50 | 31-1726 | .30 | 31-2108 | .20 |
| 30-4592 | .15 | 31-1248 | 7.00 | 31-1773 | 7.00 | 31-2111 | 8.65 |
| 30-4593 | .25 | 31-1250 | 8.00 | 31-1731 | .40 | 31-2127 | .40 |
| 30-4594 | .25 | 31-1275 | 1.10 | 31-1734 | .15 | 31-2131 | 9.65 |
| 30-4597 | .15 | 31-1276 | 1.25 | 31-1767 | 8.00 | 31-2137 | .50 |
| 30-4598 | .30 | 31-1279 | 1.30 | 31-1769 | 8.00 | 31-2161 | 9.35 |
| 30-4599 | .15 | 31-1280 | 1.25 | 31-1784 | .65 | 31-2169 | 9.65 |
| 30-4600 | .25 | 31-1283 | .45 | 31-1786 | .65 | 31-2173 | 9.35 |
| 30-4601 | .20 | 31-1289 | 9.50 | 31-1787 | 5.65 | 31-2177 | 3.35 |
| 30-4602 | .20 | 31-1291 | 6.35 | 31-1792 | .50 | 31-2178 | 3.35 |
| 30-4604 | .25 | 31-1296 | 6.00 | 31-1794 | 4.00 | 31-2185 | .85 |
| 30-4607 | 1.50 | 31-1306 | .65 | 31-1796 | 4.35 | 31-2212 | 2.00 |
| 30-4608 | .35 | 31-1307 | .65 | 31-1799 | .60 | 31-2224 | 5.00 |
| 30-4609 | .15 | 31-1308 | 1.00 | 31-1818 | 6.00 | 31-2229 | .08 |
| 30-4610 | .15 | 31-1320 | 4.35 | 31-1821 | 3.50 | 31-2260 | .30 |
| 30-4611 | .20 | 31-1327 | .90 | 31-1823 | 6.00 | 31-2262 | .60 |
| 30-4616 | .20 | 31-1328 | .75 | 31-1826 | 4.00 | 31-2265 | 4.00 |
| 30-4621 | .15 | 31-1335 | 5.65 | 31-1833 | 6.00 | 31-2267 | 3.65 |
| 30-4623 | .15 | 31-1339 | 8.80 | 31-1844 | 5.35 | 31-2269 | .20 |
| 30-4663 | .30 | 31-1344 | 1.00 | 31-1851 | .35 | 31-2273 | 3.65 |
| | | 31-1348 | 9.65 | 31-1857 | 4.35 | 31-2275 | .30 |
| | | 31-1350 | 8.65 | 31-1863 | 6.65 | 31-2280 | 5.35 |
| 31-1000 | 2.80 | 31-1352 | .10 | 31-1866 | .35 | 31-2281 | .45 |
| 31-1004 | 6.40 | 31-1359 | 10.00 | 31-1871 | .75 | 31-2282 | 5.65 |
| 31-1005 | 5.35 | 31-1361 | 5.10 | 31-1877 | .75 | 31-2283 | .50 |
| 31-1007 | 3.20 | 31-1363 | .75 | 31-1878 | .25 | 31-2284 | .40 |
| 31-1008 | .30 | 31-1364 | .90 | 31-1879 | .65 | 31-2288 | 8.65 |
| 31-1010 | 6.35 | 31-1366 | 7.60 | 31-1884 | .25 | 31-2290 | .20 |
| 31-1012 | 6.65 | 31-1370 | .95 | 31-1887 | .45 | 31-2291 | .50 |
| 31-1013 | 6.35 | 31-1382 | 1.10 | 31-1892 | 5.00 | 31-2296 | 7.35 |
| 31-1014 | 6.35 | 31-1393 | 6.00 | 31-1898 | .20 | 31-2298 | .50 |
| 31-1015 | 6.65 | 31-1408 | .30 | 31-1899 | .50 | 31-2300 | 3.65 |
| 31-1019 | 4.80 | 31-1410 | 3.65 | 31-1901 | 1.80 | 31-2301 | 3.65 |
| 31-1020 | .65 | 31-1414 | .60 | 31-1902 | 4.00 | 31-2305 | .75 |
| 31-1022 | .20 | 31-1417 | 1.50 | 31-1907 | .70 | 31-2308 | 7.35 |
| 31-1024 | .40 | 31-1420 | .70 | 31-1915 | .45 | 31-2311 | 5.65 |
| 31-1026 | .35 | 31-1422 | 4.65 | 31-1917 | .75 | 31-2312 | .20 |
| 31-1028 | .35 | 31-1424 | 6.65 | 31-1918 | .75 | 31-2315 | .25 |
| 31-1030 | 3.20 | 31-1426 | 12.00 | 31-1930 | .75 | 31-2316 | .25 |
| 31-1031 | 4.80 | 31-1438 | 6.00 | 31-1932 | 8.00 | 31-2317 | .15 |
| 31-1032 | .35 | 31-1451 | .50 | 31-1940 | 3.65 | 31-2318 | .15 |
| 31-1034 | 2.80 | 31-1456 | .08 | 31-1941 | .15 | 31-2320 | .35 |
| 31-1035 | 2.80 | 31-1457 | .10 | 31-1947 | .12 | 31-2321 | .55 |
| 31-1038 | 7.10 | 31-1459 | 8.65 | 31-1953 | 5.35 | 31-2322 | 4.00 |
| 31-1040 | 4.00 | 31-1470 | .45 | 31-1956 | 8.35 | 31-2323 | .15 |
| 31-1053 | 6.40 | 31-1471 | .40 | 31-1957 | .75 | 31-2324 | .20 |
| 31-1054 | .10 | 31-1472 | .40 | 31-1959 | .30 | 31-2325 | 9.00 |
| 31-1056 | .25 | 31-1473 | .40 | 31-1961 | .80 | 31-2326 | 7.65 |
| 31-1057 | .50 | 31-1481 | .40 | 31-1963 | 5.35 | 31-2329 | 1.75 |
| 31-1059 | 6.65 | 31-1482 | 7.35 | | | 31-2330 | .25 |
| 31-1065 | .50 | | | | | | |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 31-2331 | .15 | 31-2447 | 3.35 | 31-2547 | .20 | 31-6099 | .50 |
| 31-2334 | .50 | 31-2448 | 3.35 | 31-2548 | 3.35 | 31-6100 | .40 |
| 31-2335 | 3.35 | 31-2449 | 3.65 | 31-2549 | 4.00 | 31-6101 | .20 |
| 31-2338 | 4.00 | 31-2450 | 3.65 | 31-2551 | .15 | 31-6102 | .35 |
| 31-2340 | .50 | 31-2451 | 1.50 | 31-2553 | .25 | 31-6103 | .60 |
| 31-2343 | .10 | 31-2453 | .40 | 31-2555 | 3.65 | 31-6104 | 1.40 |
| 31-2346 | 3.65 | 31-2454 | .85 | 31-2558 | 3.35 | 31-6105 | 1.00 |
| 31-2347 | .15 | 31-2455 | 3.35 | 31-2559 | .15 | 31-6106 | 1.00 |
| 31-2350 | .20 | 31-2456 | 3.35 | 31-2561 | 3.35 | 31-6108 | 1.00 |
| 31-2351 | .50 | 31-2457 | 3.00 | 31-2562 | .25 | 31-6110 | 1.50 |
| 31-2352 | .30 | 31-2458 | .45 | 31-2563 | .10 | 31-6111 | 1.50 |
| 31-2354 | 3.35 | 31-2459 | 4.00 | 31-2564 | 3.35 | 31-6112 | 1.40 |
| 31-2355 | .20 | 31-2460 | .25 | 31-2565 | .15 | 31-6113 | 1.40 |
| 31-2356 | .30 | 31-2461 | 3.35 | 31-2567 | 3.35 | 31-6115 | .50 |
| 31-2357 | 3.65 | 31-2463 | .30 | 31-2572 | 3.65 | 31-6117 | 1.20 |
| 31-2358 | .10 | 31-2464 | 3.35 | 31-2573 | .25 | 31-6118 | 1.00 |
| 31-2362 | 3.35 | 31-2465 | .30 | 31-2576 | .20 | 31-6120 | .50 |
| 31-2363 | 3.35 | 31-2466 | 4.35 | 31-2578 | 3.35 | 31-6122 | .75 |
| 31-2365 | 3.35 | 31-2467 | 1.50 | 31-2579 | 3.35 | 31-6124 | 1.00 |
| 31-2366 | .50 | 31-2468 | .50 | 31-2581 | 3.65 | 31-6127 | 1.00 |
| 31-2369 | 3.00 | 31-2469 | .15 | 31-2585 | .20 | 31-6128 | 1.00 |
| 31-2370 | .15 | 31-2470 | .30 | 31-2586 | .25 | 31-6231 | .75 |
| 31-2371 | 3.35 | 31-2472 | 3.35 | 31-2594 | .20 | 31-6133 | 1.25 |
| 31-2372 | 3.65 | 31-2473 | .20 | 31-2596 | 5.35 | 31-6134 | .95 |
| 31-2373 | 3.65 | 31-2474 | 3.35 | 31-2597 | .20 | 31-6135 | .85 |
| 31-2374 | 4.00 | 31-2475 | .30 | 31-2604 | .20 | 31-6136 | .85 |
| 31-2375 | 4.00 | 31-2476 | 3.00 | 31-6000 | .55 | 31-6137 | .60 |
| 31-2377 | 3.35 | 31-2477 | .15 | 31-6001 | .45 | 31-6138 | .40 |
| 31-2378 | 4.00 | 31-2480 | .20 | 31-6002 | .45 | 31-6145 | .50 |
| 31-2379 | .20 | 31-2481 | 3.35 | 31-6003 | .45 | 31-6147 | .40 |
| 31-2380 | .15 | 31-2482 | 3.35 | 31-6004 | .35 | 31-6149 | .75 |
| 31-2382 | .20 | 31-2483 | 4.35 | 31-6007 | .40 | 31-6150 | .30 |
| 31-2383 | .20 | 31-2484 | .30 | 31-6008 | .40 | 31-6151 | .40 |
| 31-2384 | 3.65 | 31-2485 | 3.00 | 31-6012 | .45 | 31-6152 | .60 |
| 31-2386 | 9.35 | 31-2487 | .20 | 31-6013 | .35 | 31-6153 | 1.50 |
| 31-2387 | .10 | 31-2488 | .15 | 31-6014 | .40 | 31-6155 | .40 |
| 31-2388 | 3.65 | 31-2489 | .10 | 31-6015 | .30 | 31-6156 | .60 |
| 31-2389 | 4.65 | 31-2490 | 3.35 | 31-6016 | .15 | 31-6158 | 1.00 |
| 31-2391 | 4.00 | 31-2492 | 3.35 | 31-6020 | .50 | 31-6160 | .30 |
| 31-2392 | .25 | 31-2493 | 3.35 | 31-6021 | .50 | 31-6161 | .30 |
| 31-2393 | .10 | 31-2494 | 3.65 | 31-6022 | .40 | 31-6165 | .30 |
| 31-2394 | .10 | 31-2495 | .10 | 31-6023 | .45 | 31-6170 | .75 |
| 31-2395 | .20 | 31-2496 | .30 | 31-6024 | .25 | 31-6171 | .75 |
| 31-2397 | 4.00 | 31-2497 | 3.35 | 31-6026 | .85 | 31-6173 | .40 |
| 31-2399 | .20 | 31-2498 | .15 | 31-6027 | .70 | 31-6182 | .30 |
| 31-2400 | .10 | 31-2499 | 5.65 | 31-6028 | .85 | 31-6186 | .30 |
| 31-2401 | 3.65 | 31-2500 | 3.35 | 31-6029 | .50 | 31-6188 | .50 |
| 31-2402 | 3.35 | 31-2501 | .10 | 31-6030 | .50 | 31-6189 | 1.50 |
| 31-2403 | 3.65 | 31-2502 | .20 | 31-6033 | .50 | 31-6190 | .40 |
| 31-2404 | 3.65 | 31-2504 | .15 | 31-6034 | .35 | 31-6191 | .40 |
| 31-2405 | .30 | 31-2505 | .15 | 31-6035 | .35 | 31-6192 | .45 |
| 31-2406 | 2.25 | 31-2507 | 4.35 | 31-6036 | .35 | 31-6193 | .75 |
| 31-2408 | 3.00 | 31-2508 | .15 | 31-6038 | .35 | 31-6194 | .50 |
| 31-2411 | .10 | 31-2509 | 3.35 | 31-6040 | .40 | 31-6197 | .40 |
| 31-2412 | 3.35 | 31-2510 | .20 | 31-6041 | .75 | 31-6199 | .40 |
| 31-2413 | 3.35 | 31-2511 | .20 | 31-6042 | .25 | 31-6200 | .80 |
| 31-2414 | 3.35 | 31-2512 | .15 | 31-6044 | .50 | 31-6201 | .40 |
| 31-2415 | .10 | 31-2513 | .20 | 31-6047 | .50 | 31-6202 | .50 |
| 31-2416 | 4.00 | 31-2514 | .15 | 31-6049 | .45 | 31-6203 | .30 |
| 31-2417 | 7.35 | 31-2515 | 3.65 | 31-6050 | .40 | 31-6204 | .25 |
| 31-2418 | 3.35 | 31-2516 | .15 | 31-6053 | .50 | 31-6205 | .40 |
| 31-2421 | .30 | 31-2517 | .15 | 31-6054 | .45 | 31-6206 | .50 |
| 31-2423 | 3.35 | 31-2520 | .15 | 31-6055 | .50 | 31-6210 | .40 |
| 31-2424 | 3.65 | 31-2521 | .15 | 31-6056 | .55 | 31-6211 | .45 |
| 31-2425 | 3.35 | 31-2522 | 3.35 | 31-6057 | .70 | 31-6212 | .25 |
| 31-2426 | 3.65 | 31-2523 | 3.65 | 31-6058 | .60 | 31-6214 | .20 |
| 31-2427 | 3.35 | 31-2524 | .20 | 31-6059 | .50 | 31-6223 | .75 |
| 31-2428 | 3.65 | 31-2525 | .15 | 31-6060 | .50 | 31-6224 | .45 |
| 31-2429 | 3.35 | 31-2526 | .20 | 31-6063 | .50 | 31-6225 | .75 |
| 31-2430 | 3.65 | 31-2527 | 3.35 | 31-6064 | .50 | 31-6227 | .60 |
| 31-2431 | 3.35 | 31-2528 | .25 | 31-6066 | .45 | 31-6228 | .55 |
| 31-2432 | 3.35 | 31-2529 | .20 | 31-6067 | .45 | 31-6229 | .25 |
| 31-2433 | 5.00 | 31-2530 | 3.35 | 31-6073 | .50 | 31-6230 | .40 |
| 31-2434 | 3.35 | 31-2531 | .30 | 31-6074 | .40 | 31-6231 | .60 |
| 31-2436 | 3.35 | 31-2532 | .15 | 31-6077 | .40 | 31-6232 | .50 |
| 31-2437 | 3.65 | 31-2533 | 3.35 | 31-6081 | .40 | 31-6237 | .25 |
| 31-2438 | 3.65 | 31-2534 | 3.35 | 31-6082 | .40 | 31-6244 | .35 |
| 31-2439 | 3.35 | 31-2535 | 4.65 | 31-6084 | .15 | 31-6245 | .40 |
| 31-2440 | 4.00 | 31-2536 | 3.35 | 31-6085 | .60 | 31-6246 | .55 |
| 31-2441 | .15 | 31-2539 | 3.35 | 31-6086 | .45 | 31-6248 | .25 |
| 31-2442 | .20 | 31-2541 | .10 | 31-6087 | .45 | 31-6250 | .35 |
| 31-2443 | 3.35 | 31-2542 | .10 | 31-6092 | .60 | 31-6252 | .45 |
| 31-2444 | 5.65 | 31-2543 | .20 | 31-6093 | .40 | 31-6253 | .40 |
| 31-2445 | 3.35 | 31-2544 | 3.35 | 31-6096 | .40 | 31-6255 | .60 |
| 31-2446 | 3.35 | 31-2546 | .15 | 31-6097 | .50 | 31-6256 | 2.00 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 31-6257 | .45 | 31-6381 | 2.75 | 32-1171 | 1.20 | 32-1393 | 1.50 |
| 31-6259 | 2.00 | 31-6382 | .50 | 32-1172 | 1.20 | 32-1395 | 1.20 |
| 31-6260 | .35 | 31-6383 | .40 | 32-1173 | 1.20 | 32-1396 | .70 |
| 31-6262 | .35 | 31-6384 | .20 | 32-1174 | .90 | 32-1397 | .70 |
| 31-6263 | .60 | 31-6385 | .40 | 32-1182 | .70 | 32-1398 | .70 |
| 31-6264 | 2.00 | 31-6386 | .20 | 32-1183 | .70 | 32-1402 | .35 |
| 31-6266 | .55 | 31-6387 | .50 | 32-1184 | .60 | 32-1403 | 1.80 |
| 31-6267 | 2.00 | 31-6388 | .20 | 32-1185 | .90 | 32-1404 | 1.80 |
| 31-6268 | 1.50 | 31-6389 | 1.50 | 32-1186 | .80 | 32-1410 | 1.80 |
| 31-6273 | 2.00 | 31-6390 | 1.50 | 32-1188 | 1.20 | 32-1411 | 1.80 |
| 31-6274 | .25 | 31-6391 | .35 | 32-1195 | 1.20 | 32-1412 | 1.20 |
| 31-6276 | .25 | 31-6392 | 2.00 | 32-1197 | .90 | 32-1413 | .70 |
| 31-6278 | .30 | 31-6393 | 1.75 | 32-1198 | .80 | 32-1414 | 1.80 |
| 31-6280 | .30 | 31-6394 | .30 | 32-1201 | .90 | 32-1415 | 1.80 |
| 31-6282 | .40 | 31-6397 | .30 | 32-1205 | .90 | 32-1420 | .70 |
| 31-6283 | .50 | 31-6399 | 2.00 | 32-1208 | .70 | 32-1421 | .70 |
| 31-6284 | 1.25 | 31-6401 | .55 | 32-1209 | .90 | 32-1422 | 1.20 |
| 31-6285 | 1.25 | 31-6402 | .75 | 32-1220 | .70 | 32-1423 | .70 |
| 31-6286 | .40 | 31-6404 | .50 | 32-1221 | .70 | 32-1424 | 1.80 |
| 31-6287 | .45 | 31-6405 | 2.75 | 32-1222 | .60 | 32-1427 | 1.20 |
| 31-6288 | .30 | 31-6406 | .60 | 32-1223 | 1.00 | 32-1428 | 1.00 |
| 31-6289 | .40 | 31-6407 | .40 | 32-1236 | 1.80 | 32-1432 | .12 |
| 31-6290 | 2.25 | 31-6408 | .50 | 32-1237 | 1.80 | 32-1438 | .15 |
| 31-6292 | 2.50 | 31-6409 | .55 | 32-1255 | .70 | 32-1445 | .70 |
| 31-6293 | 2.50 | 31-6410 | .90 | 32-1256 | .70 | 32-1446 | .70 |
| 31-6296 | 2.75 | 31-6411 | .40 | 32-1257 | .90 | 32-1447 | .70 |
| 31-6297 | .25 | 31-6416 | .75 | 32-1258 | .80 | 32-1448 | 1.80 |
| 31-6298 | .60 | 31-6417 | 2.25 | 32-1260 | .60 | 32-1449 | 1.80 |
| 31-6299 | 2.00 | 31-6418 | .35 | 32-1261 | .90 | 32-1451 | 1.80 |
| 31-6302 | .75 | 31-6424 | 2.75 | 32-1262 | .90 | 32-1452 | 1.20 |
| 31-6303 | .60 | 31-6425 | .50 | 32-1263 | .80 | 32-1462 | 1.20 |
| 31-6305 | .45 | 31-6426 | .25 | 32-1264 | .80 | 32-1463 | 1.20 |
| 31-6306 | .60 | 31-6427 | .75 | 32-1268 | .30 | 32-1464 | .20 |
| 31-6307 | .40 | 31-6428 | .75 | 32-1270 | .70 | 32-1466 | .85 |
| 31-6308 | .25 | 31-6429 | 3.25 | 32-1271 | .90 | 32-1467 | 3.00 |
| 31-6309 | 2.75 | 31-6430 | .75 | 32-1272 | .90 | 32-1468 | 3.00 |
| 31-6310 | .45 | 31-6432 | .60 | 32-1273 | .90 | 32-1469 | 3.00 |
| 31-6311 | .50 | 31-6434 | .60 | 32-1274 | .80 | 32-1470 | 1.80 |
| 31-6312 | 2.75 | 31-6436 | .35 | 32-1281 | .40 | 32-1471 | 1.80 |
| 31-6313 | 2.00 | 31-6437 | .25 | 32-1286 | .35 | 32-1474 | .45 |
| 31-6315 | 2.50 | 31-6438 | .35 | 32-1288 | .80 | 32-1481 | .90 |
| 31-6316 | 2.50 | 31-6443 | 1.50 | 32-1289 | .90 | 32-1482 | 1.20 |
| 31-6317 | .45 | 31-6444 | .75 | 32-1290 | .70 | 32-1483 | 1.80 |
| 31-6318 | .25 | 31-6446 | 3.00 | 32-1291 | 1.15 | 32-1484 | 1.80 |
| 31-6320 | .25 | 31-6452 | .45 | 32-1293 | .45 | 32-1493 | .90 |
| 31-6321 | .50 | 31-6453 | .60 | 32-1304 | .80 | 32-1504 | 1.00 |
| 31-6322 | 1.50 | | | 32-1305 | .80 | 32-1512 | 1.20 |
| 31-6323 | .45 | 32-1000 | .70 | 32-1306 | 1.20 | 32-1514 | .30 |
| 31-6324 | 2.25 | 32-1001 | 1.00 | 32-1307 | 1.20 | 32-1518 | .70 |
| 31-6325 | 1.50 | 32-1002 | 1.00 | 32-1310 | 1.00 | 32-1519 | .70 |
| 31-6326 | .25 | 32-1003 | .80 | 32-1311 | .70 | 32-1530 | .20 |
| 31-6331 | .60 | 32-1004 | .90 | 32-1312 | .25 | 32-1534 | 2.50 |
| 31-6338 | .65 | 32-1005 | 1.00 | 32-1313 | 1.50 | 32-1535 | 1.20 |
| 31-6339 | .45 | 32-1029 | .25 | 32-1315 | .90 | 32-1536 | .70 |
| 31-6341 | .75 | 32-1030 | .80 | 32-1318 | .90 | 32-1537 | .70 |
| 31-6343 | .40 | 32-1031 | 1.10 | 32-1320 | 1.80 | 32-1538 | 1.80 |
| 31-6344 | .20 | 32-1047 | 1.50 | 32-1321 | 1.20 | 32-1539 | .45 |
| 31-6345 | .25 | 32-1048 | .90 | 32-1322 | 1.00 | 32-1540 | 1.20 |
| 31-6346 | .40 | 32-1062 | 1.00 | 32-1329 | 1.80 | 32-1544 | 2.05 |
| 31-6347 | .70 | 32-1063 | .75 | 32-1330 | .30 | 32-1548 | 1.60 |
| 31-6349 | 2.50 | 32-1069 | .90 | 32-1331 | .70 | 32-1549 | 1.20 |
| 31-6350 | .70 | 32-1070 | .60 | 32-1332 | .70 | 32-1550 | 1.80 |
| 31-6351 | .50 | 32-1083 | .45 | 32-1333 | .60 | 32-1551 | 1.80 |
| 31-6352 | .55 | 32-1085 | .70 | 32-1335 | .30 | 32-1556 | 1.60 |
| 31-6353 | .50 | 32-1086 | .90 | 32-1341 | 1.80 | 32-1557 | 1.20 |
| 31-6354 | 2.75 | 32-1087 | .65 | 32-1342 | 1.80 | 32-1558 | 2.40 |
| 31-6355 | .40 | 32-1108 | 1.30 | 32-1348 | .30 | 32-1561 | .15 |
| 31-6356 | .65 | 32-1111 | .70 | 32-1351 | 1.80 | 32-1563 | .50 |
| 31-6357 | .55 | 32-1115 | 1.20 | 32-1360 | 1.25 | 32-1568 | .35 |
| 31-6358 | .60 | 32-1116 | 1.20 | 32-1361 | .90 | 32-1604 | .15 |
| 31-6359 | .35 | 32-1117 | 1.60 | 32-1362 | 1.80 | 32-1607 | .35 |
| 31-6360 | .40 | 32-1118 | 1.50 | 32-1363 | 1.80 | 32-1608 | 1.20 |
| 31-6361 | 1.75 | 32-1125 | 1.00 | 32-1364 | 1.80 | 32-1614 | 1.80 |
| 31-6362 | .60 | 32-1126 | 1.00 | 32-1366 | 1.50 | 32-1618 | 1.20 |
| 31-6364 | .40 | 32-1133 | 6.00 | 32-1369 | 1.80 | 32-1619 | 1.20 |
| 31-6365 | .60 | 32-1146 | .90 | 32-1372 | .25 | 32-1620 | 1.00 |
| 31-6366 | 2.00 | 32-1152 | .70 | 32-1374 | .15 | 32-1621 | 1.80 |
| 31-6367 | .20 | 32-1153 | .90 | 32-1377 | .35 | 32-1622 | 3.40 |
| 31-6372 | 2.75 | 32-1155 | 1.50 | 32-1378 | 1.20 | 32-1630 | 3.60 |
| 31-6373 | .40 | 32-1157 | 1.60 | 32-1379 | 1.20 | 32-1631 | 1.80 |
| 31-6374 | .60 | 32-1158 | 1.20 | 32-1380 | 1.20 | 32-1632 | 1.80 |
| 31-6375 | .30 | 32-1159 | 1.20 | 32-1381 | 1.80 | 32-1634 | 1.80 |
| 31-6376 | 2.50 | 32-1160 | 1.00 | 32-1387 | .25 | 32-1635 | 3.60 |
| 31-6377 | 3.00 | 32-1168 | 1.70 | 32-1388 | .60 | 32-1637 | 3.00 |
| 31-6378 | .75 | 32-1170 | 1.20 | 32-1389 | .60 | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 32-1639 | 2.20 | 32-1970 | 1.20 | 32-2186 | .70 | 32-2483 | .50 |
| 32-1644 | .15 | 32-1973 | 1.20 | 32-2191 | 1.00 | 32-2485 | 1.60 |
| 32-1646 | 2.40 | 32-1975 | 1.20 | 32-2192 | .70 | 32-2494 | 1.60 |
| 32-1647 | 2.40 | 32-1976 | 2.00 | 32-2194 | 1.00 | 32-2495 | 1.60 |
| 32-1650 | 2.40 | 32-1978 | 2.40 | 32-2196 | 1.20 | 32-2496 | 1.00 |
| 32-1651 | 2.40 | 32-1984 | .90 | 32-2197 | .70 | 32-2509 | 1.00 |
| 32-1655 | 1.20 | 32-1985 | 1.20 | 32-2198 | .70 | 32-2516 | .70 |
| 32-1656 | .70 | 32-1986 | .70 | 32-2199 | .70 | 32-2517 | 1.60 |
| 32-1657 | .70 | 32-1990 | 1.20 | 32-2208 | 2.20 | 32-2524 | 1.60 |
| 32-1664 | 3.60 | 32-2003 | 1.60 | 32-2209 | 2.20 | 32-2535 | .15 |
| 32-1665 | 3.00 | 32-2005 | 1.80 | 32-2211 | 2.20 | 32-2537 | .30 |
| 32-1666 | 3.30 | 32-2006 | 1.80 | 32-2212 | 1.60 | 32-2554 | 2.20 |
| 32-1669 | 1.40 | 32-2018 | 1.80 | 32-2213 | .70 | 32-2556 | 2.20 |
| 32-1671 | 1.80 | 32-2019 | 1.80 | 32-2215 | 2.20 | 32-2557 | 1.25 |
| 32-1672 | 1.80 | 32-2020 | 1.80 | 32-2217 | 2.80 | 32-2558 | .70 |
| 32-1699 | 3.60 | 32-2021 | 1.80 | 32-2227 | 3.00 | 32-2559 | .50 |
| 32-1700 | .50 | 32-2026 | 1.80 | 32-2230 | 1.20 | 32-2560 | 1.25 |
| 32-1701 | .30 | 32-2027 | 1.80 | 32-2231 | 1.00 | 32-2565 | 2.40 |
| 32-1708 | 4.00 | 32-2028 | 3.00 | 32-2232 | 3.00 | 32-2573 | .70 |
| 32-1709 | 4.00 | 32-2029 | 3.00 | 32-2242 | .30 | 32-2575 | .70 |
| 32-1710 | 3.60 | 32-2030 | 1.60 | 32-2246 | .70 | 32-2576 | .70 |
| 32-1726 | 2.40 | 32-2031 | 1.80 | 32-2250 | .75 | 32-2580 | 2.20 |
| 32-1727 | 3.60 | 32-2034 | 1.80 | 32-2252 | 1.80 | 32-2582 | 2.20 |
| 32-1729 | .60 | 32-2038 | .15 | 32-2253 | 1.80 | 32-2583 | 1.60 |
| 32-1730 | 1.20 | 32-2039 | .35 | 32-2254 | 2.20 | 32-2586 | .70 |
| 32-1731 | .60 | 32-2041 | 1.60 | 32-2255 | 1.80 | 32-2588 | 1.00 |
| 32-1735 | 4.00 | 32-2043 | 1.60 | 32-2256 | 2.50 | 32-2592 | 1.60 |
| 32-1736 | 4.00 | 32-2045 | 1.60 | 32-2265 | 1.00 | 32-2596 | 1.00 |
| 32-1743 | 1.80 | 32-2046 | 1.20 | 32-2268 | 2.20 | 32-2597 | 1.25 |
| 32-1744 | 1.20 | 32-2047 | .70 | 32-2269 | .20 | 32-2598 | .70 |
| 32-1745 | .65 | 32-2048 | .70 | 32-2275 | 2.20 | 32-2600 | 2.20 |
| 32-1750 | 4.00 | 32-2049 | 1.80 | 32-2277 | 1.20 | 32-2602 | 2.20 |
| 32-1751 | 4.00 | 32-2050 | 1.80 | 32-2281 | 1.60 | 32-2604 | 2.20 |
| 32-1752 | 3.00 | 32-2055 | 2.25 | 32-2286 | 1.80 | 32-2605 | 1.60 |
| 32-1778 | .70 | 32-2056 | 1.60 | 32-2288 | 3.00 | 32-2608 | 1.15 |
| 32-1779 | .70 | 32-2059 | 3.60 | 32-2291 | 3.00 | 32-2610 | .80 |
| 32-1780 | 1.80 | 32-2063 | .20 | 32-2293 | 3.00 | 32-2611 | .80 |
| 32-1781 | 1.60 | 32-2069 | .40 | 32-2297 | 2.20 | 32-2612 | .80 |
| 32-1796 | .30 | 32-2090 | 1.20 | 32-2299 | 2.20 | 32-2613 | .90 |
| 32-1797 | .40 | 32-2093 | .50 | 32-2300 | 1.80 | 32-2614 | 1.15 |
| 32-1804 | .70 | 32-2101 | 2.20 | 32-2302 | 2.20 | 32-2615 | .70 |
| 32-1806 | 4.00 | 32-2103 | 2.20 | 32-2306 | .70 | 32-2616 | .70 |
| 32-1807 | 3.60 | 32-2105 | 1.00 | 32-2307 | 1.20 | 32-2617 | .70 |
| 32-1808 | 3.00 | 32-2106 | .70 | 32-2308 | .70 | 32-2618 | .70 |
| 32-1809 | 1.80 | 32-2108 | 1.60 | 32-2311 | 1.80 | 32-2619 | .70 |
| 32-1810 | 2.40 | 32-2109 | 1.20 | 32-2317 | .70 | 32-2620 | .70 |
| 32-1811 | 2.20 | 32-2110 | .70 | 32-2318 | 1.20 | 32-2621 | 1.00 |
| 32-1812 | 1.40 | 32-2111 | 1.00 | 32-2326 | 1.00 | 32-2622 | .50 |
| 32-1813 | 3.00 | 32-2112 | 2.00 | 32-2327 | 1.80 | 32-2623 | .50 |
| 32-1814 | 2.60 | 32-2113 | 1.60 | 32-2329 | 1.00 | 32-2624 | .70 |
| 32-1815 | 3.00 | 32-2119 | 1.20 | 32-2330 | .90 | 32-2625 | 1.60 |
| 32-1827 | 3.00 | 32-2120 | 1.00 | 32-2331 | 1.60 | 32-2626 | 1.60 |
| 32-1828 | 2.40 | 32-2121 | .70 | 32-2332 | .90 | 32-2627 | 1.60 |
| 32-1829 | 2.00 | 32-2126 | .70 | 32-2333 | 2.20 | 32-2628 | 1.60 |
| 32-1830 | 2.40 | 32-2127 | 1.60 | 32-2335 | 2.20 | 32-2629 | 1.00 |
| 32-1831 | 1.60 | 32-2128 | .70 | 32-2336 | 1.60 | 32-2630 | .70 |
| 32-1836 | 1.80 | 32-2131 | 2.40 | 32-2339 | 1.60 | 32-2631 | .50 |
| 32-1837 | 1.20 | 32-2139 | .55 | 32-2344 | .30 | 32-2632 | 1.00 |
| 32-1838 | 1.20 | 32-2140 | 1.60 | 32-2350 | 1.60 | 32-2633 | 1.25 |
| 32-1842 | .50 | 32-2141 | 1.60 | 32-2361 | 4.00 | 32-2634 | 1.80 |
| 32-1843 | 1.80 | 32-2142 | 1.20 | 32-2362 | 3.30 | 32-2636 | 3.00 |
| 32-1844 | 1.80 | 32-2143 | .70 | 32-2365 | 1.60 | 32-2643 | 2.50 |
| 32-1862 | .80 | 32-2144 | 1.60 | 32-2373 | 1.60 | 32-2645 | 2.50 |
| 32-1864 | 1.80 | 32-2146 | 1.25 | 32-2376 | 3.30 | 32-2654 | 1.25 |
| 32-1865 | 1.80 | 32-2147 | .70 | 32-2378 | 1.60 | 32-2657 | .15 |
| 32-1866 | 1.20 | 32-2149 | .70 | 32-2379 | .40 | 32-2660 | 2.20 |
| 32-1867 | 3.60 | 32-2150 | 1.20 | 32-2380 | .50 | 32-2661 | 4.00 |
| 32-1868 | 3.60 | 32-2151 | .70 | 32-2381 | 1.20 | 32-2664 | 2.20 |
| 32-1869 | 3.00 | 32-2152 | .70 | 32-2382 | 1.00 | 32-2666 | 2.20 |
| 32-1917 | 1.80 | 32-2159 | 1.60 | 32-2383 | .70 | 32-2667 | 1.60 |
| 32-1925 | 1.60 | 32-2167 | 2.20 | 32-2384 | 1.20 | 32-2668 | 1.25 |
| 32-1926 | 1.20 | 32-2168 | 1.00 | 32-2385 | 1.20 | 32-2671 | 1.80 |
| 32-1927 | .70 | 32-2169 | 1.80 | 32-2386 | .70 | 32-2672 | 2.20 |
| 32-1928 | 1.80 | 32-2170 | 2.20 | 32-2417 | .30 | 32-2677 | 2.75 |
| 32-1929 | 1.80 | 32-2171 | 1.80 | 32-2422 | .70 | 32-2680 | 1.00 |
| 32-1930 | .10 | 32-2172 | 2.20 | 32-2426 | .30 | 32-2681 | 1.25 |
| 32-1932 | .25 | 32-2175 | 1.20 | 32-2442 | 1.20 | 32-2682 | 1.50 |
| 32-1933 | .35 | 32-2176 | 1.20 | 32-2445 | 2.20 | 32-2687 | 2.50 |
| 32-1934 | 1.20 | 32-2177 | .70 | 32-2446 | 1.60 | 32-2700 | 1.60 |
| 32-1939 | 1.20 | 32-2178 | .70 | 32-2449 | 2.20 | 32-2703 | 2.20 |
| 32-1940 | 1.20 | 32-2179 | 1.20 | 32-2457 | 1.80 | 32-2718 | 1.15 |
| 32-1954 | .40 | 32-2182 | .70 | 32-2459 | 1.80 | 32-2719 | 1.00 |
| 32-1956 | .10 | 32-2183 | 1.20 | 32-2460 | 1.80 | 32-2720 | 1.15 |
| 32-1959 | .40 | 32-2184 | .70 | 32-2461 | 1.60 | 32-2727 | 2.50 |
| 32-1968 | .50 | 32-2185 | 1.20 | 32-2477 | .15 | 32-2728 | 2.50 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 32-2729 | .15 | 32-3036 | 1.00 | 32-3240 | .50 | 32-3447 | .75 |
| 32-2741 | 3.50 | 32-3037 | 1.00 | 32-3242 | .75 | 32-3448 | .65 |
| 32-2742 | 4.00 | 32-3039 | 1.25 | 32-3243 | 2.40 | 32-3449 | .55 |
| 32-2744 | .70 | 32-3040 | .75 | 32-3245 | 2.00 | 32-3450 | .55 |
| 32-2748 | .75 | 32-3041 | .50 | 32-3246 | 1.75 | 32-3451 | 1.50 |
| 32-2752 | 1.75 | 32-3042 | .50 | 32-3248 | 1.25 | 32-3452 | .75 |
| 32-2763 | 2.50 | 32-3046 | 1.00 | 32-3249 | .75 | 32-3453 | .75 |
| 32-2765 | 2.20 | 32-3051 | 1.15 | 32-3250 | 2.20 | 32-3454 | 1.50 |
| 32-2767 | 1.75 | 32-3052 | .75 | 32-3252 | .75 | 32-3455 | .75 |
| 32-2769 | 1.25 | 32-3053 | 1.00 | 32-3255 | .85 | 32-3456 | .75 |
| 32-2772 | 3.00 | 32-3054 | 1.25 | 32-3256 | .85 | 32-3457 | 1.75 |
| 32-2775 | 2.00 | 32-3055 | 1.00 | 32-3259 | 1.75 | 32-3458 | 1.00 |
| 32-2788 | .50 | 32-3056 | 1.75 | 32-3265 | 1.75 | 32-3459 | .50 |
| 32-2791 | 2.00 | 32-3074 | 2.20 | 32-3266 | 1.50 | 32-3460 | .40 |
| 32-2793 | 2.00 | 32-3075 | 2.20 | 32-3273 | 1.00 | 32-3461 | 1.25 |
| 32-2795 | 3.00 | 32-3076 | 2.20 | 32-3274 | .75 | 32-3462 | .40 |
| 32-2798 | .75 | 32-3078 | 2.25 | 32-3275 | 2.25 | 32-3463 | .40 |
| 32-2799 | .75 | 32-3079 | 2.75 | 32-3276 | .40 | 32-3464 | .50 |
| 32-2800 | 1.25 | 32-3080 | 1.75 | 32-3277 | .50 | 32-3465 | 2.20 |
| 32-2801 | 1.00 | 32-3081 | 1.80 | 32-3278 | .85 | 32-3466 | 1.50 |
| 32-2802 | .75 | 32-3082 | 1.00 | 32-3279 | 1.40 | 32-3467 | 1.50 |
| 32-2803 | .50 | 32-3083 | 1.00 | 32-3281 | 2.00 | 32-3468 | 1.30 |
| 32-2811 | .75 | 32-3084 | 1.50 | 32-3282 | 1.00 | 32-3469 | .75 |
| 32-2812 | .30 | 32-3085 | 1.25 | 32-3283 | .75 | 32-3470 | .75 |
| 32-2821 | 1.15 | 32-3086 | 2.25 | 32-3287 | .75 | 32-3471 | .60 |
| 32-2822 | 1.15 | 32-3087 | 2.25 | 32-3288 | 1.00 | 32-3472 | 2.00 |
| 32-2823 | 1.25 | 32-3088 | 2.25 | 32-3289 | 1.00 | 32-3473 | 1.50 |
| 32-2828 | .70 | 32-3089 | 4.00 | 32-3290 | .75 | 32-3475 | 1.25 |
| 32-2829 | .70 | 32-3091 | 7.50 | 32-3291 | .75 | 32-3476 | .50 |
| 32-2830 | 1.00 | 32-3092 | 1.25 | 32-3292 | .45 | 32-3477 | .50 |
| 32-2833 | 1.50 | 32-3094 | .75 | 32-3293 | .40 | 32-3478 | 1.25 |
| 32-2836 | .55 | 32-3097 | 4.00 | 32-3294 | .60 | 32-3479 | 1.50 |
| 32-2841 | 2.20 | 32-3099 | 1.25 | 32-3303 | 1.00 | 32-3480 | .75 |
| 32-2852 | 2.20 | 32-3103 | 2.25 | 32-3304 | 1.40 | 32-3481 | .40 |
| 32-2854 | 2.20 | 32-3118 | .85 | 32-3321 | 1.00 | 32-3482 | 2.00 |
| 32-2855 | 1.50 | 32-3120 | 2.00 | 32-3327 | 1.40 | 32-3483 | 1.50 |
| 32-2859 | 2.20 | 32-3121 | 2.00 | 32-3361 | 1.60 | 32-3484 | 1.75 |
| 32-2860 | 1.00 | 32-3122 | 1.00 | 32-3367 | .50 | 32-3485 | 1.50 |
| 32-2863 | 1.00 | 32-3124 | .50 | 32-3372 | .25 | 32-3487 | 1.25 |
| 32-2866 | .15 | 32-3129 | 2.20 | 32-3373 | 1.00 | 32-3489 | 1.50 |
| 32-2885 | 1.25 | 32-3149 | 1.50 | 32-3374 | .75 | 32-3490 | 1.15 |
| 32-2891 | 1.30 | 32-3150 | 1.25 | 32-3375 | 1.00 | 32-3491 | .50 |
| 32-2894 | .50 | 32-3151 | .70 | 32-3376 | .90 | 32-3492 | 1.50 |
| 32-2895 | 1.50 | 32-3152 | .50 | 32-3377 | .80 | 32-3493 | 2.00 |
| 32-2897 | 1.25 | 32-3161 | 1.00 | 32-3378 | .40 | 32-3494 | 1.65 |
| 32-2900 | 2.20 | 32-3162 | 1.25 | 32-3382 | 1.75 | 32-3495 | 1.65 |
| 32-2902 | 1.00 | 32-3163 | 1.00 | 32-3383 | 1.75 | 32-3496 | 1.25 |
| 32-2908 | 1.80 | 32-3164 | 1.25 | 32-3384 | 2.25 | 32-3497 | .50 |
| 32-2911 | .25 | 32-3166 | 1.10 | 32-3385 | .50 | 32-3498 | .40 |
| 32-2912 | 1.25 | 32-3167 | .75 | 32-3390 | 1.50 | 32-3499 | 1.25 |
| 32-2914 | 1.50 | 32-3168 | 1.50 | 32-3391 | 1.75 | 32-3500 | .75 |
| 32-2917 | 2.50 | 32-3169 | 1.50 | 32-3394 | .75 | 32-3504 | .75 |
| 32-2918 | 3.00 | 32-3170 | 1.25 | 32-3395 | 1.00 | 32-3505 | 1.25 |
| 32-2919 | .50 | 32-3176 | 2.00 | 32-3397 | .35 | 32-3506 | .75 |
| 32-2920 | 1.60 | 32-3177 | 1.50 | 32-3398 | 1.50 | 32-3507 | 1.75 |
| 32-2922 | .75 | 32-3178 | 1.50 | 32-3399 | 1.50 | 32-3508 | 1.65 |
| 32-2925 | .30 | 32-3180 | 2.00 | 32-3401 | .40 | 32-3509 | 1.50 |
| 32-2936 | 1.50 | 32-3181 | 1.50 | 32-3402 | 3.00 | 32-3510 | 1.50 |
| 32-2941 | 1.75 | 32-3182 | .50 | 32-3404 | 1.00 | 32-3514 | 1.25 |
| 32-2942 | 1.75 | 32-3183 | 1.40 | 32-3415 | .40 | 32-3515 | .40 |
| 32-2943 | 1.75 | 32-3184 | .60 | 32-3416 | .35 | 32-3516 | .60 |
| 32-2944 | 1.50 | 32-3192 | 1.00 | 32-3417 | .65 | 32-3517 | .35 |
| 32-2945 | 1.50 | 32-3194 | .45 | 32-3418 | .50 | 32-3518 | .55 |
| 32-2946 | 1.50 | 32-3195 | 1.00 | 32-3419 | .50 | 32-3519 | 1.25 |
| 32-2947 | .70 | 32-3198 | 2.00 | 32-3420 | .50 | 32-3520 | .35 |
| 32-2980 | 1.00 | 32-3199 | 1.50 | 32-3421 | .60 | 32-3521 | .50 |
| 32-2986 | .70 | 32-3210 | 1.65 | 32-3422 | 1.00 | 32-3522 | .40 |
| 32-2987 | .80 | 32-3211 | 2.00 | 32-3423 | .60 | 32-3523 | .25 |
| 32-2988 | 1.25 | 32-3212 | .75 | 32-3424 | .50 | 32-3524 | 1.75 |
| 32-2994 | 2.20 | 32-3214 | .75 | 32-3425 | .50 | 32-3525 | 1.75 |
| 32-2995 | 2.20 | 32-3217 | .50 | 32-3426 | 1.25 | 32-3527 | .60 |
| 32-3003 | .30 | 32-3218 | .75 | 32-3427 | 1.25 | 32-3530 | 1.25 |
| 32-3005 | 1.20 | 32-3219 | 1.00 | 32-3428 | 4.25 | 32-3531 | 1.25 |
| 32-3006 | 1.20 | 32-3220 | 1.00 | 32-3429 | 2.20 | 32-3534 | 1.75 |
| 32-3013 | 2.20 | 32-3222 | 2.20 | 32-3430 | 2.40 | 32-3536 | 1.25 |
| 32-3014 | 2.20 | 32-3223 | 1.75 | 32-3431 | .40 | 32-3537 | 1.25 |
| 32-3018 | 2.20 | 32-3226 | .85 | 32-3432 | 1.00 | 32-3538 | 1.50 |
| 32-3019 | .85 | 32-3227 | .50 | 32-3434 | 1.25 | 32-3539 | .75 |
| 32-3021 | .85 | 32-3230 | 1.10 | 32-3435 | .75 | 32-3540 | 1.60 |
| 32-3025 | .75 | 32-3231 | .70 | 32-3441 | .50 | 32-3543 | 1.25 |
| 32-3026 | 1.50 | 32-3232 | 1.00 | 32-3442 | .50 | 32-3544 | .75 |
| 32-3027 | 1.00 | 32-3233 | 1.60 | 32-3443 | 2.75 | 32-3545 | .90 |
| 32-3028 | 1.10 | 22-3234 | .65 | 32-3444 | 2.00 | 32-3546 | .70 |
| 32-3030 | 2.20 | 32-3237 | 1.60 | 32-3445 | 1.50 | 32-3546 | .70 |
| 32-3031 | 7.50 | 32-3238 | 1.75 | 32-3446 | 1.00 | 32-3547 | .90 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 32-3548 | .35 | 32-3679 | .65 | 32-7019 | 1.25 | 32-7283 | 7.00 |
| 32-3549 | 1.75 | 32-3680 | .65 | 32-7020 | .90 | 32-7284 | 10.75 |
| 32-3550 | 1.75 | 32-3682 | .60 | 32-7022 | 2.00 | 32-7285 | 8.75 |
| 32-3551 | .60 | 32-3683 | .60 | 32-7026 | 1.25 | 32-7286 | 1.60 |
| 32-3552 | .40 | 32-3685 | .60 | 32-7030 | 2.25 | 32-7291 | 7.00 |
| 32-3553 | .40 | 32-3686 | .60 | 32-7036 | .90 | 32-7292 | 9.25 |
| 32-3557 | 1.25 | 32-3688 | 2.00 | 32-7038 | 1.15 | 32-7296 | 1.50 |
| 32-3558 | .40 | 32-3692 | .55 | 32-7039 | 1.50 | 32-7297 | 2.00 |
| 32-3559 | .40 | 32-3695 | .70 | 32-7041 | .95 | 32-7307 | 5.25 |
| 32-3560 | 1.50 | 32-3697 | 2.00 | 32-7042 | 1.75 | 32-7309 | 1.30 |
| 32-3561 | 1.50 | 32-3698 | .50 | 32-7045 | 2.25 | 32-7313 | 8.00 |
| 32-3562 | .60 | 32-3704 | 1.75 | 32-7051 | 1.50 | 32-7315 | 2.40 |
| 32-3563 | 3.50 | 32-3705 | 1.25 | 32-7052 | 2.00 | 32-7317 | 1.90 |
| 32-3566 | 1.75 | 32-3706 | 1.75 | 32-7056 | 2.20 | 32-7324 | 8.50 |
| 32-3567 | .50 | 32-3708 | 1.50 | 32-7057 | 3.50 | 32-7325 | 8.50 |
| 32-3568 | .75 | 32-3709 | 1.00 | 32-7058 | 8.00 | 32-7326 | 4.25 |
| 32-3569 | 1.50 | 32-3710 | 1.75 | 32-7059 | 7.50 | 32-7347 | 1.20 |
| 32-3571 | 1.25 | 32-3711 | 2.00 | 32-7060 | 6.30 | 32-7351 | .90 |
| 32-3572 | .45 | 32-3712 | 1.25 | 32-7064 | 3.25 | 32-7352 | 3.00 |
| 32-3573 | 1.25 | 32-3713 | 1.60 | 32-7065 | 1.05 | 32-7355 | 2.20 |
| 32-3574 | .50 | 32-3714 | 2.00 | 32-7069 | 8.50 | 32-7356 | 1.75 |
| 32-3575 | .50 | 32-3715 | 1.00 | 32-7070 | 2.40 | 32-7365 | 8.00 |
| 32-3576 | .50 | 32-3716 | .25 | 32-7074 | 4.25 | 32-7368 | .60 |
| 32-3577 | .90 | 32-3717 | 1.75 | 32-7078 | 1.25 | 32-7370 | 8.25 |
| 32-3578 | .90 | 32-3718 | .30 | 32-7080 | 8.00 | 32-7371 | 6.75 |
| 32-3579 | 1.40 | 32-3719 | .50 | 32-7081 | 7.65 | 32-7372 | 2.50 |
| 32-3580 | .50 | 32-3720 | 1.10 | 32-7082 | 5.75 | 32-7381 | 4.00 |
| 32-3581 | .60 | 32-3722 | 2.00 | 32-7084 | 4.50 | 32-7382 | 4.25 |
| 32-3582 | 1.25 | 32-3723 | .85 | 32-7098 | 2.40 | 32-7383 | 4.50 |
| 32-3583 | 2.00 | 32-3724 | 2.00 | 32-7102 | 1.50 | 32-7384 | 5.50 |
| 32-3584 | 2.00 | 32-3725 | .25 | 32-7104 | 1.15 | 32-7385 | 7.75 |
| 32-3586 | .85 | 32-3726 | 2.00 | 32-7110 | 2.70 | 32-7386 | 5.75 |
| 32-3588 | 1.50 | 32-3727 | 1.25 | 32-7111 | 6.75 | 32-7395 | 1.10 |
| 32-3590 | .60 | 32-3728 | 1.00 | 32-7112 | 8.15 | 32-7402 | 7.50 |
| 32-3595 | .75 | 32-3729 | .40 | 32-7113 | 5.25 | 32-7403 | 9.00 |
| 32-3597 | .35 | 32-3730 | .60 | 32-7114 | 3.00 | 32-7404 | 7.50 |
| 32-3600 | .75 | 32-3731 | 2.25 | 32-7115 | 1.80 | 32-7407 | 9.00 |
| 32-3602 | 1.25 | 32-3732 | .65 | 32-7118 | 2.00 | 32-7418 | 4.75 |
| 32-3603 | 1.50 | 32-3733 | 1.60 | 32-7129 | 2.85 | 32-7423 | 2.10 |
| 32-3604 | 1.50 | 32-3734 | 2.00 | 32-7131 | 2.50 | 32-7431 | 7.50 |
| 32-3613 | .60 | 32-3737 | 2.25 | 32-7137 | 4.00 | 32-7432 | 12.00 |
| 32-3614 | 1.50 | 32-3742 | 2.20 | 32-7138 | 5.25 | 32-7433 | 8.75 |
| 32-3615 | .50 | 32-3743 | 1.25 | 32-7139 | 4.00 | 32-7440 | 6.00 |
| 32-3616 | 2.00 | 32-3744 | 1.50 | 32-7153 | 10.50 | 32-7441 | 8.75 |
| 32-3617 | 1.25 | 32-3750 | 2.00 | 32-7170 | 4.50 | 32-7446 | 1.75 |
| 32-3618 | 1.50 | 32-3751 | .25 | 32-7171 | 6.75 | 32-7447 | 1.50 |
| 32-3619 | 1.00 | 32-3755 | 2.00 | 32-7178 | 1.60 | 32-7450 | 3.00 |
| 32-3620 | 2.00 | 32-3756 | .80 | 32-7180 | 3.60 | 32-7452 | .90 |
| 32-3621 | 1.50 | 32-3757 | .50 | 32-7191 | 2.70 | 32-7453 | 1.50 |
| 32-3622 | 2.00 | 32-3758 | .40 | 32-7200 | 3.00 | 32-7454 | 1.50 |
| 32-3623 | 2.00 | 32-3760 | .85 | 32-7203 | 3.00 | 32-7455 | 8.00 |
| 32-3625 | 1.50 | 32-3762 | 2.00 | 32-7204 | 3.00 | 32-7456 | 13.75 |
| 32-3626 | 1.10 | 32-3763 | .25 | 32-7205 | 1.40 | 32-7461 | 2.00 |
| 32-3628 | 1.60 | 32-3765 | .50 | 32-7206 | 1.80 | 32-7462 | 6.00 |
| 32-3629 | 1.25 | 32-3766 | .40 | 32-7211 | 2.25 | 32-7471 | 2.10 |
| 32-3631 | 1.50 | 32-3767 | .75 | 32-7213 | 2.00 | 32-7472 | 1.50 |
| 32-3632 | .40 | 32-3768 | .40 | 32-7214 | 1.00 | 32-7473 | 1.75 |
| 32-3633 | .50 | 32-3771 | .55 | 32-7215 | .90 | 32-7476 | 1.25 |
| 32-3634 | .50 | 32-3772 | 2.25 | 32-7216 | 2.60 | 32-7478 | 1.50 |
| 32-3635 | .75 | 32-3773 | 2.00 | 32-7217 | .07 | 32-7480 | 1.50 |
| 32-3636 | .40 | 32-3774 | 1.25 | 32-7218 | 4.95 | 32-7482 | 2.50 |
| 32-3637 | .40 | 32-3775 | 1.50 | 32-7223 | 1.50 | 32-7484 | 1.90 |
| 32-3638 | 2.00 | 32-3787 | 4.00 | 32-7226 | 4.25 | 32-7485 | 1.10 |
| 32-3640 | 1.50 | 32-3788 | 2.50 | 32-7227 | 6.75 | 32-7488 | 2.50 |
| 32-3641 | .55 | 32-3789 | 4.00 | 32-7228 | 4.75 | 32-7489 | 1.10 |
| 32-3642 | .60 | 32-3791 | .75 | 32-7229 | 5.25 | 32-7491 | .95 |
| 32-3644 | 1.60 | 32-3792 | 1.50 | 32-7230 | 8.25 | 32-7493 | 13.00 |
| 32-3645 | .50 | 32-3794 | 4.00 | 32-7232 | 2.40 | 32-7495 | 1.05 |
| 32-3646 | 1.25 | 32-3796 | 4.00 | 32-7233 | 1.00 | 32-7503 | 1.65 |
| 32-3647 | 2.00 | 32-3797 | 1.50 | 32-7234 | 5.50 | 32-7504 | 2.75 |
| 32-3649 | 1.00 | 32-3798 | 1.15 | 32-7235 | 8.00 | 32-7507 | 1.00 |
| 32-3651 | .85 | 32-3811 | 2.00 | 32-7236 | 5.85 | 32-7508 | 1.50 |
| 32-3652 | 1.00 | 32-3812 | .60 | 32-7243 | 1.10 | 32-7527 | 1.50 |
| 32-3653 | 1.75 | 32-3856 | 1.10 | 32-7245 | 1.20 | 32-7528 | 1.35 |
| 32-3654 | 2.00 | 32-3857 | 2.00 | 32-7247 | 2.00 | 32-7532 | 4.25 |
| 32-3655 | 1.25 | 32-3858 | .30 | 32-7249 | 2.75 | 32-7543 | 1.35 |
| 32-3656 | .85 | 32-3859 | 1.50 | 32-7253 | 2.50 | 32-7544 | .95 |
| 32-3658 | .60 | 32-3860 | 1.75 | 32-7254 | 1.00 | 32-7545 | .90 |
| 32-3661 | 1.00 | 32-7000 | .70 | 32-7256 | 1.80 | 32-7546 | 3.60 |
| 32-3662 | .60 | 32-7001 | .80 | 32-7258 | 7.50 | 32-7547 | 3.00 |
| 32-3663 | .70 | 32-7005 | 1.40 | 32-7259 | 11.25 | 32-7550 | 2.75 |
| 32-3673 | 1.40 | 32-7010 | 5.75 | 32-7260 | 8.75 | 32-7551 | 1.50 |
| 32-3674 | 1.60 | 32-7012 | 3.00 | 32-7261 | .85 | 32-7552 | 3.25 |
| 32-3675 | 1.50 | 32-7014 | 1.25 | 32-7267 | 1.00 | 32-7553 | 5.75 |
| 32-3678 | .65 | 32-7018 | 1.50 | 32-7275 | 1.85 | 32-7554 | 4.00 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|-----------|------------|
| 32-7558 | 1.60 | 32-7829 | 1.60 | 32-8009 | 1.40 | 32-8144 | 1.25 |
| 32-7559 | 1.60 | 32-7831 | 1.25 | 32-8010 | 4.75 | 32-8145 | 1.25 |
| 32-7560 | 1.60 | 32-7833 | 4.00 | 32-8012 | 7.75 | 32-8147 | 5.50 |
| 32-7562 | 1.40 | 32-7835 | 5.75 | 32-8013 | 9.50 | 32-8148 | 5.50 |
| 32-7566 | 1.10 | 32-7837 | 5.50 | 32-8014 | 4.75 | 32-8149 | 5.75 |
| 32-7567 | 1.00 | 32-7839 | 7.75 | 32-8015 | 2.75 | 32-8150 | 5.50 |
| 32-7568 | .95 | 32-7842 | 2.25 | 32-8016 | 2.25 | 32-8151 | 9.00 |
| 32-7569 | 1.30 | 32-7849 | 3.00 | 32-8017 | 11.00 | 32-8152 | 1.25 |
| 32-7572 | 1.00 | 32-7852 | 4.00 | 32-8018 | 1.50 | 32-8155 | 1.75 |
| 32-7574 | 3.00 | 32-7853 | 6.50 | 32-8019 | 2.25 | 32-8156 | 5.00 |
| 32-7583 | 4.50 | 32-7862 | 1.45 | 32-8020 | 2.25 | 32-8157 | 4.75 |
| 32-7584 | 6.50 | 32-7863 | 1.60 | 32-8022 | 9.50 | 32-8158 | 1.15 |
| 32-7585 | 6.50 | 32-7864 | 1.85 | 32-8023 | 3.75 | 32-8159 | 1.25 |
| 32-7597 | 5.25 | 32-7865 | 2.50 | 32-8026 | 2.00 | 32-8162 | 1.25 |
| 32-7598 | 8.00 | 32-7866 | 1.85 | 32-8027 | 2.50 | 32-8163 | 3.50 |
| 32-7599 | 7.50 | 32-7867 | 4.75 | 32-8029 | 1.60 | 32-8164 | 1.25 |
| 32-7606 | 6.25 | 32-7868 | 1.25 | 32-8031 | 13.50 | 32-8165 | 3.50 |
| 32-7607 | 9.00 | 32-7869 | 7.15 | 32-8033 | 1.40 | 32-8166 | 4.00 |
| 32-7608 | 8.00 | 32-7870 | 12.50 | 32-8036 | 1.40 | 32-8168 | 1.00 |
| 32-7615 | 7.00 | 32-7874 | 1.15 | 32-8040 | .95 | 32-8169 | 1.00 |
| 32-7617 | 9.00 | 32-7876 | 3.75 | 32-8042 | 8.00 | 32-8170 | 1.75 |
| 32-7626 | 4.25 | 32-7885 | 8.50 | 32-8043 | 2.00 | 32-8172 | 1.00 |
| 32-7627 | 5.50 | 32-7886 | 11.75 | 32-8044 | 1.00 | 32-8173 | 1.00 |
| 32-7628 | 5.25 | 32-7887 | 11.00 | 32-8046 | 1.25 | 32-8174 | 1.50 |
| 32-7634 | 1.50 | 32-7888 | 8.75 | 32-8047 | 1.00 | 32-8177 | 4.00 |
| 32-7637 | 2.00 | 32-7889 | 11.75 | 32-8049 | 3.75 | 32-8180 | 1.00 |
| 32-7638 | 1.50 | 32-7890 | 10.00 | 32-8050 | 3.00 | 32-8182 | 1.25 |
| 32-7639 | 1.60 | 32-7904 | 1.75 | 32-8051 | 1.00 | 32-8183 | 3.75 |
| 32-7640 | 6.50 | 32-7905 | 2.00 | 32-8052 | 3.50 | 32-8187 | 4.00 |
| 32-7641 | 10.00 | 32-7909 | 1.75 | 32-8053 | 1.25 | 32-9007 | 1.25 |
| 32-7642 | 8.50 | 32-7910 | 1.25 | 32-8055 | 3.50 | 32-9008 | 1.50 |
| 32-7651 | 10.00 | 32-7911 | 3.00 | 32-8056 | 1.00 | 32-9013 | 1.00 |
| 32-7662 | 1.60 | 32-7914 | 1.85 | 32-8057 | 1.25 | 32-9024 | 3.20 |
| 32-7663 | 1.00 | 32-7915 | 1.60 | 32-8058 | 1.75 | 32-9026 | 6.35 |
| 32-7667 | 1.60 | 32-7925 | 3.75 | 32-8059 | 5.25 | 32-9035 | 1.15 |
| 32-7668 | 1.20 | 32-7926 | 1.40 | 32-8062 | 1.40 | 32-9046 | 1.85 |
| 32-7671 | 2.50 | 32-7927 | 1.80 | 32-8063 | 1.00 | 32-9051 | 1.10 |
| 32-7681 | 1.75 | 32-7928 | 1.50 | 32-8064 | 3.00 | 32-9055 | 3.30 |
| 32-7682 | 2.75 | 32-7934 | 3.60 | 32-8065 | 3.50 | 32-9076 | 1.85 |
| 32-7683 | 2.50 | 32-7935 | 8.50 | 32-8066 | 1.60 | 32-9077 | 1.90 |
| 32-7684 | 1.60 | 32-7936 | 1.75 | 32-8068 | 4.00 | 32-9078 | 1.95 |
| 32-7685 | 2.00 | 32-7942 | 1.70 | 32-8069 | 5.25 | 32-9079 | 2.45 |
| 32-7688 | 7.50 | 32-7943 | 1.00 | 32-8070 | 1.60 | 32-9080 | 2.20 |
| 32-7689 | 12.50 | 32-7944 | 3.00 | 32-8071 | 1.25 | 32-9081 | 2.70 |
| 32-7690 | 10.00 | 32-7946 | 1.25 | 32-8072 | 1.75 | 32-9082 | 3.00 |
| 32-7699 | 7.50 | 32-7949 | 3.50 | 32-8073 | 1.25 | 32-9087 | 2.00 |
| 32-7700 | 12.00 | 32-7950 | 3.50 | 32-8074 | 5.50 | 32-9100 | .55 |
| 32-7701 | 10.00 | 32-7951 | 3.25 | 32-8075 | 5.00 | 32-9236 | .80 |
| 32-7710 | 1.25 | 32-7954 | 4.50 | 32-8076 | 5.50 | 32-9263 | 1.25 |
| 32-7717 | 2.00 | 32-7955 | 1.00 | 32-8080 | 9.00 | 32-9473 | 1.00 |
| 32-7720 | 2.60 | 32-7956 | 1.50 | 32-8086 | 5.50 | 32-9484 | 1.00 |
| 32-7721 | 1.35 | 32-7957 | 1.10 | 32-8095 | 1.25 | 32-9493 | 2.00 |
| 32-7722 | 1.20 | 32-7958 | 3.25 | 32-8096 | 1.25 | 32-9588 | 1.50 |
| 32-7724 | 1.75 | 32-7959 | 1.25 | 32-8100 | 1.25 | | |
| 32-7725 | 3.20 | 32-7960 | 1.00 | 32-8106 | 1.25 | 33-1015 | .30 |
| 32-7727 | 1.70 | 32-7961 | 1.15 | 32-8107 | 1.10 | 33-1017 | .30 |
| 32-7728 | 6.50 | 32-7962 | 3.20 | 32-8108 | 4.50 | 33-1101 | .30 |
| 32-7729 | 12.00 | 32-7967 | 2.00 | 32-8110 | 2.00 | 33-1102 | .30 |
| 32-7730 | 9.00 | 32-7968 | 2.00 | 32-8111 | 1.75 | 33-1103 | .30 |
| 32-7751 | 2.00 | 32-7974 | 2.75 | 32-8112 | 2.25 | 33-1113 | .30 |
| 32-7753 | 1.70 | 32-7975 | 5.00 | 32-8113 | 1.75 | 33-1192 | .30 |
| 32-7754 | 1.50 | 32-7976 | 2.75 | 32-8114 | 1.25 | 33-1193 | .30 |
| 32-7758 | 1.50 | 32-7977 | 3.25 | 32-8115 | 6.00 | 33-1195 | .30 |
| 32-7765 | 1.50 | 32-7978 | 1.00 | 32-8116 | 1.00 | 33-1196 | .30 |
| 32-7778 | 1.60 | 32-7979 | 2.75 | 32-8117 | 3.50 | 33-1211 | .20 |
| 32-7779 | 1.50 | 32-7980 | 1.00 | 32-8118 | 5.50 | 33-1212 | .20 |
| 32-7780 | 3.60 | 32-7981 | 1.80 | 32-8120 | 1.25 | 33-1213 | .20 |
| 32-7781 | 6.00 | 32-7984 | 1.40 | 32-8121 | 4.00 | 33-1214 | .20 |
| 32-7782 | 4.00 | 32-7986 | 1.00 | 32-8122 | 3.75 | 33-1218 | .20 |
| 32-7786 | 1.50 | 32-7988 | 1.50 | 32-8125 | 1.00 | 33-1219 | .20 |
| 32-7788 | 2.75 | 32-7989 | 4.50 | 32-8127 | 1.15 | 33-1220 | .20 |
| 32-7789 | 5.85 | 32-7990 | 1.50 | 32-8128 | 2.00 | 33-1221 | .20 |
| 32-7792 | 8.75 | 32-7993 | 1.50 | 32-8129 | 4.50 | 33-1223 | .20 |
| 32-7811 | 1.00 | 32-7994 | 4.00 | 32-8132 | 1.00 | 33-1259 | .20 |
| 32-7815 | 1.25 | 32-7995 | 1.40 | 32-8133 | 4.00 | 33-1260 | .20 |
| 32-7816 | 1.65 | 32-7996 | 2.25 | 32-8134 | 1.25 | 33-1261 | .20 |
| 32-7817 | 1.35 | 32-7997 | 2.00 | 32-8135 | 2.25 | 33-1264 | .17 |
| 32-7818 | 1.45 | 32-7998 | 5.00 | 32-8136 | 5.50 | 33-1266 | .17 |
| 32-7819 | 3.00 | 32-7999 | 6.50 | 32-8137 | 1.00 | 33-1267 | .17 |
| 32-7820 | 3.00 | 32-8000 | 1.25 | 32-8138 | 10.50 | 33-1270 | .20 |
| 32-7821 | 2.60 | 32-8001 | 7.00 | 32-8139 | 2.00 | 33-1273 | .17 |
| 32-7822 | 1.00 | 32-8002 | 2.25 | 32-8140 | 1.25 | 33-1283-1 | .25 |
| 32-7826 | 3.00 | 32-8005 | 3.75 | 32-8142 | 10.00 | 33-3010 | .20 |
| 32-7827 | 1.00 | 32-8006 | 4.50 | 32-8143 | 4.25 | 33-3011 | .30 |
| 32-7828 | 2.50 | 32-8007 | 7.00 | | 4.25 | 33-3012 | .30 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 33-3015 | 2.75 | 33-3118 | 1.05 | 33-3252 | .50 | 33-3411 | .45 |
| 33-3016 | .17 | 33-3119 | .20 | 33-3253 | .50 | 33-3412 | .25 |
| 33-3017 | .17 | 33-3120 | .20 | 33-3254 | .50 | 33-3413 | .45 |
| 33-3019 | .30 | 33-3123 | .20 | 33-3255 | .50 | 33-3414 | 1.25 |
| 33-3020 | .35 | 33-3124 | .20 | 33-3256 | .50 | 33-3415 | .35 |
| 33-3021 | .30 | 33-3125 | .20 | 33-3258 | .50 | 33-3416 | .25 |
| 33-3022 | .17 | 33-3126 | .20 | 33-3259 | .50 | 33-5000 | 1.00 |
| 33-3023 | .20 | 33-3127 | .20 | 33-3260 | .50 | 33-5002 | 1.00 |
| 33-3025 | .30 | 33-3128 | .25 | 33-3261 | .50 | 33-5004 | 1.45 |
| 33-3027 | .20 | 33-3130 | .30 | 33-3262 | .50 | 33-5005 | 1.45 |
| 33-3031 | .20 | 33-3131 | .25 | 33-3263 | .50 | 33-5006 | 1.45 |
| 33-3033 | .30 | 33-3132 | .20 | 33-3264 | .50 | 33-5007 | 1.00 |
| 33-3034 | .20 | 33-3135 | .30 | 33-3265 | .50 | 33-5009 | 1.70 |
| 33-3035 | .30 | 33-3136 | .40 | 33-3266 | .50 | 33-5010 | 1.45 |
| 33-3037 | .20 | 33-3138 | .45 | 33-3267 | .50 | 33-5011 | 1.45 |
| 33-3040 | .20 | 33-3139 | .17 | 33-3268 | .50 | 33-5013 | 1.45 |
| 33-3041 | .20 | 33-3140 | .17 | 33-3269 | .50 | 33-5014 | 1.45 |
| 33-3042 | .20 | 33-3142 | 3.00 | 33-3272 | .20 | 33-5015 | 1.00 |
| 33-3043 | .20 | 33-3143 | .40 | 33-3276 | .30 | 33-5016 | 1.70 |
| 33-3045 | .20 | 33-3144 | .40 | 33-3278 | .30 | 33-5020 | 1.45 |
| 33-3046 | .20 | 33-3145 | .35 | 33-3279 | .55 | 33-5021 | 1.00 |
| 33-3047 | .20 | 33-3147 | .40 | 33-3280 | .30 | 33-5023 | 1.45 |
| 33-3048 | .20 | 33-3148 | .25 | 33-3281 | .60 | 33-5025 | 1.45 |
| 33-3049 | .50 | 33-3150 | .40 | 33-3282 | .60 | 33-5026 | 1.45 |
| 33-3051 | .50 | 33-3158 | .45 | 33-3284 | .30 | 33-5027 | 1.45 |
| 33-3052 | .50 | 33-3159 | .35 | 33-3289 | .50 | 33-5028 | 1.45 |
| 33-3053 | .50 | 33-3161 | 2.35 | 33-3290 | .60 | 33-5029 | 1.45 |
| 33-3054 | .50 | 33-3163 | .17 | 33-3291 | .40 | 33-5030 | 1.45 |
| 33-3055 | .50 | 33-3165 | .17 | 33-3292 | .60 | 33-5031 | 1.45 |
| 33-3057 | .50 | 33-3166 | .50 | 33-3294 | 1.00 | 33-5032 | 1.45 |
| 33-3058 | .50 | 33-3167 | .50 | 33-3296 | .45 | 33-5033 | 1.45 |
| 33-3059 | .50 | 33-3168 | .50 | 33-3297 | .17 | 33-5034 | 1.45 |
| 33-3060 | .50 | 33-3169 | .50 | 33-3298 | .17 | 33-5035 | 1.45 |
| 33-3061 | .55 | 33-3170 | .50 | 33-3301 | .60 | 33-5036 | 1.45 |
| 33-3062 | .55 | 33-3172 | .55 | 33-3302 | 1.00 | 33-5037 | 1.45 |
| 33-3063 | .55 | 33-3173 | .55 | 33-3311 | .60 | 33-5038 | 1.45 |
| 33-3064 | .55 | 33-3176 | .75 | 33-3313 | .60 | 33-5039 | 1.45 |
| 33-3065 | .55 | 33-3177 | .90 | 33-3314 | .45 | 33-5040 | 1.45 |
| 33-3066 | .55 | 33-3178 | .90 | 33-3315 | .40 | 33-5041 | 1.00 |
| 33-3067 | .55 | 33-3179 | .90 | 33-3316 | .35 | 33-5042 | 1.00 |
| 33-3068 | .65 | 33-3180 | 1.00 | 33-3317 | .35 | 33-5043 | 1.00 |
| 33-3071 | .50 | 33-3181 | 1.05 | 33-3318 | .70 | 33-5044 | 1.00 |
| 33-3072 | .50 | 33-3182 | .65 | 33-3319 | .50 | 33-5045 | 1.00 |
| 33-3073 | .50 | 33-3185 | .17 | 33-3320 | .65 | 33-5046 | 1.00 |
| 33-3074 | .50 | 33-3186 | .17 | 33-3321 | .40 | 33-5047 | 1.00 |
| 33-3075 | .50 | 33-3187 | .17 | 33-3322 | .65 | 33-5048 | 1.00 |
| 33-3076 | .50 | 33-3188 | .70 | 33-3323 | 1.00 | 33-5049 | 1.00 |
| 33-3077 | .55 | 33-3190 | .85 | 33-3324 | .35 | 33-5050 | 1.00 |
| 33-3078 | .55 | 33-3191 | .85 | 33-3325 | .45 | 33-5051 | 1.00 |
| 33-3079 | .65 | 33-3192 | .85 | 33-3329 | .25 | 33-5052 | 1.00 |
| 33-3081 | .65 | 33-3193 | 1.45 | 33-3333 | 1.20 | 33-5053 | 1.00 |
| 33-3082 | .65 | 33-3194 | 1.60 | 33-3334 | .70 | 33-5054 | 1.00 |
| 33-3083 | .65 | 33-3195 | 1.65 | 33-3347 | .50 | 33-5055 | 1.45 |
| 33-3084 | .70 | 33-3207 | .17 | 33-3348 | .95 | 33-5056 | 1.70 |
| 33-3085 | .75 | 33-3208 | .17 | 33-3349 | .95 | 33-5059 | 1.45 |
| 33-3087 | .75 | 33-3209 | .17 | 33-3358 | .30 | 33-5060 | 1.00 |
| 33-3088 | .75 | 33-3211 | .65 | 33-3361 | .50 | 33-5063 | 1.00 |
| 33-3089 | .75 | 33-3212 | .65 | 33-3362 | .40 | 33-5064 | 1.45 |
| 33-3090 | .75 | 33-3213 | .50 | 33-3363 | .35 | 33-5066 | 1.45 |
| 33-3091 | .75 | 33-3214 | .30 | 33-3364 | .50 | 33-5067 | 1.70 |
| 33-3092 | .75 | 33-3216 | .60 | 33-3365 | .35 | 33-5068 | 1.45 |
| 33-3093 | .75 | 33-3220 | .30 | 33-3366 | .30 | 33-5069 | 1.00 |
| 33-3094 | .75 | 33-3222 | .30 | 33-3368 | .30 | 33-5071 | 1.45 |
| 33-3095 | .75 | 33-3224 | .30 | 33-3370 | 2.00 | 33-5076 | .80 |
| 33-3096 | .75 | 33-3225 | .30 | 33-3372 | .40 | 33-5078 | 1.00 |
| 33-3097 | .75 | 33-3226 | .30 | 33-3375 | .30 | 33-5079 | 1.45 |
| 33-3098 | .75 | 33-3231 | .75 | 33-3376 | .30 | 33-5080 | 1.00 |
| 33-3099 | .75 | 33-3232 | .17 | 33-3377 | .90 | 33-5081 | 1.45 |
| 33-3100 | .75 | 33-3233 | .17 | 33-3387 | .40 | 33-5082 | 1.00 |
| 33-3101 | .75 | 33-3234 | .30 | 33-3389 | 1.00 | 33-5084 | 1.70 |
| 33-3102 | .75 | 33-3235 | .55 | 33-3390 | .40 | 33-5088 | 1.70 |
| 33-3103 | .75 | 33-3236 | .30 | 33-3391 | 1.50 | 33-5093 | 1.00 |
| 33-3104 | .75 | 33-3237 | .60 | 33-3392 | .35 | 33-5097 | 1.45 |
| 33-3105 | .90 | 33-3238 | .30 | 33-3393 | .35 | 33-5101 | .85 |
| 33-3106 | .90 | 33-3240 | 2.75 | 33-3394 | .35 | 33-5102 | 1.45 |
| 33-3107 | .90 | 33-3242 | .50 | 33-3395 | .35 | 33-5103 | 4.25 |
| 33-3108 | .90 | 33-3243 | .50 | 33-3396 | .35 | 33-5105 | 1.45 |
| 33-3109 | .90 | 33-3244 | .50 | 33-3397 | .30 | 33-5106 | 1.45 |
| 33-3110 | .90 | 33-3245 | .50 | 33-3400 | .40 | 33-5107 | 1.45 |
| 33-3111 | .90 | 33-3246 | .50 | 33-3401 | .25 | 33-5108 | 1.45 |
| 33-3113 | 1.00 | 33-3247 | .50 | 33-3405 | .35 | 33-5111 | .70 |
| 33-3114 | 1.00 | 33-3248 | .20 | 33-3406 | .25 | 33-5113 | 1.45 |
| 33-3115 | 1.05 | 33-3249 | .50 | 33-3407 | .45 | 33-5114 | 1.45 |
| 33-3117 | 1.05 | 33-3250 | .50 | 33-3408 | .25 | 33-5117 | 1.00 |
| 33-3116 | 1.05 | 33-3251 | .50 | 33-3410 | .30 | 33-5118 | .70 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|-----------|------------|-----------|------------|
| 33-5119 | 1.45 | 33-5278 | 1.45 | 33-5434 | 1.45 | 33-120436 | .20 |
| 33-5120 | 1.45 | 33-5280 | 1.25 | 33-5435 | .30 | 33-120439 | .20 |
| 33-5121 | 1.00 | 33-5281 | 1.00 | 33-5436 | 1.45 | 33-122339 | .17 |
| 33-5125 | 1.00 | 33-5282 | 1.00 | 33-5437 | 1.45 | 33-122438 | .20 |
| 33-5126 | 1.00 | 33-5283 | 1.00 | 33-5438 | 1.00 | 33-125339 | .17 |
| 33-5127 | 1.45 | 33-5285 | 1.80 | 33-5441 | 1.45 | 33-125436 | .20 |
| 33-5129 | .75 | 33-5286 | 1.00 | 33-5442 | 1.00 | 33-125438 | .20 |
| 33-5130 | .80 | 33-5287 | 1.00 | 33-5443 | 1.00 | 33-125439 | .20 |
| 33-5131 | .80 | 33-5288 | 1.45 | 33-5445 | 1.45 | 33-127438 | .20 |
| 33-5137 | 1.45 | 33-5289 | 1.00 | 33-5447 | 1.45 | 33-127439 | .20 |
| 33-5139 | 1.00 | 33-5290 | 1.45 | 33-5448 | 1.00 | 33-128438 | .20 |
| 33-5140 | 1.45 | 33-5291 | 1.45 | 33-5450 | 1.00 | 33-128439 | .20 |
| 33-5141 | .75 | 33-5292 | 3.50 | 33-5451 | 1.00 | 33-130336 | .17 |
| 33-5142 | 1.45 | 33-5295 | 1.00 | 33-5452 | 1.45 | 33-130339 | .17 |
| 33-5144 | 1.00 | 33-5298 | 1.00 | 33-5454 | 1.00 | 33-130436 | .20 |
| 33-5145 | 1.45 | 33-5299 | 1.00 | 33-5455 | 1.45 | 33-130438 | .20 |
| 33-5146 | 1.45 | 33-5300 | 1.45 | 33-5456 | 1.45 | 33-130439 | .20 |
| 33-5148 | 1.00 | 33-5301 | 1.45 | 33-5457 | 1.45 | 33-130538 | .30 |
| 33-5149 | 1.00 | 33-5302 | 1.45 | 33-5458 | 1.45 | 33-133339 | .17 |
| 33-5150 | 1.00 | 33-5303 | 1.45 | 33-5459 | 1.00 | 33-133436 | .20 |
| 33-5152 | 1.45 | 33-5304 | 1.00 | 33-5460 | 1.00 | 33-135438 | .20 |
| 33-5153 | 1.45 | 33-5305 | 1.00 | 33-5461 | 1.00 | 33-139336 | .17 |
| 33-5154 | 1.00 | 33-5306 | 1.00 | 33-5462 | 1.45 | 33-139339 | .17 |
| 33-5155 | 1.45 | 33-5310 | 1.45 | 33-5463 | 1.45 | 33-140239 | .17 |
| 33-5157 | 1.00 | 33-5311 | 1.00 | 33-5464 | 1.45 | 33-140436 | .20 |
| 33-5158 | 1.00 | 33-5312 | 1.45 | 33-5465 | 1.00 | 33-140438 | .20 |
| 33-5165 | 1.00 | 33-5323 | 1.00 | 33-5467 | 1.00 | 33-140439 | .20 |
| 33-5166 | 1.00 | 33-5314 | 1.45 | 33-5468 | 1.00 | 33-145339 | .17 |
| 33-5168 | 1.45 | 33-5319 | 1.00 | 33-5469 | 1.45 | 33-145438 | .20 |
| 33-5169 | 1.45 | 33-5320 | 1.00 | 33-5470 | 1.00 | 33-147339 | .17 |
| 33-5170 | 1.20 | 33-5321 | 1.45 | 33-5471 | 1.00 | 33-150336 | .17 |
| 33-5171 | 1.00 | 33-5322 | 1.00 | 33-5472 | 1.00 | 33-150436 | .20 |
| 33-5172 | .70 | 33-5324 | 1.00 | 33-5474 | 1.45 | 33-150438 | .20 |
| 33-5173 | .75 | 33-5325 | 1.00 | 33-5477 | 1.00 | 33-150439 | .20 |
| 33-5175 | .75 | 33-5326 | 1.45 | 33-010439 | .20 | 33-155338 | .17 |
| 33-5176 | 1.60 | 33-5327 | 1.00 | 33-014326 | 1.00 | 33-160336 | .17 |
| 33-5178 | 1.50 | 33-5329 | 1.45 | 33-015336 | 1.45 | 33-160339 | .17 |
| 33-5181 | 1.50 | 33-5331 | 1.45 | 33-016436 | 1.45 | 33-160339 | .20 |
| 33-5182 | 1.45 | 33-5332 | 1.00 | 33-016438 | 1.00 | 33-160438 | .17 |
| 33-5183 | 1.00 | 33-5333 | 1.25 | 33-016439 | 1.25 | 33-160439 | .20 |
| 33-5193 | 1.45 | 33-5334 | 1.00 | 33-018336 | 1.00 | 33-165326 | .17 |
| 33-5198 | 1.45 | 33-5336 | 1.45 | 33-020326 | 1.45 | 33-170339 | .17 |
| 33-5202 | 1.00 | 33-5375 | 1.45 | 33-020339 | 1.45 | 33-170436 | .20 |
| 33-5206 | 1.00 | 33-5389 | 1.45 | 33-020439 | 1.45 | 33-170438 | .20 |
| 33-5215 | 1.00 | 33-5390 | 1.45 | 33-022338 | 1.45 | 33-170439 | .20 |
| 33-5222 | 1.00 | 33-5391 | 1.00 | 33-027439 | 1.00 | 33-175439 | .20 |
| 33-5224 | 1.00 | 33-5392 | 1.00 | 33-028339 | 1.00 | 33-180326 | .17 |
| 33-5225 | 1.00 | 33-5393 | 1.45 | 33-028439 | 1.45 | 33-180339 | .17 |
| 33-5228 | 1.00 | 33-5394 | 1.45 | 33-033428 | 1.45 | 33-180439 | .20 |
| 33-5229 | 1.00 | 33-5395 | 1.00 | 33-033436 | 1.00 | 33-182339 | .17 |
| 33-5230 | 1.45 | 33-5396 | 1.45 | 33-039336 | 1.45 | 33-190436 | .20 |
| 33-5231 | .75 | 33-5397 | 1.45 | 33-040336 | 1.45 | 33-190438 | .20 |
| 33-5232 | 1.00 | 33-5398 | 1.45 | 33-040439 | 1.45 | 33-190439 | .20 |
| 33-5233 | 1.00 | 33-5399 | 1.00 | 33-047336 | 1.00 | 33-190446 | .20 |
| 33-5234 | 1.00 | 33-5400 | 1.45 | 33-050339 | 1.45 | 33-210333 | .17 |
| 33-5235 | 1.00 | 33-5401 | 1.00 | 33-050436 | 1.00 | 33-210339 | .17 |
| 33-5237 | 1.45 | 33-5402 | 1.00 | 33-050438 | 1.00 | 33-210439 | .20 |
| 33-5238 | 1.00 | 33-5403 | 1.00 | 33-050439 | 1.00 | 33-210533 | .30 |
| 33-5239 | .40 | 33-5404 | 1.00 | 33-060336 | 1.00 | 33-212339 | .17 |
| 33-5240 | 1.80 | 33-5405 | 1.45 | 33-060339 | 1.45 | 33-214339 | .17 |
| 33-5241 | 1.80 | 33-5408 | 1.00 | 33-060436 | 1.00 | 33-214439 | .20 |
| 33-5245 | 1.00 | 33-5409 | 1.45 | 33-060439 | 1.45 | 33-214539 | .30 |
| 33-5246 | 1.00 | 33-5410 | 1.45 | 33-070339 | 1.45 | 33-215339 | .20 |
| 33-5247 | 1.45 | 33-5411 | 1.00 | 33-070439 | 1.00 | 33-215439 | .20 |
| 33-5248 | .35 | 33-5412 | 1.00 | 33-075428 | 1.00 | 33-218339 | .17 |
| 33-5249 | 1.45 | 33-5413 | 1.45 | 33-085439 | 1.45 | 33-220334 | .17 |
| 33-5250 | 1.00 | 33-5415 | 1.45 | 33-110333 | 1.45 | 33-220339 | .17 |
| 33-5251 | 1.00 | 33-5416 | 1.45 | 33-110336 | 1.45 | 33-220344 | .17 |
| 33-5252 | 1.45 | 33-5417 | 1.45 | 33-110436 | 1.45 | 33-220439 | .30 |
| 33-5253 | 1.45 | 33-5418 | 1.00 | 33-110438 | 1.00 | 33-220534 | .20 |
| 33-5254 | 1.45 | 33-5419 | .89 | 33-110439 | 1.45 | 33-220539 | .30 |
| 33-5257 | 1.00 | 33-5420 | .89 | 33-112326 | 1.45 | 33-221539 | .17 |
| 33-5259 | 1.00 | 33-5421 | .89 | 33-112339 | 1.45 | 33-222339 | .17 |
| 33-5260 | 1.45 | 33-5422 | .89 | 33-113336 | 1.45 | 33-224339 | .17 |
| 33-5261 | .35 | 33-5423 | .89 | 33-113339 | 1.45 | 33-225439 | .20 |
| 33-5262 | 2.25 | 33-5424 | .89 | 33-113439 | 1.45 | 33-227339 | .17 |
| 33-5264 | .35 | 33-5425 | .89 | 33-115336 | 1.45 | 33-229439 | .20 |
| 33-5265 | 1.00 | 33-5426 | .89 | 33-115339 | 1.45 | 33-230339 | .17 |
| 33-5268 | 1.45 | 33-5427 | .89 | 33-115436 | 1.45 | 33-230439 | .20 |
| 33-5269 | 1.45 | 33-5428 | 1.45 | 33-115438 | 1.45 | 33-233339 | .17 |
| 33-5270 | 1.45 | 33-5429 | 1.45 | 33-115439 | 1.45 | 33-233439 | .20 |
| 33-5272 | 1.45 | 33-5430 | 1.45 | 33-118339 | 1.45 | 33-235439 | .17 |
| 33-5275 | 1.00 | 33-5431 | 1.45 | 33-118438 | 1.45 | 33-235339 | .20 |
| 33-5276 | 1.00 | 33-5432 | 1.00 | 33-120336 | 1.45 | 33-239339 | .17 |
| | | 33-5433 | 1.00 | 33-120339 | 1.45 | 33-240339 | .17 |
| | | | | | | 33-240439 | .20 |
| | | | | | | 33-240533 | .30 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|-----------|------------|-----------|------------|-----------|------------|-----------|------------|
| 33-240543 | .30 | 33-351539 | .30 | 33-547339 | .17 | 35-1214-1 | 5.75 |
| 33-245439 | .20 | 33-360339 | .17 | 33-550339 | .17 | 35-1216 | 6.50 |
| 33-247339 | .17 | 33-360439 | .20 | 33-550439 | .20 | 35-1217-1 | 1.00 |
| 33-249439 | .20 | 33-365439 | .20 | 33-560339 | .17 | 35-1218 | .25 |
| 33-250333 | .17 | 33-368339 | .17 | 33-560439 | .20 | 35-1222-2 | 6.50 |
| 33-250339 | .17 | 33-368434 | .20 | 33-570439 | .20 | 35-1225 | 6.50 |
| 33-250344 | .17 | 33-370339 | .20 | 33-580439 | .20 | 35-1226 | 10.00 |
| 33-250543 | .30 | 33-370439 | .17 | 33-590439 | .20 | 35-1228 | 7.00 |
| 33-250643 | .30 | 33-375339 | .20 | 33-610339 | .17 | 35-1237 | 10.00 |
| 33-255327 | .17 | 33-375439 | .17 | 33-610439 | .20 | 35-1240 | 6.00 |
| 33-256339 | .17 | 33-375539 | .30 | 33-615327 | .17 | 35-1251 | 18.50 |
| 33-256439 | .20 | 33-385439 | .20 | 33-615339 | .17 | 35-1252 | 18.00 |
| 33-260339 | .17 | 33-390439 | .20 | 33-615439 | .20 | 35-1257 | 8.25 |
| 33-260439 | .20 | 33-398439 | .20 | 33-930418 | .20 | 35-1265 | 5.00 |
| 33-268339 | .17 | 33-399339 | .17 | 33-934416 | .20 | 35-1275 | 9.00 |
| 33-270439 | .20 | 33-410339 | .17 | 33-980348 | .17 | 35-1277 | 9.00 |
| 33-275339 | .17 | 33-410439 | .20 | 33-983326 | .17 | 35-1278 | 5.50 |
| 33-275439 | .20 | 33-410533 | .30 | | | 35-1280 | 9.75 |
| 33-275543 | .30 | 33-410539 | .30 | 34-2031 | .10 | 35-2003 | 18.50 |
| 33-275639 | .30 | 33-412339 | .17 | 34-2038 | .09 | 35-2004 | 11.50 |
| 33-280339 | .17 | 33-412439 | .20 | 34-2039 | .09 | 35-2007 | 11.25 |
| 33-280439 | .20 | 33-415339 | .17 | 34-2040 | .09 | 35-2009 | 13.50 |
| 33-282339 | .17 | 33-415439 | .20 | 34-2047 | .12 | 35-2010 | 10.00 |
| 33-290339 | .17 | 33-416339 | .17 | 34-2063 | .10 | 35-2011 | 9.00 |
| 33-290439 | .20 | 33-416439 | .20 | 34-2064 | .09 | 35-2013 | .05 |
| 33-290539 | .30 | 33-417439 | .20 | 34-2065 | .22 | 35-2014 | 7.25 |
| 33-290544 | .30 | 33-418339 | .17 | 34-2068 | .09 | 35-2022 | 6.50 |
| 33-310339 | .17 | 33-419339 | .17 | 34-2081 | .22 | 35-2026 | 6.75 |
| 33-310439 | .20 | 33-419439 | .20 | 34-2141 | .12 | 35-2027 | 10.00 |
| 33-310533 | .30 | 33-420339 | .17 | 34-2150 | .22 | 35-2030 | 6.00 |
| 33-310534 | .30 | 33-420439 | .20 | 34-2184 | .15 | 35-2036 | 6.75 |
| 33-310639 | .30 | 33-422339 | .17 | 34-2192 | .15 | 35-2037 | 1.50 |
| 33-312439 | .20 | 33-424339 | .17 | 34-2210 | .18 | 35-2038 | 1.25 |
| 33-313339 | .17 | 33-424439 | .20 | 34-2221 | .09 | 35-2039 | .75 |
| 33-313439 | .20 | 33-425339 | .17 | 34-2246 | .09 | 35-2042 | 6.25 |
| 33-313539 | .30 | 33-425439 | .20 | 34-2397 | .30 | 35-2044 | 7.50 |
| 33-313639 | .30 | 33-425533 | .30 | 34-2408 | .40 | 35-2053 | 1.00 |
| 33-315339 | .17 | 33-425539 | .30 | 34-2432 | 1.00 | 35-2057 | 2.50 |
| 33-315363 | .17 | 33-427339 | .17 | 34-2477 | .15 | 35-2058 | .65 |
| 33-315439 | .20 | 33-430339 | .17 | 34-2478 | .45 | 35-2060 | .35 |
| 33-315543 | .30 | 33-430439 | .20 | 34-9001 | 1.80 | 35-2061 | .35 |
| 33-315639 | .30 | 33-433333 | .17 | | | 35-2062 | .35 |
| 33-316339 | .17 | 33-433339 | .17 | 35-1002 | 23.00 | 35-2063 | .35 |
| 33-316439 | .20 | 33-433439 | .20 | 35-1007 | 23.00 | 35-2064 | 6.50 |
| 33-316539 | .30 | 33-434339 | .17 | 35-1019 | 28.50 | 35-2067 | 11.00 |
| 33-316633 | .30 | 33-434439 | .20 | 35-1030 | 14.75 | 35-2068 | 5.00 |
| 33-316639 | .30 | 33-435339 | .17 | 35-1035 | .50 | 35-2069 | 5.00 |
| 33-317439 | .20 | 33-435439 | .20 | 35-1036 | 10.00 | 35-2070 | 1.25 |
| 33-318439 | .20 | 33-440339 | .17 | 35-1044 | 1.25 | 35-2071 | 2.00 |
| 33-320333 | .17 | 33-440439 | .20 | 35-1046 | 4.00 | 35-2072 | 3.00 |
| 33-320419 | .20 | 33-447339 | .17 | 35-1048 | 1.35 | 35-2073 | .10 |
| 33-320439 | .20 | 33-449339 | .17 | 35-1049 | .02 | 35-2074 | .40 |
| 33-320533 | .30 | 33-449439 | .20 | 35-1050 | .25 | 35-2075 | .25 |
| 33-322339 | .17 | 33-450339 | .17 | 35-1051 | .20 | 35-2076 | .10 |
| 33-322439 | .20 | 33-450439 | .20 | 35-1054 | .10 | 35-2077 | .20 |
| 33-325339 | .17 | 33-460339 | .17 | 35-1055 | .60 | 35-2078 | .05 |
| 33-325439 | .20 | 33-460439 | .20 | 35-1057 | .03 | 35-2079 | .05 |
| 33-325533 | .30 | 33-468339 | .17 | 35-1058 | 1.50 | 35-2080 | .35 |
| 33-327339 | .17 | 33-468439 | .20 | 35-1060 | .05 | 35-2083 | .35 |
| 33-327439 | .20 | 33-470439 | .20 | 35-1063 | .05 | 35-2085 | .10 |
| 33-330339 | .17 | 33-475339 | .17 | 35-1071 | .10 | 35-2087 | .50 |
| 33-330439 | .20 | 33-475439 | .20 | 35-1075 | .10 | 35-2088 | .10 |
| 33-330634 | .30 | 33-475539 | .30 | 35-1090 | .04 | 35-2089 | .10 |
| 33-332339 | .17 | 33-480439 | .20 | 35-1092 | 34.00 | 35-2090 | .50 |
| 33-332439 | .20 | 33-490439 | .20 | 35-1112 | 20.00 | 35-2091 | .65 |
| 33-332543 | .30 | 33-491439 | .20 | 35-1116 | 18.00 | 35-2092 | .75 |
| 33-333339 | .17 | 33-510339 | .17 | 35-1118 | 2.50 | 35-2093 | .25 |
| 33-335439 | .20 | 33-510439 | .20 | 35-1119 | .15 | 35-2094 | .60 |
| 33-337439 | .20 | 33-515339 | .17 | 35-1122 | .35 | 35-2095 | 5.25 |
| 33-337539 | .30 | 33-515439 | .20 | 35-1123 | 27.00 | 35-2096 | .25 |
| 33-339339 | .17 | 33-517439 | .20 | 35-1136 | 20.00 | 35-2097 | .50 |
| 33-339439 | .20 | 33-518439 | .20 | 35-1148 | 17.50 | 35-2098 | .10 |
| 33-340339 | .17 | 33-520339 | .17 | 35-1151 | 5.50 | 35-2099 | .02 |
| 33-340439 | .20 | 33-520439 | .20 | 35-1152 | 6.25 | 35-2100 | .30 |
| 33-343339 | .17 | 33-522339 | .17 | 35-1153 | 12.00 | 35-2101 | 2.50 |
| 33-345339 | .17 | 33-524439 | .20 | 35-1162 | 7.50 | 35-2102 | .10 |
| 33-345439 | .20 | 33-525439 | .20 | 35-1164 | 2.50 | 35-2103 | .50 |
| 33-347339 | .17 | 33-530339 | .17 | 35-1165 | 2.50 | 35-2104 | .10 |
| 33-350339 | .17 | 33-530439 | .20 | 35-1167 | 2.50 | 35-2105 | .10 |
| 33-350439 | .20 | 33-533339 | .17 | 35-1168 | 4.00 | 35-2106 | .10 |
| 33-350533 | .30 | 33-535339 | .17 | 35-1170 | .05 | 35-2107 | .45 |
| 33-350539 | .30 | 33-535439 | .20 | 35-1171 | .20 | 35-2108 | .10 |
| 33-351339 | .17 | 33-539339 | .17 | 35-1179 | .15 | 35-2109 | .75 |
| 33-351439 | .20 | 33-540339 | .17 | 35-1199 | 2.50 | 35-2110 | .10 |
| 33-351533 | .30 | 33-540439 | .20 | 35-1204 | 18.00 | 35-2111 | .65 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 35-2112 | .15 | 35-2217 | 1.50 | 35-2310 | .07 | 35-2406 | .25 |
| 35-2113 | 2.50 | 35-2218 | .05 | 35-2311 | .07 | 35-2407 | .03 |
| 35-2114 | 4.00 | 35-2219 | .30 | 35-2312 | 1.00 | 35-2408 | .25 |
| 35-2115 | .10 | 35-2220 | 1.25 | 35-2313 | .20 | 35-2410 | .15 |
| 35-2116 | .40 | 35-2221 | .25 | 35-2314 | .07 | 35-2411 | .05 |
| 35-2117 | .50 | 35-2222 | 4.25 | 35-2315 | .30 | 35-2412 | .10 |
| 35-2118 | .90 | 35-2224 | .10 | 35-2316 | .07 | 35-2413 | .10 |
| 35-2119 | .10 | 35-2225 | 4.00 | 35-2317 | .30 | 35-2415 | .10 |
| 35-2120 | .35 | 35-2226 | .20 | 35-2318 | 1.10 | 35-2417 | .60 |
| 35-2121 | 1.50 | 35-2227 | .60 | 35-2319 | 1.75 | 35-2420 | .40 |
| 35-2122 | .15 | 35-2228 | .02 | 35-2320 | .07 | 35-2421 | .25 |
| 35-2123 | .10 | 35-2229 | .06 | 35-2321 | .20 | 35-2422 | .10 |
| 35-2124 | .10 | 35-2231 | .25 | 35-2322 | .02 | 35-2423 | .08 |
| 35-2125 | .05 | 35-2232 | 10.00 | 35-2323 | .10 | 35-2424 | .10 |
| 35-2126 | .40 | 35-2233 | 17.50 | 35-2325 | .15 | 35-2426 | .15 |
| 35-2127 | 2.25 | 35-2234 | 1.40 | 35-2326 | .25 | 35-2428 | 3.50 |
| 35-2128 | .50 | 35-2235 | .10 | 35-2327 | .90 | 35-2429 | .05 |
| 35-2129 | .80 | 35-2236 | .10 | 35-2328 | .05 | 35-2430 | .05 |
| 35-2130 | 2.00 | 35-2237 | .90 | 35-2329 | 1.10 | 35-2431 | .35 |
| 35-2131 | .02 | 35-2238 | .10 | 35-2330 | .06 | 35-2433 | .50 |
| 35-2132 | .20 | 35-2239 | .10 | 35-2331 | 1.50 | 35-2434 | .01 |
| 35-2133 | .35 | 35-2240 | .10 | 35-2332 | .10 | 35-2436 | .10 |
| 35-2134 | .30 | 35-2241 | .20 | 35-2333 | .35 | 35-2437 | 4.00 |
| 35-2135 | 1.75 | 35-2242 | 2.00 | 35-2334 | 2.25 | 35-2438 | .50 |
| 35-2136 | 1.50 | 35-2243 | 1.00 | 35-2335 | .90 | 35-2439 | .50 |
| 35-2137 | 1.75 | 35-2244 | 1.00 | 35-2336 | .30 | 35-2440 | .04 |
| 35-2138 | .05 | 35-2245 | .50 | 35-2337 | .10 | 35-2441 | 1.00 |
| 35-2139 | .10 | 35-2246 | .10 | 35-2338 | .15 | 35-2442 | .50 |
| 35-2140 | .15 | 35-2247 | .03 | 35-2339 | 5.75 | 35-2443 | .07 |
| 35-2141 | .02 | 35-2248 | .75 | 35-2340 | .40 | 35-2444 | .50 |
| 35-2142 | .02 | 35-2249 | .20 | 35-2341 | .45 | 35-2445 | .50 |
| 35-2143 | .10 | 35-2250 | .45 | 35-2342 | .30 | 35-2446 | 2.00 |
| 35-2144 | .05 | 35-2251 | .20 | 35-2343 | .50 | 35-2447 | .10 |
| 35-2145 | .30 | 35-2252 | .05 | 35-2344 | .15 | 35-2448 | .50 |
| 35-2146 | .75 | 35-2253 | .05 | 35-2345 | .05 | 35-2449 | .55 |
| 35-2147 | .80 | 35-2254 | 10.00 | 35-2346 | .05 | 35-2451 | 2.75 |
| 35-2148 | .75 | 35-2255 | .35 | 35-2347 | .01 | 35-2452 | .05 |
| 35-2149 | .20 | 35-2256 | .10 | 35-2348 | .02 | 35-2453 | .02 |
| 35-2150 | .03 | 35-2257 | .10 | 35-2349 | .20 | 35-2454 | .50 |
| 35-2151 | .10 | 35-2258 | .10 | 35-2350 | .20 | 35-2456 | 6.50 |
| 35-2152 | .75 | 35-2259 | .10 | 35-2351 | .20 | 35-2457 | .03 |
| 35-2153 | .05 | 35-2260 | .10 | 35-2352 | .20 | 35-2458 | .03 |
| 35-2154 | .05 | 35-2261 | .15 | 35-2354 | .05 | 35-2459 | .05 |
| 35-2155 | 2.50 | 35-2262 | .15 | 35-2355 | .75 | 35-2460 | .50 |
| 35-2156 | 5.00 | 35-2263 | .03 | 35-2356 | .90 | 35-2461 | .20 |
| 35-2157 | 1.75 | 35-2264 | .10 | 35-2357 | .60 | 35-2463 | 4.00 |
| 35-2161 | .10 | 35-2265 | .10 | 35-2358 | 2.75 | 35-2465 | .10 |
| 35-2162 | .50 | 35-2266 | .01 | 35-2359 | 2.00 | 35-2466 | .03 |
| 35-2163 | .30 | 35-2268 | 1.00 | 35-2360 | .08 | 35-2468 | .10 |
| 35-2164 | .10 | 35-2269 | 1.75 | 35-2361 | 17.50 | 35-2469 | .01 |
| 35-2165 | 1.65 | 35-2270 | 1.75 | 35-2362 | .75 | 35-2471 | .06 |
| 35-2166 | .30 | 35-2271 | .10 | 35-2363 | .55 | 35-2474 | .20 |
| 35-2167 | .75 | 35-2272 | .15 | 35-2364 | .35 | 35-2475 | 2.25 |
| 35-2168 | .25 | 35-2273 | 1.25 | 35-2365 | .35 | 35-2476 | 6.00 |
| 35-2169 | 5.00 | 35-2274 | 1.75 | 35-2366 | 3.00 | 35-2477 | .05 |
| 35-2170 | .10 | 35-2275 | .10 | 35-2367 | .50 | 35-2478 | .50 |
| 35-2171 | .35 | 35-2276 | .05 | 35-2369 | .20 | 35-2479 | 5.00 |
| 35-2172 | 3.00 | 35-2277 | 1.10 | 35-2370 | .10 | 35-2480 | .05 |
| 35-2173 | .05 | 35-2278 | .01 | 35-2371 | 1.00 | 35-2481 | .20 |
| 35-2175 | 17.50 | 35-2279 | .06 | 35-2372 | .05 | 35-2482 | .20 |
| 35-2177 | .50 | 35-2280 | .03 | 35-2373 | .03 | 35-2483 | 1.25 |
| 35-2178 | .02 | 35-2281 | 17.50 | 35-2374 | .10 | 35-2484 | .10 |
| 35-2179 | 2.50 | 35-2282 | .15 | 35-2375 | .05 | 35-2485 | .15 |
| 35-2187 | .10 | 35-2283 | .10 | 35-2376 | .05 | 35-2486 | .15 |
| 35-2188 | .75 | 35-2284 | .60 | 35-2377 | .05 | 35-2487 | .02 |
| 35-2192 | .45 | 35-2285 | .10 | 35-2378 | .01 | 35-2488 | 4.50 |
| 35-2195 | .10 | 35-2286 | 1.25 | 35-2379 | .03 | 35-2491 | .25 |
| 35-2196 | .10 | 35-2288 | .05 | 35-2380 | .03 | 35-2492 | 1.25 |
| 35-2197 | .45 | 35-2289 | .10 | 35-2384 | .20 | 35-2493 | 1.40 |
| 35-2198 | .60 | 35-2290 | .25 | 35-2385 | .10 | 35-2494 | .01 |
| 35-2199 | .10 | 35-2292 | .10 | 35-2386 | .05 | 35-2495 | .03 |
| 35-2200 | .10 | 35-2293 | .05 | 35-2387 | 4.50 | 35-2496 | .02 |
| 35-2201 | 2.00 | 35-2295 | .05 | 35-2388 | .05 | 35-2514 | 1.75 |
| 35-2204 | 4.25 | 35-2296 | .95 | 35-2389 | .03 | 35-2515 | 6.50 |
| 35-2205 | 5.25 | 35-2297 | 4.50 | 35-2390 | .15 | 35-2516 | .15 |
| 35-2207 | 3.25 | 35-2299 | 3.50 | 35-2393 | .02 | 35-2520 | .10 |
| 35-2208 | .10 | 35-2300 | .04 | 35-2394 | .01 | 35-2521 | .10 |
| 35-2209 | 17.50 | 35-2301 | .07 | 35-2395 | .25 | 35-2522 | .10 |
| 35-2210 | .75 | 35-2302 | .03 | 35-2396 | .35 | 35-2523 | .10 |
| 35-2211 | .15 | 35-2303 | .10 | 35-2397 | .10 | 35-3000 | 1.00 |
| 35-2212 | .60 | 35-2304 | .10 | 35-2398 | .60 | 35-3001 | 9.00 |
| 35-2213 | .20 | 35-2306 | .15 | 35-2399 | .15 | 35-3002 | 1.35 |
| 35-2214 | .10 | 35-2307 | .45 | 35-2400 | .05 | 35-3007 | 2.50 |
| 35-2215 | .10 | 35-2308 | .10 | 35-2404 | .03 | 35-3007 | 2.50 |
| 35-2216 | 1.75 | 35-2309 | .10 | 35-2405 | .50 | 35-3009 | 2.40 |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|-----------|------------|----------|------------|----------|------------|----------|------------|
| 35-3011 | 2.50 | 36-1207 | 12.00 | 36-1438 | 9.00 | 36-3162 | 11.00 |
| 35-3012 | 2.25 | 36-1209 | 5.75 | 36-1440 | 6.25 | 36-3170 | 1.90 |
| 35-3013 | .20 | 36-1211 | 8.50 | 36-1441 | 4.00 | 36-3218 | 4.25 |
| 35-3014 | 1.30 | 36-1217 | 17.25 | 36-1442 | 5.50 | 36-3243 | 3.00 |
| 35-3015 | .60 | 36-1224 | 8.25 | 36-1444 | 4.25 | 36-3325 | 3.50 |
| 35-3017 | 3.50 | 36-1225 | 5.75 | 36-1445 | 6.50 | 36-3327 | 1.40 |
| 35-3022 | 2.50 | 36-1229 | 7.25 | 36-1447 | 7.50 | 36-3341 | 3.50 |
| 35-3023 | 1.75 | 36-1231 | 7.25 | 36-1449 | 6.25 | 36-3352 | 4.25 |
| 35-3029 | .15 | 36-1233 | 7.25 | 36-1450 | 9.00 | 36-3357 | 3.50 |
| 35-3030 | .10 | 36-1235 | 7.25 | 36-1451 | 6.50 | 36-3381 | 2.00 |
| 35-3038 | 2.50 | 36-1236 | 8.25 | 36-1452 | 4.75 | 36-3403 | 3.50 |
| 35-3039 | 3.00 | 36-1238 | 8.25 | 36-1453 | 6.50 | 36-3405 | .06 |
| 35-3044-2 | 1.00 | 36-1240 | 8.25 | 36-1455 | 7.50 | 36-3407 | 3.50 |
| 35-3045 | 1.00 | 36-1248 | 10.00 | 36-1461 | 4.50 | 36-3430 | 4.25 |
| 35-3046 | .25 | 36-1249 | 10.00 | 36-1469 | 4.00 | 36-3431 | .10 |
| 35-3047 | 1.25 | 36-1250 | 11.00 | 36-1476 | 5.50 | 36-3432 | .95 |
| 35-3048 | 2.50 | 36-1251 | 11.00 | 36-1477 | 5.50 | 36-3446 | .80 |
| 35-3049 | 4.25 | 36-1252 | 16.00 | 36-1478 | 4.25 | 36-3461 | 4.25 |
| 35-3051 | .60 | 36-1255 | 6.25 | 36-1479 | 8.00 | 36-3474 | .20 |
| 35-3052 | .75 | 36-1256 | 6.50 | 36-1480 | 6.25 | 36-3478 | .60 |
| 35-3053 | .15 | 36-1260 | 11.00 | 36-1481 | 5.00 | 36-3485 | .70 |
| 35-3054 | .65 | 36-1261 | 11.00 | 36-1482 | 6.50 | 36-3495 | 3.50 |
| 35-3055 | .30 | 36-1262 | 7.25 | 36-1483 | 5.00 | 36-3503 | 1.00 |
| 35-3056 | 2.00 | 36-1266 | 8.50 | 36-1484 | 4.25 | 36-3504 | .75 |
| 35-3057 | 3.25 | 36-1267 | 5.00 | 36-1487 | 7.00 | 36-3508 | 4.15 |
| 35-4069 | 33.50 | 36-1270 | 4.50 | 36-1488 | 9.50 | 36-3513 | 4.25 |
| 35-4070 | 6.25 | 36-1271 | 22.50 | 36-1489 | 9.00 | 36-3517 | 3.50 |
| 35-4071 | 1.50 | 36-1273 | 22.50 | 36-1491 | 7.00 | 36-3519 | 3.50 |
| 35-4075 | 16.50 | 36-1279 | 5.00 | 36-1504 | 4.00 | 36-3526 | 1.40 |
| 35-4076 | 25.00 | 36-1280 | 6.00 | 36-1505 | 4.00 | 36-3531 | 1.35 |
| 35-4077 | 9.00 | 36-1281 | 7.50 | 36-1506 | 5.00 | 36-3539 | .10 |
| | | 36-1282 | 22.50 | 36-1507 | 4.75 | 36-3540 | 1.00 |
| 36-1006 | 8.25 | 36-1284 | 22.50 | 36-1508 | 6.50 | 36-3547 | .45 |
| 36-1007 | 5.75 | 36-1285 | 7.25 | 36-1509 | 5.00 | 36-3552 | .45 |
| 36-1016 | 5.75 | 36-1289 | 7.25 | 36-1510 | 4.00 | 36-3557 | 1.90 |
| 36-1018 | 5.50 | 36-1293 | 8.25 | 36-1511 | 4.75 | 36-3558 | .65 |
| 36-1019 | 15.00 | 36-1295 | 8.25 | 36-1512 | 4.00 | 36-3559 | .45 |
| 36-1025 | 7.25 | 36-1297 | 8.25 | 36-1513 | 6.25 | 36-3560 | .05 |
| 36-1036 | 8.25 | 36-1299 | 6.75 | 36-1514 | 7.00 | 36-3569 | .40 |
| 36-1039 | 15.00 | 36-1308 | 10.00 | 36-1515 | 8.50 | 36-3586 | .90 |
| 36-1055 | 7.25 | 36-1314 | 7.00 | 36-1516 | 4.75 | 36-3588 | 2.50 |
| 36-1057 | 8.25 | 36-1317 | 11.00 | 36-1517 | 3.00 | 36-3593 | 3.00 |
| 36-1058 | 7.25 | 36-1323 | 10.00 | 36-1518 | 8.00 | 36-3597 | 3.00 |
| 36-1059 | 8.25 | 36-1324 | 11.00 | 36-1519 | 4.75 | 36-3609 | 3.00 |
| 36-1064 | 8.25 | 36-1326 | 5.50 | 36-1520 | 4.00 | 36-3620 | 3.00 |
| 36-1065 | 8.25 | 36-1329 | 11.00 | 36-1521 | 5.00 | 36-3627 | 1.20 |
| 36-1073 | 5.75 | 36-1330 | 6.25 | 36-1522 | 8.00 | 36-3631 | 2.00 |
| 36-1085 | 13.25 | 36-1331 | 12.00 | 36-1523 | 7.50 | 36-3654 | .90 |
| 36-1088 | 16.00 | 36-1333 | 10.00 | 36-1524 | 7.25 | 36-3664 | 3.50 |
| 36-1090 | 16.00 | 36-1338 | 5.00 | 36-1525 | 4.00 | 36-3672 | .15 |
| 36-1098 | 5.00 | 36-1342 | 6.75 | 36-1526 | 4.50 | 36-3673 | 4.25 |
| 36-1108 | 15.00 | 36-1344 | 16.00 | 36-1527 | 3.00 | 36-3687 | 4.25 |
| 36-1114 | 5.00 | 36-1345 | 5.00 | 36-1528 | 8.25 | 36-3735 | .15 |
| 36-1121 | 8.50 | 36-1348 | 5.75 | 36-1530 | 7.50 | 36-3782 | 15.00 |
| 36-1122 | 9.50 | 36-1351 | 11.00 | 36-1532 | 3.25 | 36-3786 | .60 |
| 36-1129 | 5.00 | 36-1352 | 11.00 | 36-1533 | 4.50 | 36-3787 | 4.25 |
| 36-1135 | 10.00 | 36-1356 | 8.00 | 36-1534 | 8.00 | 36-3788 | 15.00 |
| 36-1138 | 9.50 | 36-1360 | 10.00 | 36-1535 | 7.50 | 36-3808 | 2.50 |
| 36-1141 | 7.00 | 36-1362 | 5.00 | 36-1536 | 3.00 | 36-3811 | 5.00 |
| 36-1142 | 5.25 | 36-1363 | 22.50 | 36-1537 | 7.50 | 36-3822 | 1.20 |
| 36-1147 | 5.00 | 36-1365 | 22.50 | 36-1538 | 4.75 | 36-3824 | 1.50 |
| 36-1151 | 7.25 | 36-1371 | 11.00 | 36-1540 | 6.00 | 36-3836 | 3.00 |
| 36-1152 | 8.25 | 36-1372 | 8.50 | 36-1541 | 5.25 | 36-3884 | .60 |
| 36-1153 | 7.00 | 36-1373 | 4.00 | 36-1542 | 4.00 | 36-3885 | 1.00 |
| 36-1154 | 7.00 | 36-1376 | 5.75 | 36-1543 | 4.00 | 36-3907 | .60 |
| 36-1155 | 1.25 | 36-1377 | 10.00 | 36-1544 | 4.00 | 36-3928 | 3.50 |
| 36-1156 | 9.00 | 36-1378 | 11.00 | 36-1548 | 4.00 | 36-3941 | 4.25 |
| 36-1158 | 2.00 | 36-1379 | 10.00 | 36-1549 | 5.00 | 36-3981 | 1.50 |
| 36-1159 | 5.00 | 36-1380 | 11.00 | 36-3000 | .70 | 36-3985 | 3.50 |
| 36-1162 | 16.00 | 36-1381 | 6.00 | 36-3009 | .35 | 36-3987 | 3.50 |
| 36-1173 | 5.75 | 36-1382 | 5.75 | 36-3025 | .08 | 36-3995 | 3.00 |
| 36-1175 | 3.75 | 36-1384 | 5.25 | 36-3029 | 1.10 | 36-4008 | .75 |
| 36-1177 | 6.00 | 36-1387 | 7.50 | 36-3040 | 3.00 | 36-4012 | 4.25 |
| 36-1180 | 6.00 | 36-1390 | 5.50 | 36-3046 | 3.50 | 36-4019 | .65 |
| 36-1181 | 10.00 | 36-1398 | 4.50 | 36-3058 | .85 | 36-4023 | 1.10 |
| 36-1182 | 4.00 | 36-1401 | 4.50 | 36-3074 | 11.00 | 36-4048 | .50 |
| 36-1183 | 4.00 | 36-1404 | 4.00 | 36-3087 | 1.25 | 36-4055 | .50 |
| 36-1185 | 11.00 | 36-1406 | 4.75 | 36-3088 | 11.00 | 36-4057 | 5.25 |
| 36-1189 | 4.00 | 36-1409 | 10.00 | 36-3096 | 6.40 | 36-4083 | 1.50 |
| 36-1191 | 4.00 | 36-1410 | 11.50 | 36-3104 | 4.25 | 36-4085 | 1.50 |
| 36-1192 | 17.25 | 36-1411 | 4.75 | 36-3130 | 4.25 | 36-4086 | 1.75 |
| 36-1194 | 6.00 | 36-1416 | 5.25 | 36-3140 | 4.25 | 36-4087 | 1.75 |
| 36-1203 | 4.00 | 36-1426 | 4.00 | 36-3157 | 1.50 | 36-4088 | 2.25 |
| 36-1204 | 5.00 | 36-1436 | 12.00 | 36-3159 | 1.50 | 36-4089 | 2.50 |
| 36-1205 | 6.00 | 36-1437 | 7.00 | 36-3160 | .07 | 36-4090 | 1.50 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 36-4092 | 1.75 | 38-5511 | 1.70 | 38-7763 | .20 | 38-9254 | 13.00 |
| 36-4093 | 1.50 | 38-5519 | 1.00 | 38-7820 | .45 | 38-9270 | .15 |
| 36-4094 | 1.75 | 38-5527 | .30 | 38-7844 | .15 | 38-9282 | .50 |
| 36-4095 | 1.40 | 38-5534 | 1.80 | 38-7848 | .25 | 38-9287 | .10 |
| 36-4096 | 1.75 | 38-5570 | .40 | 38-7871 | .10 | 38-9298 | 1.25 |
| 36-4101 | 1.75 | 38-5606 | 1.70 | 38-7876 | .25 | 38-9339 | .70 |
| 36-4111 | 2.50 | 38-5640 | 6.00 | 38-7878 | .04 | 38-9368 | .30 |
| 36-4112 | 1.75 | 38-5735 | 1.30 | 38-7886 | .05 | 38-9449 | .10 |
| 36-4113 | 1.25 | 38-5740 | .45 | 38-7912 | .30 | 38-9519 | .30 |
| 36-4114 | 1.40 | 38-5749 | .13 | 38-7929 | 10.00 | 38-9542 | .20 |
| 36-4115 | 1.25 | 38-5772 | .03 | 38-7937 | .05 | 38-9562 | .55 |
| 36-4116 | 1.75 | 38-5851 | 1.70 | 38-7963 | .40 | 38-9593 | .35 |
| 36-4117 | 2.50 | 38-5894 | .45 | 38-7968 | 1.80 | 38-9595 | .10 |
| 36-4118 | 2.25 | 38-5911 | .55 | 38-7984 | .25 | 38-9604 | .25 |
| 36-4119 | 1.50 | 38-5935 | 1.70 | 38-8022 | .25 | 38-9607 | .20 |
| 36-4120 | 2.00 | 38-6022 | 1.80 | 38-8030 | .70 | 38-9609 | 10.00 |
| 36-4121 | 1.50 | 38-6038 | .85 | 38-8051 | .50 | 38-9611 | .35 |
| 36-4124 | 1.75 | 38-6044 | .45 | 38-8058 | .12 | 38-9612 | .50 |
| 36-4126 | 1.50 | 38-6049 | .65 | 38-8059 | .10 | 38-9623 | 1.50 |
| 36-4127 | 1.75 | 38-6057 | 5.00 | 38-8060 | .12 | 38-9629 | .15 |
| 36-4128 | 2.00 | 38-6073 | .50 | 38-8061 | .12 | 38-9640 | .35 |
| 36-4129 | 1.75 | 38-6075 | .15 | 38-8067 | 2.20 | 38-9643 | .20 |
| 36-4130 | 1.50 | 38-6248 | .55 | 38-8073 | 1.60 | 38-9649 | 1.00 |
| 36-4132 | 1.25 | 38-6297 | 1.95 | 38-8074 | .40 | 38-9657 | .40 |
| 36-4133 | 2.00 | 38-6306 | .03 | 38-8084 | .35 | 38-9658 | .25 |
| 36-4134 | 1.50 | 38-6353 | .20 | 38-8106 | .60 | 38-9660 | .10 |
| 36-4135 | 1.75 | 38-6449 | .50 | 38-8120 | 1.45 | 38-9661 | .50 |
| 36-4136 | 1.75 | 38-6468 | 1.20 | 38-8142 | .70 | 38-9662 | .10 |
| 36-4137 | 1.50 | 38-6499 | .35 | 38-8198 | .15 | 38-9663 | .60 |
| 36-4146 | 1.50 | 38-6533 | .10 | 38-8210 | 2.40 | 38-9664 | .55 |
| 36-4147 | 2.00 | 38-6551 | .25 | 38-8285 | .12 | 38-9665 | .60 |
| 36-4152 | 1.75 | 38-6605 | 1.50 | 38-8310 | .65 | 38-9689 | 20.00 |
| 36-4158 | 1.50 | 38-6606 | .05 | 38-8369 | .10 | 38-9693 | .15 |
| 36-4161 | 1.75 | 38-6631 | .45 | 38-8370 | .50 | 38-9694 | .20 |
| 36-4162 | 1.25 | 38-6635 | 1.70 | 38-8453 | .30 | 38-9695 | .20 |
| 36-4163 | 1.25 | 38-6636 | 1.70 | 38-8467 | .30 | 38-9696 | .40 |
| 36-4164 | 2.00 | 38-6639 | .15 | 38-8487 | 1.00 | 38-9700 | .20 |
| 36-4165 | 1.25 | 38-6655 | .25 | 38-8517 | .50 | 38-9701 | .20 |
| 36-4166 | 1.50 | 38-6656 | .12 | 38-8532 | .35 | 38-9702 | .30 |
| 36-4167 | 1.25 | 38-6690 | 2.00 | 38-8596 | 1.80 | 38-9704 | 10.50 |
| 36-4168 | 1.25 | 38-6750 | .30 | 38-8619 | .15 | 38-9707 | .35 |
| 36-4169 | 2.00 | 38-6786 | 1.50 | 38-8620 | .40 | 38-9709 | 1.50 |
| 36-4170 | 2.50 | 38-6787 | .20 | 38-8651 | .25 | 38-9711 | .20 |
| 36-4171 | 2.00 | 38-6789 | .50 | 38-8654 | .10 | 38-9712 | .20 |
| 36-4172 | 1.50 | 38-6791 | .60 | 38-8693 | .20 | 38-9713 | .15 |
| 36-4173 | 2.50 | 38-6808 | .25 | 38-8697 | .40 | 38-9716 | .60 |
| 36-4175 | 1.25 | 38-6850 | 1.10 | 38-8744 | .15 | 38-9717 | .15 |
| 36-4176 | 2.00 | 38-6889 | 1.00 | 38-8745 | .10 | 38-9723 | .50 |
| 36-4178 | 2.50 | 38-6921 | .35 | 38-8746 | .15 | 38-9725 | .60 |
| 36-4179 | 1.25 | 38-6972 | .75 | 38-8765 | .05 | 38-9729 | .10 |
| 36-4180 | 1.50 | 38-7077 | .15 | 38-8790 | .20 | 38-9746 | 3.00 |
| 36-4181 | 2.50 | 38-7078 | .15 | 38-8802 | .85 | 38-9758 | .25 |
| 36-4182 | 1.50 | 38-7178 | .02 | 38-8812 | .50 | 38-9759 | .20 |
| 36-4183 | 1.25 | 38-7189 | .40 | 38-8833 | 2.50 | 38-9760 | .75 |
| 36-4187 | 2.00 | 38-7205 | .20 | 38-8844 | .35 | 38-9761 | .40 |
| 36-4188 | 1.75 | 38-7217 | .40 | 38-8849 | .10 | 38-9763 | 1.00 |
| 36-4189 | 2.00 | 38-7240 | .45 | 38-8912 | 10.00 | 38-9764 | 1.50 |
| 36-4190 | 1.50 | 38-7241 | .85 | 38-8923 | .20 | 38-9766 | .50 |
| 36-4192 | 2.50 | 38-7275 | .20 | 38-8925 | .25 | 38-9806 | .15 |
| 36-4193 | 1.25 | 38-7295 | .75 | 38-8932 | 1.10 | 38-9820 | .30 |
| 36-4194 | 1.25 | 38-7334 | .65 | 38-8954 | .35 | 38-9825 | .20 |
| 36-4196 | 2.50 | 38-7401 | .50 | 38-8968 | .45 | 38-9831 | .25 |
| 36-4197 | 1.75 | 38-7402 | .10 | 38-8981 | 7.00 | 38-9838 | .20 |
| 36-4200 | 2.00 | 38-7405 | .35 | 38-9001 | .15 | 38-9839 | .20 |
| 36-4204 | 1.25 | 38-7406 | .12 | 38-9006 | .25 | 38-9842 | .15 |
| 36-4206 | 1.50 | 38-7415 | 1.00 | 38-9064 | 16.00 | 38-9843 | .05 |
| | | 38-7425 | .12 | 38-9100 | 1.20 | 38-9844 | .20 |
| | | 38-7431 | 1.60 | 38-9102 | .12 | 38-9851 | .30 |
| 38-1536 | 4.00 | 38-7436 | .15 | 38-9107 | .15 | 38-9854 | .15 |
| 38-4401 | .35 | 38-7479 | .60 | 38-9120 | .15 | 38-9855 | .35 |
| 38-5105 | .75 | 38-7513 | .50 | 38-9121 | .25 | 38-9856 | .35 |
| 38-5131 | .50 | 38-7516 | .40 | 38-9127 | .50 | 38-9857 | .25 |
| 38-5144 | .30 | 38-7529 | .30 | 38-9128 | 2.00 | 38-9858 | 3.00 |
| 38-5160 | .75 | 38-7602 | .10 | 38-9129 | 2.00 | 38-9859 | 3.00 |
| 38-5206 | 1.60 | 38-7621 | .15 | 38-9130 | 2.00 | 38-9861 | .30 |
| 38-5207 | .30 | 38-7630 | 1.45 | 38-9131 | 2.00 | 38-9865 | .75 |
| 38-5265 | .95 | 38-7631 | 1.50 | 38-9132 | 2.00 | 38-9867 | 1.00 |
| 38-5280 | 1.70 | 38-7693 | 1.80 | 38-9152 | 7.50 | 38-9868 | .10 |
| 38-5296 | .65 | 38-7702 | .15 | 38-9159 | .60 | 38-9869 | .15 |
| 38-5316 | .15 | 38-7703 | .25 | 38-9160 | 1.45 | 38-9870 | .15 |
| 38-5380 | .15 | 38-7706 | .35 | 38-9167 | .15 | 38-9874 | .15 |
| 38-5400 | .02 | 38-7714 | .15 | 38-9232 | .50 | 38-9878 | .20 |
| 38-5424 | .02 | 38-7734 | .35 | 38-9234 | .15 | 38-9880 | 6.50 |
| 38-5432 | .35 | 38-7742 | 1.30 | 38-9247 | .55 | 38-9881 | 6.50 |
| 38-5487 | .55 | 38-7745 | .60 | 38-9253 | 10.50 | 38-9882 | 6.50 |
| 38-5500 | .03 | | | | | | |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 38-9883 | .45 | 40-6391 | .50 | 40-8137 | .15 | 41-3369 | 1.25 |
| 38-9884 | 1.00 | 40-6392 | .60 | 40-8221 | 6.00 | 41-3371 | .35 |
| 38-9886 | .10 | 40-6395 | 1.00 | 40-8417 | 7.50 | 41-3372 | .75 |
| 38-9889 | 3.50 | 40-6396 | 2.75 | 40-8419 | .05 | 41-3374 | 1.75 |
| 38-9890 | 3.50 | 40-6397 | 3.00 | | | 41-3375 | 4.00 |
| 38-9891 | 4.00 | 40-6405 | 1.00 | 41-2013 | 16.50 | 41-3376 | 1.50 |
| 38-9892 | 4.00 | 40-6406 | 1.75 | 41-2015 | 5.50 | 41-3383 | 4.75 |
| 38-9893 | 1.35 | 40-6408 | .40 | 41-2028 | 5.50 | 41-3387 | .15 |
| 38-9894 | 4.25 | 40-6409 | 2.50 | 41-2029 | 5.50 | 41-3389 | .50 |
| 38-9895 | 6.50 | 40-6410 | 2.75 | 41-2030 | 4.95 | 41-3390 | 1.60 |
| 38-9896 | 1.25 | 40-6414 | 8.00 | 41-3017 | 2.70 | 41-3395 | 2.25 |
| 38-9897 | 6.50 | 40-6415 | 8.00 | 41-3035 | 3.00 | 41-3398 | 2.50 |
| 38-9898 | 1.20 | 40-6421 | 2.75 | 41-3042 | .90 | 41-3400 | 4.25 |
| 38-9904 | .15 | 40-6425 | .20 | 41-3044 | 1.75 | 41-3402 | 1.40 |
| 38-9906 | .20 | 40-6427 | .20 | 41-3065 | 2.60 | 41-3409 | 2.00 |
| 38-9908 | .15 | 40-6429 | .50 | 41-3069 | 1.15 | 41-3411 | 2.25 |
| 38-9909 | 2.95 | 40-6433 | 2.25 | 41-3083 | 2.00 | 41-3427 | .65 |
| 38-9910 | 4.95 | 40-6451 | .15 | 41-3084 | 2.50 | 41-3429 | .65 |
| 38-9911 | 2.95 | 40-6452 | .15 | 41-3104 | 3.00 | 41-3430 | .50 |
| 38-9912 | 2.95 | 40-6456 | .20 | 41-3112 | 1.40 | 41-3431 | .50 |
| 38-9913 | 2.95 | 40-6459 | .25 | 41-3118 | 2.25 | 41-3432 | .50 |
| 38-9914 | 3.95 | 40-6460 | .15 | 41-3120 | 5.50 | 41-3433 | .65 |
| 38-9915 | 2.50 | 40-6461 | .25 | 41-3125 | 2.50 | 41-3435 | .65 |
| 38-9917 | 2.50 | 40-6465 | .15 | 41-3131 | .55 | 41-3436 | .10 |
| 38-9918 | .10 | 40-6467 | 1.75 | 41-3143 | 1.25 | 41-3437 | .60 |
| 38-9922 | .35 | 40-6468 | 25.00 | 41-3144 | 1.50 | 41-3441 | .10 |
| 38-9926 | 3.00 | 40-6472 | .40 | 41-3158 | 2.50 | 41-3442 | .10 |
| 38-9931 | 1.75 | 40-6473 | .35 | 41-3167 | 2.00 | 41-3443 | .55 |
| 38-9932 | 3.00 | 40-6474 | .35 | 41-3170 | 2.50 | 41-3445 | .10 |
| 38-9933 | 1.25 | 40-6475 | .60 | 41-3175 | 2.00 | 41-3446 | .20 |
| 38-9935 | 1.00 | 40-6477 | 2.50 | 41-3176 | .95 | 41-3447 | .15 |
| 38-9936 | 4.25 | 40-6478 | 3.00 | 41-3180 | .25 | 41-3448 | .15 |
| 38-9937 | 4.25 | 40-6481 | .30 | 41-3186 | 3.00 | 41-3449 | .15 |
| 38-9938 | .20 | 40-6485 | 1.75 | 41-3189 | 1.50 | 41-3450 | .15 |
| 38-9939 | .35 | 40-6488 | .25 | 41-3191 | .90 | 41-3451 | .15 |
| 38-9940 | 6.50 | 40-6489 | 1.50 | 41-3194 | .20 | 41-3452 | .35 |
| 38-9941 | 1.00 | 40-6490 | 2.25 | 41-3198 | 1.40 | 41-3453 | .60 |
| 38-9943 | 6.50 | 40-6492 | .25 | 41-3202 | .40 | 41-3458 | .15 |
| 38-9944 | 1.25 | 40-6494 | 24.00 | 41-3203 | 1.40 | 41-3465 | .50 |
| 38-9945 | 1.25 | 40-6495 | 2.50 | 41-3204 | 1.20 | 41-3477 | .50 |
| 38-9956 | .30 | 40-6496 | 2.50 | 41-3207 | .30 | 41-3478 | .30 |
| 38-9957 | .60 | 40-6510 | .35 | 41-3210 | .45 | 41-3480 | .25 |
| 38-9968 | 1.25 | 40-6520 | .20 | 41-3214 | .35 | 41-3482 | .10 |
| 38-9977 | 1.00 | 40-6526 | .35 | 41-3220 | .50 | 41-3483 | .15 |
| 38-9978 | 3.50 | 40-6527 | .35 | 41-3222 | 5.25 | 41-3484 | .20 |
| 38-9987 | .50 | 40-6529 | .20 | 41-3223 | .50 | 41-3486 | .55 |
| 38-9985 | 6.00 | 40-6543 | .30 | 41-3230 | 3.50 | 41-3487 | .25 |
| 38-9989 | 2.00 | 40-6546 | .20 | 41-3234 | 2.60 | 41-3488 | .35 |
| 38-9990 | 1.00 | 40-6548 | .25 | 41-3235 | 1.80 | 41-3489 | .30 |
| 38-9992 | 4.50 | 40-6550 | .30 | 41-3236 | .50 | 41-3494 | .15 |
| 38-9994 | 4.50 | 40-6551 | 1.25 | 41-3237 | 1.25 | 41-3495 | 1.10 |
| | | 40-6559 | .25 | 41-3245 | .50 | 41-3496 | .25 |
| 39-6081A | 1.25 | 40-6560 | .25 | 41-3247 | 1.60 | 41-3502 | .20 |
| | | 40-6566 | 1.25 | 41-3250 | 1.20 | 41-3503 | .25 |
| 40-5939 | .75 | 40-6566 | .20 | 41-3253 | .25 | 41-3504 | .35 |
| 40-5945 | .70 | 40-6570 | 1.25 | 41-3255 | 1.80 | 41-3505 | .50 |
| 40-5946 | .75 | 40-6574 | 1.75 | 41-3258 | .50 | 41-3506 | .45 |
| 40-5947 | .80 | 40-6577 | 3.00 | 41-3259 | .50 | 41-3507 | .25 |
| 40-5948 | .80 | 40-6583 | .40 | 41-3260 | 2.00 | 41-3508 | .30 |
| 40-6112 | 5.00 | 40-6586 | .35 | 41-3262 | .90 | 41-3509 | .15 |
| 40-6117 | .90 | 40-6588 | .20 | 41-3275 | 1.10 | 41-3510 | .35 |
| 40-6118 | .90 | 40-6589 | .20 | 41-3276 | .40 | 41-3511 | .35 |
| 40-6124 | .90 | 40-6590 | .30 | 41-3291 | .25 | 41-3514 | .20 |
| 40-6127 | 1.05 | 40-6591 | .20 | 41-3293 | .10 | 41-3516 | .35 |
| 40-6128 | 1.05 | 40-6593 | .30 | 41-3294 | 1.50 | 41-3517 | 1.10 |
| 40-6129 | 1.10 | 40-6594 | .35 | 41-3295 | 1.00 | 41-3522 | .30 |
| 40-6130 | 1.00 | 40-6595 | .45 | 41-3300 | 4.00 | 41-3523 | .30 |
| 40-6132 | 1.10 | 40-6598 | 3.00 | 41-3306 | 1.50 | 41-3526 | .25 |
| 40-6136 | 1.20 | 40-6601 | 1.75 | 41-3308 | 4.25 | 41-3531 | 2.25 |
| 40-6141 | .25 | 40-6604 | .25 | 41-3317 | 1.25 | 41-3534 | .25 |
| 40-6158 | 1.20 | 40-6605 | 1.50 | 41-3321 | .10 | 41-3535 | .30 |
| 40-6175 | .20 | 40-6611 | 1.50 | 41-3324 | .40 | 41-3538 | .25 |
| 40-6183 | 1.20 | 40-6612 | 2.75 | 41-3326 | .20 | 41-3539 | .15 |
| 40-6187 | .20 | 40-6614 | .20 | 41-3327 | .35 | 41-3540 | 1.00 |
| 40-6192 | 13.50 | 40-6619 | .35 | 41-3328 | .20 | 41-3541 | .30 |
| 40-6311 | .25 | 40-6623 | .20 | 41-3329 | .45 | 41-3542 | .35 |
| 40-6364 | 1.25 | 40-6624 | .20 | 41-3329 | .60 | 41-3543 | .25 |
| 40-6365 | 1.75 | 40-6625 | .30 | 41-3336 | .50 | 41-3544 | .15 |
| 40-6369 | .40 | 40-6626 | .30 | 41-3338 | .50 | 41-3545 | 1.00 |
| 40-6374 | 2.00 | 40-6627 | 2.75 | 41-3340 | 3.75 | 41-3546 | .30 |
| 40-6377 | .40 | 40-6628 | 2.75 | 41-3350 | .45 | 41-3547 | .35 |
| 40-6378 | .40 | 40-6640 | .35 | 41-3352 | .90 | 41-3548 | .30 |
| 40-6381 | 1.75 | 40-6641 | .25 | 41-3364 | 1.15 | 41-3549 | .35 |
| 40-6382 | 2.00 | 40-6660 | .35 | 41-3367 | 3.00 | 41-3550 | .80 |
| 40-6383 | 1.50 | 40-6663 | .60 | 41-3368 | 1.00 | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|-------------------|----------|------------|----------|------------|----------|------------|
| 41-3551 | .15 | 42-1150 | .45 | 42-1318 | .40 | 42-1502 | .70 |
| 41-3552 | .40 | 42-1151 | 1.20 | 42-1319 | 1.00 | 42-1503 | .75 |
| 41-3553 | 4.50 | 42-1152 | 1.75 | 42-1320 | 1.45 | 42-1505 | .70 |
| 41-3554 | .75 | 42-1153 | 2.00 | 42-1322 | .80 | 42-1507 | 2.00 |
| 41-3555 | .35 | 42-1156 | .25 | 42-1324 | .85 | 42-1508 | .75 |
| 41-3557 | .25 | 42-1159 | .25 | 42-1325 | .75 | 42-1511 | 3.00 |
| 41-3560 | .30 | 42-1161 | .60 | 42-1326 | 1.00 | 42-1512 | 2.75 |
| 41-3561 | .50 | 42-1163 | 1.50 | 42-1327 | 1.00 | 42-1515 | 3.75 |
| 41-3566 | .60 | 42-1167 | .40 | 42-1331 | .60 | 42-1516 | 1.50 |
| 41-3567 | .15 | 42-1168 | 1.10 | 42-1332 | .90 | 42-1517 | .75 |
| 41-3570 | .40 | 42-1171 | 1.00 | 42-1333 | 1.60 | 42-1520 | 1.00 |
| 41-3571 | .40 | 42-1172 | 1.10 | 42-1334 | .85 | 42-1521 | 1.25 |
| 41-3576 | per 100 ft. 12.00 | 42-1173 | .50 | 42-1335 | 1.15 | 42-1523 | .65 |
| 41-3589 | 1.75 | 42-1174 | .50 | 42-1336 | 1.35 | 42-1524 | .70 |
| 41-3590 | .40 | 42-1180 | 1.00 | 42-1337 | 1.35 | 42-1525 | 5.00 |
| 41-3592 | .25 | 42-1182 | .75 | 42-1338 | 1.35 | 42-1526 | 4.25 |
| 41-3593 | .50 | 42-1183 | .75 | 42-1339 | .75 | 42-1527 | 3.00 |
| 41-3595 | .45 | 42-1184 | 1.00 | 42-1340 | 1.15 | 42-1528 | 2.75 |
| 41-3601 | 2.00 | 42-1186 | .50 | 42-1341 | 1.00 | 42-1530 | 1.50 |
| 41-3606 | .60 | 42-1187 | .50 | 42-1343 | .80 | 42-1531 | .60 |
| 41-3607 | .35 | 42-1188 | 1.75 | 42-1346 | 1.00 | 42-1533 | .50 |
| 41-3610 | .40 | 42-1189 | 1.25 | 42-1347 | 1.00 | 42-1535 | .30 |
| 41-3620 | .25 | 42-1190 | 1.25 | 42-1348 | 1.50 | 42-1536 | 1.25 |
| 41-3627 | .50 | 42-1191 | 1.25 | 42-1351 | 1.00 | 42-1537 | 4.75 |
| 41-8009 | .30 | 42-1192 | .50 | 42-1354 | 1.50 | 42-1545 | .45 |
| | | 42-1194 | .60 | 42-1355 | 1.50 | 42-1548 | 1.00 |
| 42-1000 | .75 | 42-1195 | 1.50 | 42-1356 | 1.50 | 42-1550 | 2.50 |
| 42-1001 | .60 | 42-1196 | 1.00 | 42-1358 | .75 | 42-1551 | .50 |
| 42-1005 | .15 | 42-1197 | .60 | 42-1360 | 1.00 | 42-1552 | 2.00 |
| 42-1013 | .70 | 42-1200 | 1.20 | 42-1361 | 1.00 | 42-1553 | .60 |
| 42-1026 | 1.20 | 42-1202 | 1.50 | 42-1362 | 3.00 | 42-1555 | .90 |
| 42-1027 | .55 | 42-1203 | 1.50 | 42-1363 | 1.00 | 42-1557 | 1.25 |
| 42-1031 | 1.10 | 42-1204 | 1.50 | 42-1366 | .70 | 42-1558 | 3.25 |
| 42-1035 | .80 | 42-1207 | 1.20 | 42-1368 | .35 | 42-1560 | .90 |
| 42-1036 | .75 | 42-1208 | .50 | 42-1369 | .35 | 42-1562 | .30 |
| 42-1037 | 3.20 | 42-1211 | 1.60 | 42-1373 | 1.65 | 42-1564 | 3.00 |
| 42-1038 | .85 | 42-1212 | 1.60 | 42-1374 | .35 | 42-1566 | 1.25 |
| 42-1039 | .45 | 42-1213 | 1.60 | 42-1377 | .75 | 42-1569 | .30 |
| 42-1040 | .65 | 42-1215 | .30 | 42-1378 | .75 | 42-1570 | .90 |
| 42-1042 | 3.60 | 42-1216 | .75 | 42-1383 | .50 | 42-1572 | 9.50 |
| 42-1043 | .30 | 42-1217 | 2.00 | 42-1386 | 1.00 | 42-1574 | .50 |
| 42-1045 | 3.60 | 42-1221 | .45 | 42-1389 | 1.00 | 42-1575 | .90 |
| 42-1046 | .80 | 42-1223 | .12 | 42-1393 | 1.00 | 42-1576 | 3.25 |
| 42-1047 | .65 | 42-1224 | .75 | 42-1399 | .75 | 42-1577 | 2.25 |
| 42-1048 | .90 | 42-1225 | .45 | 42-1404 | 1.50 | 42-1578 | 2.25 |
| 42-1053 | .70 | 42-1226 | 1.20 | 42-1406 | .30 | 42-1579 | 1.25 |
| 42-1054 | .60 | 42-1227 | 1.25 | 42-1408 | 1.25 | 42-1580 | 2.75 |
| 42-1056 | .70 | 42-1228 | 1.60 | 42-1409 | 1.00 | 42-1581 | .75 |
| 42-1057 | 1.00 | 42-1229 | 1.60 | 42-1415 | 1.75 | 42-1582 | 3.25 |
| 42-1062 | 1.10 | 42-1237 | .70 | 42-1419 | 1.50 | 42-1583 | 1.25 |
| 42-1064 | .40 | 42-1241 | 1.00 | 42-1429 | .40 | 42-1584 | .85 |
| 42-1066 | .90 | 42-1242 | 1.00 | 42-1430 | .40 | 42-1585 | 1.40 |
| 42-1068 | 1.50 | 42-1243 | 1.20 | 42-1443 | .75 | 42-1586 | 2.00 |
| 42-1076 | 1.00 | 42-1244 | 1.20 | 42-1444 | .75 | 42-1587 | 4.25 |
| 42-1078 | 3.00 | 42-1245 | 1.20 | 42-1445 | 1.25 | 42-1588 | .85 |
| 42-1079 | 3.50 | 42-1246 | 1.20 | 42-1446 | 3.75 | 42-1589 | 2.00 |
| 42-1080 | .55 | 42-1247 | .60 | 42-1448 | 1.25 | 42-1590 | .80 |
| 42-1083 | 2.00 | 42-1252 | .75 | 42-1449 | .70 | 42-1591 | 3.25 |
| 42-1092 | .90 | 42-1253 | 1.60 | 42-1452 | 5.75 | 42-1592 | 4.25 |
| 42-1093 | 2.25 | 42-1254 | 1.50 | 42-1453 | 3.00 | 42-1593 | 1.25 |
| 42-1095 | 1.50 | 42-1255 | 1.60 | 42-1454 | 1.50 | 42-1594 | .90 |
| 42-1099 | .85 | 42-1257 | 1.00 | 42-1456 | 1.75 | 42-1598 | 1.25 |
| 42-1102 | 3.00 | 42-1258 | 1.25 | 42-1459 | 1.25 | 42-1599 | 1.75 |
| 42-1103 | .80 | 42-1259 | 1.00 | 42-1461 | 3.75 | 42-1600 | 1.00 |
| 42-1104 | 2.50 | 42-1265 | .50 | 42-1462 | 3.75 | 42-1601 | 2.50 |
| 42-1106 | 2.00 | 42-1267 | .75 | 42-1466 | 1.50 | 42-1602 | 2.00 |
| 42-1107 | 1.75 | 42-1268 | .75 | 42-1467 | .75 | 42-1603 | 1.00 |
| 42-1112 | 1.10 | 42-1269 | .75 | 42-1468 | 3.50 | 42-1606 | 3.00 |
| 42-1114 | 2.50 | 42-1273 | .75 | 42-1469 | 1.25 | 42-1608 | 3.25 |
| 42-1117 | .45 | 42-1274 | 1.25 | 42-1471 | 2.75 | 42-1609 | .60 |
| 42-1118 | 2.60 | 42-1277 | .45 | 42-1477 | 2.75 | 42-1610 | .50 |
| 42-1119 | .50 | 42-1279 | 1.80 | 42-1478 | 1.40 | 42-1612 | 1.20 |
| 42-1120 | 2.50 | 42-1281 | .75 | 42-1484 | 3.00 | 42-1613 | 3.25 |
| 42-1121 | 2.00 | 42-1282 | .75 | 42-1485 | 3.00 | 42-1618 | 3 00 |
| 42-1123 | .45 | 42-1283 | .75 | 42-1486 | .50 | 42-1619 | 5.25 |
| 42-1126 | 2.50 | 42-1284 | .75 | 42-1489 | 3.75 | 42-1620 | 4.00 |
| 42-1127 | 2.85 | 42-1287 | .50 | 42-1490 | .95 | 42-1621 | 4.00 |
| 42-1128 | 2.50 | 42-1290 | .75 | 42-1493 | 3.00 | 42-1623 | .60 |
| 42-1129 | .50 | 42-1291 | .50 | 42-1494 | .60 | 42-1624 | .55 |
| 42-1130 | 2.25 | 42-1296 | 2.00 | 42-1495 | 1.00 | 42-1625 | 2.75 |
| 42-1139 | .50 | 42-1300 | .50 | 42-1497 | .35 | 42-1627 | 5.25 |
| 42-1140 | .45 | 42-1314 | .75 | 42-1498 | .60 | 42-1628 | .75 |
| 42-1143 | .75 | 42-1315 | .50 | 42-1499 | .90 | 42-1630 | .25 |
| 42-1145 | .75 | 42-1316 | .60 | 42-1500 | .70 | 42-1631 | 3.25 |
| 42-1149 | .45 | 42-1317 | .30 | 42-1501 | .50 | 42-1632 | 1.00 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|-------------|----------|--------------|
| 42-1633 | .90 | 42-5666 | .35 | 45-1413 | 2.00 | 45-2348 | .60 |
| 42-1635 | 2.50 | 42-5672 | .25 | 45-1416 | 2.00 | 45-2350 | .15 |
| 42-1636 | 1.25 | 42-5694 | .60 | 45-1417 | 35.25 | 45-2351 | 5.00 |
| 42-1637 | 1.75 | 42-5713 | 6.75 | 45-1418 | .30 | 45-2362 | 1.00 |
| 42-1638 | .75 | 42-5714 | .35 | 45-1419 | .35 | 45-2364 | .75 |
| 42-1639 | .25 | 42-5739 | 10.00 | 45-1420 | 1.75 | 45-2367 | .70 |
| 42-1642 | 1.75 | 42-5768 | .35 | 45-1443 | .35 | 45-2373 | .50 |
| 42-1643 | 1.25 | 42-5771 | .15 | 45-1452 | .55 | 45-2375 | 1.00 |
| 42-1644 | 1.00 | 42-5779 | .35 | 45-1453 | .50 | 45-2377 | .10 |
| 42-1645 | 1.50 | 42-5786 | .35 | 45-2000 | 40.00 | 45-2381 | 1.80 |
| 42-1646 | .30 | 42-5797 | .10 | 45-2010 | .10 | 45-2382 | .45 |
| 42-1647 | 1.25 | 42-5861 | .15 | 45-2015 | per 100 .60 | 45-2385 | .50 |
| 42-1648 | 3.00 | 42-5802 | .20 | 45-2016 | .02 | 45-2386 | .20 |
| 42-1650 | .75 | 42-5803 | .45 | 45-2017 | .05 | 45-2388 | .75 |
| 42-1651 | .65 | 42-5813 | .30 | 45-2028 | 3.50 | 45-2389 | .75 |
| 42-1652 | 2.50 | 42-5821 | 2.00 | 45-2042 | 3.50 | 45-2390 | 1.00 |
| 42-1654 | .65 | 42-5826 | .50 | 45-2046 | .05 | 45-2391 | 1.00 |
| 42-1655 | .65 | 42-5837 | 2.75 | 45-2048 | 30.00 | 45-2392 | .75 |
| 42-1656 | 3.50 | 42-5839 | .75 | 45-2052 | 3.50 | 45-2393 | 1.00 |
| 42-1657 | .30 | 42-5840 | 7.25 | 45-2056 | 3.50 | 45-2394 | .75 |
| 42-1658 | 1.75 | 42-5842 | .08 | 45-2060 | .03 | 45-2395 | 1.00 |
| 42-1660 | 12.00 | 42-5843 | 3.25 | 45-2061 | .04 | 45-2396 | .75 |
| 42-1661 | 12.75 | 42-5844 | .40 | 45-2062 | 2.00 | 45-2397 | 1.00 |
| 42-1664 | .60 | 42-5846 | .20 | 45-2080 | 3.50 | 45-2398 | .40 |
| 42-1665 | 1.00 | 42-5848 | 3.00 | 45-2083 | 3.50 | 45-2399 | .45 |
| 42-1668 | 1.40 | 42-5850 | 3.50 | 45-2086 | 3.50 | 45-2401 | .70 |
| 42-1669 | 3.00 | | | 45-2088 | 3.50 | 45-2413 | .06 |
| 42-1670 | 1.00 | 44-1177 | yd. 4.25 | 45-2093 | 1.25 | 45-2424 | .35 |
| 42-1671 | 1.00 | 44-1178 | yd. 3.60 | 45-2094 | 1.00 | 45-2425 | .15 |
| 42-1672 | 2.00 | 44-1180 | yd. 3.00 | 45-2098 | 4.25 | 45-2426 | .25 |
| 42-1673 | 1.50 | 44-1181 | yd. 4.00 | 45-2099 | 3.50 | 45-2429 | .40 |
| 42-1674 | 1.50 | 44-1257 | yd. 2.40 | 45-2107 | .75 | 45-2434 | 1.50 |
| 42-1676 | .40 | 44-1290 | yd. 4.25 | 45-2113 | .16 | 45-2440 | .35 |
| 42-1677 | 3.50 | 44-1422 | yd. 4.50 | 45-2127 | 2.95 | 45-2443 | 2.25 |
| 42-1678 | 1.75 | 44-1423 | yd. 4.50 | 45-2134 | .05 | 45-2444 | .10 |
| 42-1679 | .40 | | | 45-2146 | .65 | 45-2450 | 5.00 |
| 42-1680 | 1.50 | 45-1020 | 2.00 | 45-2150 | .36 | 45-2453 | 15.00 |
| 42-1681 | 5.00 | 45-1030 | .40 | 45-2152 | 1.30 | 45-2454 | .10 |
| 42-1682 | 1.00 | 45-1031 | 2.00 | 45-2153 | .08 | 45-2469 | .21 |
| 42-1683 | 2.25 | 45-1034 | .40 | 45-2154 | .13 | 45-2472 | 2.50 |
| 42-1684 | 2.50 | 45-1035 | 1.75 | 45-2155 | .07 | 45-2473 | .45 |
| 42-1686 | 3.00 | 45-1115 | 4.30 | 45-2156 | .13 | 45-2474 | .60 |
| 42-1687 | 3.00 | 45-1123 | 1.75 | 45-2157 | .25 | 45-2475 | .45 |
| 42-1689 | 7.00 | 45-1135 | 1.75 | 45-2167 | .06 | 45-2476 | 1.75 |
| 42-1692 | 5.00 | 45-1162 | 2.25 | 45-2168 | .06 | 45-2477 | .20 |
| 42-1695 | 3.00 | 45-1175 | .50 | 45-2170 | .02 | 45-2480 | 1.00 |
| 42-1696 | 2.75 | 45-1274 | 3.15 | 45-2171 | .16 | 45-2481 | .50 |
| 42-1697 | 1.00 | 45-1278 | .40 | 45-2182 | 4.85 | 45-2483 | 6.00 |
| 42-1700 | .75 | 45-1281 | .70 | 45-2183 | 4.85 | 45-2490 | .50 |
| 42-1708 | 3.25 | 45-1285 | 1.25 | 45-2189 | 3.50 | 45-2491 | .60 |
| 42-1712 | 1.40 | 45-1317 | 5.65 | 45-2215 | .60 | 45-2497 | 1.30 |
| 42-5016 | .16 | 45-1321 | 3.00 | 45-2216 | .60 | 45-2510 | 8.00 |
| 42-5173 | .50 | 45-1328 | .35 | 45-2217 | 2.50 | 45-2511 | .20 |
| 42-5189 | .50 | 45-1329 | .40 | 45-2218 | .75 | 45-2522 | .50 |
| 42-5191 | .40 | 45-1330 | .40 | 45-2219 | 3.00 | 45-2524 | .45 |
| 42-5302 | .45 | 45-1331 | .40 | 45-2220 | .75 | 45-2540 | 15.75 |
| 42-5333 | .15 | 45-1332 | .50 | 45-2221 | 1.00 | 45-2554 | 1.20 |
| 42-5334 | .10 | 45-1333 | .50 | 45-2222 | 3.50 | 45-2556 | .85 |
| 42-5335 | .25 | 45-1335 | .50 | 45-2227 | 7.50 | 45-2558 | .75 |
| 42-5336 | .45 | 45-1336 | .45 | 45-2228 | .30 | 45-2559 | .05 |
| 42-5342 | .20 | 45-1337 | .20 | 45-2232 | .35 | 45-2579 | 2.65 |
| 42-5355 | .30 | 45-1338 | 1.40 | 45-2233 | .18 | 45-2588 | .35 |
| 42-5362 | .50 | 45-1339 | .45 | 45-2250 | 1.00 | 45-2602 | .90 |
| 42-5365 | .08 | 45-1340 | .25 | 45-2253 | .45 | 45-2607 | 1.50 |
| 42-5394 | .30 | 45-1342 | .75 | 45-2267 | .30 | 45-2608 | 1.40 |
| 42-5404 | .15 | 45-1343 | .30 | 45-2275 | .45 | 45-2610 | .45 |
| 42-5408 | .30 | 45-1344 | 1.10 | 45-2285 | .35 | 45-2612 | .45 |
| 42-5413 | .35 | 45-1350 | .40 | 45-2290 | .45 | 45-2615 | 4.00 |
| 42-5422 | .35 | 45-1351 | .25 | 45-2298 | .02 | 45-2623 | .50 |
| 42-5442 | .30 | 45-1359 | 5.10 | 45-2307 | 3.50 | 45-2649 | .07 |
| 42-5443 | .30 | 45-1363 | qt. 2.00 | 45-2308 | 3.50 | 45-2650 | 7.50 |
| 42-5454 | .40 | 45-1364 | 2.75 | 45-2310 | 6.00 | 45-2653 | 1.75 |
| 42-5460 | .15 | 45-1365 | 7.00 | 45-2312 | 1.00 | 45-2654 | 4.85 |
| 42-5534 | 6.75 | 45-1370 | 11.35 | 45-2315 | 1.20 | 45-2655 | 6.25 |
| 42-5536 | 7.50 | 45-1390 | 6.00 | 45-2316 | .40 | 45-2659 | .05 |
| 42-5539 | .50 | 45-1399 | 10.80 | 45-2324 | 2.50 | 45-2664 | 1.75 |
| 42-5540 | .50 | 45-1400 | .50 | 45-2328 | .75 | 45-2666 | 1.40 |
| 42-5565 | .15 | 45-1401 | .50 | 45-2329 | .50 | 45-2668 | 22.50 |
| 42-5603 | .30 | 45-1402 | .50 | 45-2330 | 1.20 | 45-2669 | 22.50 |
| 42-5606 | .50 | 45-1404 | .35 | 45-2331 | .10 | 45-2685 | 2.50 |
| 42-5612 | .10 | 45-1407 | .35 | 45-2342 | 2.40 | 45-2686 | .25 |
| 42-5616 | .10 | 45-1408 | 9.18 | 45-2344 | .50 | 45-2690 | .05 |
| 42-5617 | .40 | 45-1410 | 7.90 | 45-2345 | .10 | 45-2691 | .05 |
| 42-5635 | .40 | 45-1411 | 1.15 | 45-2347 | .60 | 45-2692 | per 100 1.00 |
| 42-5637 | .35 | | | | | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|--------------|-------------|------------------|----------|--------------|----------|--------------|
| 45-2693 | .05 | 45-6056 | .35 | 54-4006 | 1.50 | 55-0165 | .10 |
| 45-2694 | .10 | 45-6058 | .40 | 54-4007 | 1.50 | 55-0166 | .15 |
| 45-2695 | .25 | 45-6059FA-9 | .10 | 54-4008 | .15 | 55-0167 | .10 |
| 45-2697 | .10 | 45-6061 | .35 | 54-4009 | .10 | 55-0168 | .15 |
| 45-2699 | 45.00 | 45-6066 | .60 | 54-4010 | .60 | 55-0169 | .10 |
| 45-2710 | 3.75 | 45-6067 | .20 | 54-4012 | .10 | 55-0170 | .15 |
| 45-2712 | .15 | 45-6068 | .30 | 54-4013 | .15 | 55-0171 | .10 |
| 45-2715 | .50 | 45-6069 | 2.00 | 54-4015 | .05 | 55-0172 | .05 |
| 45-2717 | .50 | 45-6070 | .35 | 54-4016 | .05 | 55-0173 | .25 |
| 45-2720 | .20 | 45-6078 | .35 | 54-4018 | .04 | 55-0174 | .05 |
| 45-2721 | 7.50 | 45-6080 | .35 | 54-4019 | .03 | 55-0182 | .45 |
| 45-2726 | 1.00 | 45-6082 | .20 | 54-4020 | .02 | 55-0184 | .10 |
| 45-2740 | .15 | 45-6088 | .35 | 54-4023 | .15 | 55-0196 | .10 |
| 45-2741 | .15 | 45-6091 | .35 | 54-4024 | .50 | 55-0197 | .25 |
| 45-2742 | .15 | 45-6092 | .15 | 54-4027 | .50 | 55-0198 | .04 |
| 45-2758 | 1.75 | 45-6093 | .10 | 54-4028 | .45 | 55-0202 | .55 |
| 45-2765 | .40 | 45-6096 | .25 | 54-4029 | .40 | 55-0206 | .10 |
| 45-2766 | 1.25 | 45-6098 | 1.00 | 54-4030 | .50 | 55-0209 | .30 |
| 45-2767 | 1.75 | 45-6100 | .25 | 54-4031 | 1.25 | 55-0240 | .10 |
| 45-2769 | 2.00 | 45-6101 | .25 | 54-4033 | .15 | 55-0260 | .20 |
| 45-2772 | .25 | 45-6102 | 1.00 | 54-4034 | .10 | 55-0266 | .15 |
| 45-2779 | 5.50 | 45-6103 | .05 | 54-4037 | .60 | 55-0270 | .10 |
| 45-2780 | 1.50 | 45-6104 | .25 | 54-4038 | 2.00 | 55-0272 | .10 |
| 45-2781 | .15 | 45-6110 | 3.50 | 54-4041 | .30 | 55-0273 | .03 |
| 45-2785 | .05 | 45-6111 | 2.00 | 54-4042 | 2.00 | 55-0274 | .30 |
| 45-2786 | 1.50 | 45-6112 | 1.00 | 54-4043 | .10 | 55-0275 | .55 |
| 45-2787 | .20 | 45-6113 | .20 | 54-4048 | .05 | 55-0282 | .75 |
| 45-2788 | .10 | 45-6115 | .75 | 54-4052 | .15 | 55-0285 | .03 |
| 45-2789 | .05 | 45-6116 | 1.25 | 54-4053 | .03 | 55-0303 | .15 |
| 45-2790 | .01 | 45-6117 | .90 | 54-4055 | .05 | 55-0304 | .40 |
| 45-2795 | 11.50 | 45-6120 | 2.00 | 54-4056 | .05 | 55-0310 | .40 |
| 45-2798 | .10 | 45-6122 | .50 | 54-4058 | 1.00 | 55-0332 | .20 |
| 45-2799 | 6.50 | 45-6123 | 5.00 | 54-4063 | .10 | 55-0333 | .25 |
| 45-2800 | 6.25 | 45-6124 | 15.00 | 54-4070 | .04 | 55-0334 | per 100 1.50 |
| 45-2801 | .25 | 45-6125 | .60 | 54-4071 | .10 | 55-0358 | .15 |
| 45-2802 | .30 | 45-6126 | .75 | 54-4077 | .25 | 55-0359 | .10 |
| 45-2803 | 5.50 | 45-6128 | .20 | 54-4088 | .25 | 55-0369 | .35 |
| 45-2804 | 5.50 | 45-6129 | .85 | 54-4089 | .15 | 55-0370 | .10 |
| 45-2805 | 15.00 | 45-6130 | .90 | 54-4090 | 2.00 | 55-0371 | .40 |
| 45-2806 | .35 | 45-6132 | .65 | 54-4093 | 1.75 | 55-0372 | .10 |
| 45-2816 | .10 | 45-6137 | .20 | 54-4099 | 2.00 | 55-0373 | .20 |
| 45-2817 | 3.85 | 45-6138 | .20 | 54-4101 | .15 | 55-0385 | .20 |
| 45-2822 | .75 | 45-6139 | .05 | 54-4102 | .15 | 55-0405 | .20 |
| 45-2823 | 1.00 | 45-6142 | .60 | 54-4104 | .15 | 55-0407 | .25 |
| 45-2824 | 1.00 | 45-6143 | .60 | 54-4105 | .15 | 55-0408 | .20 |
| 45-2827 | .10 | 45-6145 | .15 | 54-4106 | .10 | 55-0409 | .05 |
| 45-2828 | .10 | 45-6148 | .35 | 54-4111 | .10 | 55-0412 | .10 |
| 45-2830 | 1.50 | 45-6150 | 1.50 | 54-4111 | .15 | 55-0413 | .15 |
| 45-2831 | .85 | 45-6151 | .65 | 54-4118 | .15 | 55-0426 | .25 |
| 45-2833 | 1.75 | 45-6157 | 9.00 | 54-4125 | .15 | 55-0428 | .15 |
| 45-2834 | 1.50 | 45-6159 | 9.00 | 54-4126 | .15 | 55-0431 | .25 |
| 45-2835 | 1.75 | 45-6160 | 7.75 | 54-4135 | .15 | 55-0438 | .15 |
| 45-2836 | .10 | 45-6164 | .95 | 54-4136 | .15 | 55-0440 | .10 |
| 45-2837 | 1.25 | 45-6165 | 1.25 | 54-4137 | .15 | 55-0441 | .15 |
| 45-2838 | 1.00 | 45-6166 | 7.25 | 54-4143 | .15 | 55-0443 | .15 |
| 45-2839 | 2.00 | 45-6167 | 7.50 | 54-4148 | .25 | 55-0445 | .20 |
| 45-2840 | 4.50 | 45-6168 | 7.50 | | | 55-0446 | .20 |
| 45-2844 | .50 | 45-6169 | 5.75 | 55-0004 | .05 | 55-0448 | .05 |
| 45-2848 | .10 | 45-6170 | 6.00 | 55-0005 | .10 | 55-0449 | per 100 2.00 |
| 45-2849 | .50 | 45-6188 | 8.25 | 55-0010 | .30 | 55-0474 | .10 |
| 45-2852 | 1.00 | 45-6189 | 8.25 | 55-0011 | .20 | 55-0482 | .10 |
| 45-2853 | 1.00 | 45-6191 | 1.50 | 55-0013 | .15 | 55-0483 | .05 |
| 45-2855 | 5.50 | | | 55-0014 | 1.25 | 55-0486 | .25 |
| 45-2890 | 5.50 | 49-000000 | per 100 ft. .95 | 55-0018 | .15 | 55-0499 | .25 |
| 45-2900 | .20 | 49-002000 | per 100 ft. .95 | 55-0020 | .35 | 55-0501 | .15 |
| 45-2903 | 1.25 | 49-003000 | per 100 ft. .95 | 55-0021 | .15 | 55-0547 | .15 |
| 45-2904 | per 100 2.50 | 49-004000 | per 100 ft. .95 | 55-0044 | .15 | 55-0572 | .15 |
| 45-2914 | 7.26 | 49-005000 | per 100 ft. .95 | 55-0057 | .05 | 55-0575 | .10 |
| 45-2926 | 8.25 | 49-006000 | per 100 ft. .95 | 55-0062 | per 100 1.50 | 55-0581 | .30 |
| 45-2927 | 2.95 | 49-009000 | per 100 ft. .95 | 55-0066 | .10 | 55-0587 | .10 |
| 45-2928 | 8.00 | 49-020000 | per 100 ft. 1.25 | 55-0068 | .25 | 55-0588 | .15 |
| 45-2930 | 3.00 | 49-021000 | per 100 ft. 1.25 | 55-0089 | .10 | 55-0589 | .15 |
| 45-2933 | 15.00 | 49-022000 | per 100 ft. 1.25 | 55-0100 | .05 | 55-0590 | .15 |
| 45-2943 | 1.50 | 49-023000 | per 100 ft. 1.25 | 55-0102 | .20 | 55-0592 | .25 |
| 45-6002 | .10 | 49-025000 | per 100 ft. 1.25 | 55-0109 | .15 | 55-0593 | .15 |
| 45-6034 | .30 | 49-026000 | per 100 ft. 1.25 | 55-0110 | .15 | 55-0608 | .03 |
| 45-6035 | .40 | 49-027000 | per 100 ft. 1.25 | 55-0117 | .35 | 55-0610 | .10 |
| 45-6036 | pr. .40 | 49-029000 | per 100 ft. 1.25 | 55-0119 | .10 | 55-0614 | .10 |
| 45-6038 | .90 | 49-140000 | per 100 ft. 1.25 | 55-0120 | .60 | 55-0617 | .10 |
| 45-6039 | .04 | 49-142000 | per 100 ft. 5.00 | 55-0129 | .10 | 55-0618 | .20 |
| 45-6040 | per 100 1.50 | | | 55-0137 | .03 | 55-0619 | .20 |
| 45-6045 | .15 | 54-4002 | .10 | 55-0145 | .01 | 55-0631 | .05 |
| 45-6051 | .30 | 54-4003 | 1.50 | 55-0157 | .25 | 55-0633 | .20 |
| 45-6052 | .25 | 54-4004 | .15 | 55-0162 | .30 | 55-0636 | .10 |
| 45-6053 | .35 | 54-4005 | .10 | 55-0164 | .15 | 55-0641 | .30 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|--------------|----------|--------------|-------------|--------------|-------------|-------------|
| 55-0642 | .20 | 55-0905 | .05 | 55-1235 | .05 | 56-1406 | per 100 .90 |
| 55-0651 | .10 | 55-0935 | .15 | 55-1248 | .02 | 56-1408 | .01 |
| 55-0652 | .15 | 55-0936 | .15 | 55-1246 | .15 | 56-1411 | .10 |
| 55-0653 | .10 | 55-0937 | .25 | 55-1247 | .25 | 56-1412 | .15 |
| 55-0655 | .04 | 55-0945 | .15 | 55-1251 | .15 | 56-1415 | .35 |
| 55-0679 | .15 | 55-0946 | .10 | 55-1266 | .15 | 56-1418 | .15 |
| 55-0683 | .10 | 55-0950 | .25 | 55-1297 | .25 | 56-1420 | .45 |
| 55-0684 | .10 | 55-0955 | per 100 3.00 | 55-1300 | .40 | 56-1430 | .15 |
| 55-0685 | .10 | 55-0957 | .10 | 55-1320 | .50 | 56-1446FA-3 | .10 |
| 55-0686 | .60 | 55-0958 | .50 | 55-1348 | .35 | 56-1452 | .05 |
| 55-0688 | .15 | 55-0960 | .45 | 55-1350 | .60 | 56-1453 | 1.50 |
| 55-0695 | .05 | 55-0961 | .45 | 55-1351 | .40 | 56-1455 | .10 |
| 55-0697 | .15 | 55-0993 | .30 | 55-1353 | .20 | 56-1464 | .10 |
| 55-0698 | .05 | 55-1004 | .02 | 55-1354 | .05 | 56-1465 | .20 |
| 55-0699 | .10 | 55-1012 | .35 | 55-1355 | .10 | 56-1466 | .02 |
| 55-0700 | .25 | 55-1017 | per 100 .75 | 55-1366 | .10 | 56-1470FA-3 | .10 |
| 55-0704 | .10 | 55-1023 | .02 | 55-1371 | .65 | 56-1479 | .10 |
| 55-0705 | .20 | 55-1033 | .02 | 55-1388 | .30 | 56-1480 | .10 |
| 55-0706 | .20 | 55-1034 | .35 | 55-1389 | .10 | 56-1481 | .05 |
| 55-0707 | .40 | 55-1037 | .40 | 55-1392 | .20 | 56-1484 | .15 |
| 55-0713 | .10 | 55-1044 | .03 | 55-1407 | .02 | 56-1485FA3 | .02 |
| 55-0714 | .10 | 55-1045 | .20 | 55-1408 | .15 | 56-1486 | .15 |
| 55-0729 | .10 | 55-1047 | .15 | 55-1409 | .10 | 56-1487 | .05 |
| 55-0730 | per 100 2.50 | 55-1049 | .10 | | | 56-1488 | .10 |
| 55-0731 | per 100 1.25 | 55-1050 | .03 | 56-1011 | .10 | 56-1494 | .35 |
| 55-0732 | .20 | 55-1052 | .15 | 56-1026FA-3 | .04 | 56-1505 | .02 |
| 55-0733 | .20 | 55-1054 | .10 | 56-1029 | per 100 .40 | 56-1507 | 2.00 |
| 55-0734 | .05 | 55-1055 | .10 | 56-1033 | .15 | 56-1508 | 1.00 |
| 55-0735 | .05 | 55-1056 | .10 | 56-1034 | .05 | 56-1509 | 2.50 |
| 55-0738 | .05 | 55-1058 | .15 | 56-1036 | .10 | 56-1516 | .10 |
| 55-0740 | .10 | 55-1059 | .15 | 56-1037 | .20 | 56-1517 | .03 |
| 55-0743 | .15 | 55-1060 | .10 | 56-1039 | .35 | 56-1525 | .40 |
| 55-0744 | .15 | 55-1061 | .05 | 56-1040 | .40 | 56-1526 | .05 |
| 55-0745 | .20 | 55-1062 | .02 | 56-1042 | .10 | 56-1529 | .35 |
| 55-0748 | .40 | 55-1063 | .02 | 56-1051 | .02 | 56-1532 | .15 |
| 55-0749 | .40 | 55-1064 | .10 | 56-1072 | .08 | 56-1539 | .35 |
| 55-0750 | .20 | 55-1065 | .05 | 56-1073 | .03 | 56-1547 | .55 |
| 55-0751 | .35 | 55-1067 | .15 | 56-1074 | .40 | 56-1548 | .10 |
| 55-0754 | 1.00 | 55-1068 | .02 | 56-1091 | .03 | 56-1565 | .05 |
| 55-0756 | .01 | 55-1069 | .06 | 56-1092 | 2.25 | 56-1566 | .10 |
| 55-0757 | per 100 1.50 | 55-1071 | .15 | 56-1104 | 2.75 | 56-1567 | .02 |
| 55-0758 | .25 | 55-1072 | .10 | 56-1112 | 1.50 | 56-1637FA4 | .03 |
| 55-0759 | .15 | 55-1073 | .05 | 56-1113 | .30 | 56-1639 | .25 |
| 55-0760 | .25 | 55-1074 | .10 | 56-1118 | .05 | 56-1645 | .10 |
| 55-0761 | .25 | 55-1075 | .25 | 56-1119 | .10 | 56-1646 | .10 |
| 55-0763 | .10 | 55-1078 | .20 | 56-1130 | .10 | 56-1647 | .10 |
| 55-0764 | .15 | 55-1080 | .10 | 56-1131 | per 100 1.00 | 56-1651 | .15 |
| 55-0766 | .15 | 55-1084 | .10 | 56-1132 | .02 | 56-1659 | .02 |
| 55-0774 | .10 | 55-1089 | .02 | 56-1135 | .01 | 56-1663 | .10 |
| 55-0775 | .10 | 55-1091 | per 100 .50 | 56-1156 | .01 | 56-1670 | .05 |
| 55-0776 | .10 | 55-1103 | .02 | 56-1161 | .02 | 56-1673 | .15 |
| 55-0777 | .35 | 55-1104 | .15 | 56-1176 | .20 | 56-1686 | .05 |
| 55-0781 | .15 | 55-1111 | .15 | 56-1180 | .20 | 56-1689 | .03 |
| 55-0782 | .15 | 55-1117 | .15 | 56-1185 | .05 | 56-1710 | .05 |
| 55-0783 | .10 | 55-1118 | .15 | 56-1193 | .10 | 56-1711 | .15 |
| 55-0784 | .10 | 55-1122 | .10 | 56-1194 | .05 | 56-1734 | .10 |
| 55-0785 | .05 | 55-1125 | .15 | 56-1222 | 2.50 | 56-1736 | .15 |
| 55-0786 | .02 | 55-1138 | .03 | 56-1232 | .10 | 56-1775 | .10 |
| 55-0788 | .40 | 55-1140 | 1.25 | 56-1238 | per 100 1.00 | 56-1776 | .10 |
| 55-0789 | .20 | 55-1141 | .20 | 56-1240 | .90 | 56-1777 | .10 |
| 55-0791 | .20 | 55-1143 | .35 | 56-1252 | .45 | 56-1793 | .25 |
| 55-0792 | .05 | 55-1144 | .02 | 56-1255 | .25 | 56-1802 | .03 |
| 55-0793 | .15 | 55-1151 | .50 | 56-1257 | .45 | 56-1804FA33 | .15 |
| 55-0811 | per 100 1.25 | 55-1153 | per 100 .75 | 56-1259 | .10 | 56-1815 | .15 |
| 55-0821 | .05 | 55-1154 | .60 | 56-1260 | .15 | 56-1819 | .20 |
| 55-0822 | .01 | 55-1155 | .01 | 56-1261 | .05 | 56-1822 | .15 |
| 55-0824 | .01 | 55-1156 | .01 | 56-1295 | .10 | 56-1826 | .02 |
| 55-0826 | per 100 .50 | 55-1157 | .15 | 56-1296 | .10 | 56-1832 | .60 |
| 55-0827 | .03 | 55-1159 | .10 | 56-1305 | 1.50 | 56-1848 | .02 |
| 55-0828 | .02 | 55-1162 | .02 | 56-1306 | .02 | 56-1856 | .15 |
| 55-0830 | .02 | 55-1165 | .45 | 56-1322 | .05 | 56-1863 | .20 |
| 55-0840 | .45 | 55-1166 | .15 | 56-1326 | .10 | 56-1866 | .01 |
| 55-0841 | .50 | 55-1173 | .25 | 56-1330 | .10 | 56-1875 | .15 |
| 55-0844 | .05 | 55-1174 | .15 | 56-1333 | .10 | 56-1876 | .02 |
| 55-0846 | .10 | 55-1177 | per 100 2.50 | 56-1337 | .10 | 56-1877 | .02 |
| 55-0856 | .02 | 55-1181 | .03 | 56-1345 | .10 | 56-1880 | .05 |
| 55-0865 | .05 | 55-1189 | .03 | 56-1346 | .02 | 56-1881 | .02 |
| 55-0871 | .25 | 55-1191 | .10 | 56-1356 | .20 | 56-1882FA5 | .05 |
| 55-0872 | .25 | 55-1194 | .60 | 56-1360 | .30 | 56-1888 | .06 |
| 55-0881 | .15 | 55-1195 | .25 | 56-1364 | .75 | 56-1893 | .60 |
| 55-0890 | .05 | 55-1196 | .50 | 56-1376FA-3 | .05 | 56-1907FA3 | .03 |
| 55-0892 | .10 | 55-1199 | .02 | 56-1379 | .05 | 56-1918 | .10 |
| 55-0893 | .10 | 55-1200 | .35 | 56-1383 | .15 | 56-1926 | .05 |
| 55-0894 | .25 | 55-1231 | .20 | 56-1385 | .03 | 56-1956 | .02 |
| 55-0904 | .05 | 55-1232 | .35 | 56-1387 | .01 | 56-1958 | .25 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|--------------|------------|--------------|------------|--------------|------------|--------------|------------|
| 56-1966 | .50 | 57-0249 | .90 | 57-0603 | .10 | 57-1037FA34 | .20 |
| 56-1968 | .05 | 57-0250 | .90 | 57-0604 | .10 | 57-1039 | .05 |
| 56-1983 | .50 | 57-0252FC-34 | .40 | 57-0605 | .10 | 57-1042 | .10 |
| 56-1984 | .60 | 57-0261FC-34 | .40 | 57-0607 | 1.50 | 57-1043FA-17 | .15 |
| 56-2014 | .05 | 57-0264 | .40 | 57-0609 | .03 | 57-1043FA-32 | .10 |
| 56-2028 | .10 | 57-0265 | .40 | 57-0610 | .07 | 57-1044 | .02 |
| 56-2036 | .10 | 57-0273FA-28 | .50 | 57-0613 | .25 | 57-1053 | .05 |
| 56-2044 | .05 | 57-0274FA-28 | .50 | 57-0614 | .02 | 57-1062FA-3 | .20 |
| 56-2059 | .03 | 57-0278 | .20 | 57-0615 | .04 | 57-1071 | 3.00 |
| 56-2076 | .15 | 57-0294 | .05 | 57-0617 | .03 | 57-1072 | .45 |
| 56-2112 | .05 | 57-0318 | .20 | 57-0631 | 1.00 | 57-1073 | .05 |
| 56-2134 | .15 | 57-0319 | .10 | 57-0638 | .08 | 57-1074 | .05 |
| 56-2159 | .15 | 57-0320FA-1 | .10 | 57-0642 | 1.00 | 57-1076 | .10 |
| 56-2178 | .10 | 57-0321 | 3.00 | 57-0647 | .05 | 57-1079 | .10 |
| 56-2215 | .10 | 57-0324 | .02 | 57-0651 | .25 | 57-1082 | .10 |
| 56-2228 | .20 | 57-0327 | .20 | 57-0660 | .25 | 57-1084 | .10 |
| 56-2233 | .50 | 57-0329 | .04 | 57-0661 | 1.50 | 57-1087 | .10 |
| 56-2272 | .15 | 57-0330 | .02 | 57-0662 | 1.50 | 57-1089 | .20 |
| 56-2289 | .15 | 57-0331FA-11 | .05 | 57-0664 | .90 | 57-1096FA-7 | .10 |
| 56-2331 | .15 | 57-0332FA-1 | .05 | 57-0667 | .10 | 57-1096FA-17 | .10 |
| 56-6015 | .45 | 57-0333FA-4 | .05 | 57-0670 | 1.75 | 57-1107 | .10 |
| 56-6016FA-3 | .15 | 57-0344 | .05 | 57-0693 | .25 | 57-1110FA-7 | .20 |
| 56-6017 | per 100 | 57-0345 | .20 | 57-0700 | .10 | 57-1110FA-17 | .30 |
| 56-6025 | .03 | 57-0361 | .10 | 57-0715FA3 | .02 | 57-1121 | .05 |
| 56-6027 | .02 | 57-0368FA-8 | .45 | 57-0716 | .15 | 57-1123 | .02 |
| 56-6028 | .02 | 57-0369FA-8 | .45 | 57-0720FA-3 | .15 | 57-1125FC1 | .30 |
| 56-6032FA-3 | .10 | 57-0372 | 2.00 | 57-0728 | 1.50 | 57-1127FA4 | .05 |
| 56-6033 | .25 | 57-0373FA-8 | .25 | 57-0734 | .10 | 57-1129 | .10 |
| 56-6043 | .15 | 57-0384 | 1.50 | 57-0742 | .03 | 57-1131 | .15 |
| 56-6045 | .05 | 57-0387 | .75 | 57-0753FA-3 | .10 | 57-1135 | .15 |
| 56-6051 | .50 | 57-0389 | .20 | 57-0754FC-1 | .15 | 57-1137 | .10 |
| 56-6052 | .10 | 57-0394 | 1.00 | 57-0761 | .10 | 57-1141 | .35 |
| 56-6056FA-9 | .10 | 57-0408FA-3 | .20 | 57-0762FA-3 | .10 | 57-1144 | .02 |
| 56-6065 | .35 | 57-0409FA-3 | .02 | 57-0766FC-36 | 1.25 | 57-1145 | .02 |
| 56-6066 | .15 | 57-0410 | .05 | 57-0769 | .35 | 57-1146 | .05 |
| 56-6070 | .10 | 57-0413FA-1 | .05 | 57-0770 | 1.50 | 57-1147 | .20 |
| 56-6080 | .15 | 57-0415 | .03 | 57-0772 | .35 | 57-1154 | .10 |
| 56-6082 | .02 | 57-0416 | .05 | 57-0773 | .35 | 57-1170 | .05 |
| 56-6084 | .03 | 57-0417FA-1 | .05 | 57-0776 | .30 | 57-1183 | .60 |
| 56-6086 | .15 | 57-0425 | .90 | 57-0794 | .10 | 57-1185 | .02 |
| 56-6087 | .15 | 57-0432 | .15 | 57-0796 | .05 | 57-1196 | .05 |
| 56-6097 | .20 | 57-0434 | .05 | 57-0798 | .15 | 57-1197 | .05 |
| 56-6098 | .20 | 57-0436 | .15 | 57-0800FA-1 | .15 | 57-1198FA3 | .05 |
| 56-6109 | .15 | 57-0443FA-1 | .15 | 57-0802 | .10 | 57-1199FA3 | .05 |
| 56-6110 | .35 | 57-0450 | .01 | 57-0805 | .10 | 57-1201FA3 | .20 |
| 56-6111 | .40 | 57-0452 | .15 | 57-0812FC-36 | .15 | 57-1202FA3 | .05 |
| 56-6120 | per 100 | 57-0456 | .02 | 57-0822 | .04 | 57-1203FA3 | .03 |
| 56-6132 | .20 | 57-0457 | .20 | 57-0836FA3 | .40 | 57-1217 | .50 |
| 56-6136 | .15 | 57-0458 | .15 | 57-0857FA-1 | .15 | 57-1218 | .10 |
| | | 57-0465FA-1 | .01 | 57-0858 | 1.35 | 57-1128 | .20 |
| 57-0001 | .30 | 57-0467 | .90 | 57-0859 | .25 | 57-1228FA3 | .20 |
| 57-0007 | .15 | 57-0468 | 1.00 | 57-0860 | .05 | 57-1233 | .15 |
| 57-0008 | .25 | 57-0472FA-8 | .05 | 57-0868FC-29 | .10 | 57-1234 | .20 |
| 57-0024 | .04 | 57-0473 | 1.60 | 57-0869FA3 | .05 | 57-1235 | .05 |
| 57-0025 | .05 | 57-0479FA-3 | .03 | 57-0871FA3 | .10 | 57-1237 | .02 |
| 57-0026FA-1 | .15 | 57-0480FA-1 | .20 | 57-0874 | .05 | 57-1240 | .02 |
| 57-0029 | .05 | 57-0482 | .20 | 57-0875 | .15 | 57-1247 | 2.50 |
| 57-0050 | .10 | 57-0485 | .02 | 57-0885 | .10 | 57-1248 | 1.50 |
| 57-0052 | .10 | 57-0486 | .10 | 57-0891 | .05 | 57-1249 | 1.80 |
| 57-0055 | .15 | 57-0487 | .10 | 57-0892 | .08 | 57-1250 | .10 |
| 57-0064FC-34 | .06 | 57-0489 | per 100 | 57-0894 | .10 | 57-1251 | .20 |
| 57-0066 | .60 | 57-0491 | 1.25 | 57-0896 | .30 | 57-1252 | .05 |
| 57-0112 | .90 | 57-0492 | .60 | 57-0897 | .02 | 57-1253 | .05 |
| 57-0116 | .90 | 57-0493 | .04 | 57-0900 | .10 | 57-1254 | .10 |
| 57-0117 | .90 | 57-0501 | .30 | 57-0922FA-8 | .20 | 57-1255 | .10 |
| 57-0131 | 1.80 | 57-0502 | .30 | 57-0923 | .20 | 57-1272 | 2.50 |
| 57-0133 | .05 | 57-0508FA-3 | .15 | 57-0962 | .10 | 57-1278 | .20 |
| 57-0142 | .10 | 57-0509FA-7 | .25 | 57-0964 | .05 | 57-1294 | .40 |
| 57-0151 | .05 | 57-0519 | .30 | 57-0968FA3 | .05 | 57-1298FA3 | .02 |
| 57-0153 | .05 | 57-0528 | .05 | 57-0972 | .05 | 57-1300FC45 | .10 |
| 57-0159 | per 100 | 57-0547 | .05 | 57-0984 | .02 | 57-1301FC46 | .15 |
| 57-0166 | .10 | 57-0548 | .20 | 57-0992 | .05 | 57-1302 | .05 |
| 57-0169 | 1.50 | 57-0550 | .05 | 57-0996 | .15 | 57-1303 | .10 |
| 57-0185 | .10 | 57-0554 | 1.25 | 57-1001 | .05 | 57-1304FA3 | .10 |
| 57-0191FA-1 | .03 | 57-0556 | .10 | 57-1002FA3 | .15 | 57-1306 | .35 |
| 57-0201 | .05 | 57-0557FA-1 | .10 | 57-1004 | .05 | 57-1324 | .25 |
| 57-0205 | .08 | 57-0558FA-3 | .05 | 57-1005 | .05 | 57-1331 | .05 |
| 57-0206 | .12 | 57-0559FA-8 | .20 | 57-1006FA3 | .50 | 57-1332FC46 | 1.25 |
| 57-0220 | .03 | 57-0563 | .15 | 57-1019FA3 | .03 | 57-1333 | .25 |
| 57-0221 | .90 | 57-0585 | .15 | 57-1020FC-1 | 1.25 | 57-1335 | .02 |
| 57-0227FA-7 | .25 | 57-0586 | .15 | 57-1021FC-1 | .60 | 57-1338 | .10 |
| 57-0228 | .02 | 57-0590 | .10 | 57-1022FA3 | .25 | 57-1340FA3 | .10 |
| 57-0230 | .40 | 57-0591 | .15 | 57-1023FC-1 | .60 | 57-1348FC48 | .25 |
| 57-0238 | .35 | 57-0592 | .40 | 57-1024FC-1 | .75 | 57-1353 | .05 |
| 57-0244 | .15 | 57-0598 | .30 | 57-1030 | per 100 | 57-1354 | .40 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|-------------|--------------|-------------|--------------|------------|------------|-----------|------------|
| 57-1359 | .15 | 57-1646 | .05 | 57-2018 | .35 | 60-180127 | .30 |
| 57-1360 | .20 | 57-1648FE11 | .04 | 57-2033 | .10 | 60-180137 | .25 |
| 57-1362 | per 100 2.00 | 57-1649 | .05 | 57-2069 | .20 | 60-210134 | .25 |
| 57-1363 | .10 | 57-1650 | .05 | 57-2100 | .02 | 60-210137 | .25 |
| 57-1364 | .35 | 57-1651 | .05 | 57-2102 | .03 | 60-216324 | .25 |
| 57-1366 | .20 | 57-1652 | .05 | 57-2113 | .05 | 60-220134 | .35 |
| 57-1370 | .05 | 57-1653 | .03 | 57-2130 | .10 | 60-220324 | .40 |
| 57-1381 | .05 | 57-1659 | .15 | 57-2135 | 1.00 | 60-230124 | .45 |
| 57-1384 | 1.00 | 57-1665 | .20 | 57-2143 | .20 | 60-230334 | .45 |
| 57-1385 | 1.00 | 57-1668FA3 | .05 | 57-2176 | .10 | 60-235124 | .45 |
| 57-1386 | 1.00 | 57-1669 | per 100 1.50 | 57-2178 | 1.75 | 60-245124 | .45 |
| 57-1387 | .03 | 57-1678FA8 | .10 | 57-2188FA8 | 1.50 | 60-250324 | .55 |
| 57-1389FC45 | 1.25 | 57-1679 | .25 | 57-2200 | 1.40 | | |
| 57-1390 | .40 | 57-1682FA8 | .25 | 57-2202 | .03 | 61-0003 | .40 |
| 57-1394FC45 | 1.25 | 57-1683FA8 | .25 | 57-2211 | 1.00 | 61-0007 | .20 |
| 57-1402 | .35 | 57-1688FA3 | .05 | 57-2216 | 1.00 | 61-0008 | 1.25 |
| 57-1403 | .10 | 57-1691 | .04 | 57-2217 | .25 | 61-0009 | 1.60 |
| 57-1404FA3 | .05 | 57-1692 | .05 | 57-2238 | .02 | 61-0010 | .35 |
| 57-1408 | .20 | 57-1693 | .10 | 57-2239 | 1.20 | 61-0011 | .35 |
| 57-1411 | .03 | 57-1694 | .10 | 57-2240 | 1.20 | 61-0012 | 1.75 |
| 57-1413 | .35 | 57-1696 | per 100 .90 | 57-2241 | 1.20 | 61-0013 | 1.25 |
| 57-1417 | .04 | 57-1700 | .01 | 57-2249 | .15 | 61-0014 | .15 |
| 57-1421 | .10 | 57-1701 | .05 | 57-5001 | .80 | 61-0016 | 1.25 |
| 57-1422 | .05 | 57-1704 | 1.75 | 57-5002 | .80 | 61-0017 | 1.35 |
| 57-1423 | .03 | 57-1710 | .10 | | | 61-0018 | 1.60 |
| 57-1425 | .05 | 57-1727FA8 | .20 | 60-005157 | .15 | 61-0019 | 1.40 |
| 57-1427 | .25 | 57-1728 | .05 | 60-006177 | .15 | 61-0020 | .15 |
| 57-1428 | per 100 .75 | 57-1729 | .35 | 60-008337 | .15 | 61-0022 | 1.00 |
| 57-1429 | .02 | 57-1731 | .05 | 60-010137 | .15 | 61-0023 | .15 |
| 57-1433 | .05 | 57-1745 | .25 | 60-010157 | .15 | 61-0024 | 1.50 |
| 57-1434 | 1.20 | 57-1746 | .10 | 60-010327 | .20 | 61-0026 | .30 |
| 57-1461 | .20 | 57-1749FC51 | 1.25 | 60-010337 | .15 | 61-0027 | .40 |
| 57-1463 | .02 | 57-1750 | .25 | 60-011327 | .20 | 61-0028 | 1.25 |
| 57-1468FA3 | .02 | 57-1769FA3 | .02 | 60-012327 | .20 | 61-0030 | .30 |
| 57-1475FA8 | .40 | 57-1772 | .02 | 60-015327 | .20 | 61-0031 | .40 |
| 57-1477 | .25 | 57-1774FA3 | .10 | 60-015337 | .15 | 61-0033 | .20 |
| 57-1480 | 2.50 | 57-1775 | .01 | 60-015357 | .15 | 61-0034 | .20 |
| 57-1483 | .01 | 57-1776 | .05 | 60-018317 | .20 | 61-0035 | .35 |
| 57-1524 | 1.10 | 57-1780FA8 | .25 | 60-020127 | .20 | 61-0036 | .25 |
| 57-1525 | 1.30 | 57-1782FA8 | 1.25 | 60-020327 | .20 | 61-0037 | .50 |
| 57-1526 | 1.50 | 57-1784FC58 | 2.50 | 60-023317 | .20 | 61-0038 | .15 |
| 57-1538 | .02 | 57-1789FA3 | .05 | 60-025327 | .20 | 61-0039 | .20 |
| 57-1541 | .25 | 57-1792FA3 | .05 | 60-025337 | .15 | 61-0040 | .50 |
| 57-1542 | .25 | 57-1794 | .05 | 60-030127 | .20 | 61-0042 | .40 |
| 57-1549FA8 | 1.00 | 57-1797 | .10 | 60-030137 | .15 | 61-0043 | .35 |
| 57-1550FC51 | 2.25 | 57-1801 | 1.50 | 60-030337 | .15 | 61-0044 | .20 |
| 57-1555FC51 | .15 | 57-1804 | 1.75 | 60-035157 | .15 | 61-0047 | .40 |
| 57-1559FA8 | .25 | 57-1805 | 1.35 | 60-040117 | .20 | 61-0048 | .20 |
| 57-1560FA3 | .10 | 57-1806 | 1.25 | 60-050137 | .15 | 61-0049 | .25 |
| 57-1561FA3 | .05 | 57-1836 | .06 | 60-015137 | .15 | 61-0050 | 1.25 |
| 57-1566 | 3.00 | 57-1838 | .40 | 60-050327 | .20 | 61-0052 | .20 |
| 57-1567 | 1.10 | 57-1839 | .15 | 60-060127 | .20 | 61-0053 | .15 |
| 57-1568 | 1.20 | 57-1840 | .01 | 60-090327 | .20 | 61-0054 | .30 |
| 57-1569 | 1.10 | 57-1841 | .05 | 60-070437 | .20 | 61-0055 | .15 |
| 57-1570 | 1.30 | 57-1846FC52 | 2.00 | 60-060327 | .20 | 61-0056 | .25 |
| 57-1571 | 1.10 | 57-1847 | .01 | 60-110137 | .15 | 61-0059 | .35 |
| 57-1572 | 1.30 | 57-1849 | .20 | 60-110157 | .15 | 61-0061 | .15 |
| 57-1578 | .05 | 57-1850 | .25 | 60-110327 | .20 | 61-0063 | 1.25 |
| 57-1582FA8 | 1.25 | 57-1860 | .15 | 60-110337 | .15 | 61-0064 | .15 |
| 57-1585FA3 | .05 | 57-1862 | .25 | 60-110457 | .15 | 61-0065 | .20 |
| 57-1593 | .40 | 57-1865 | .30 | 60-111137 | .15 | 61-0066 | .40 |
| 57-1594 | .30 | 57-1869 | 1.25 | 60-111157 | .15 | 61-0067 | .40 |
| 57-1596 | .25 | 57-1870 | .01 | 60-111237 | .15 | 61-0068 | 1.25 |
| 57-1597 | .05 | 57-1885 | .15 | 60-113117 | .20 | 61-0071 | .40 |
| 57-1598 | .70 | 57-1887 | .20 | 60-115137 | .15 | 61-0072 | 1.25 |
| 57-1599 | .50 | 57-1888 | .15 | 60-115327 | .20 | 61-0073 | .20 |
| 57-1607 | .01 | 57-1889 | .10 | 60-120327 | .25 | 61-0074 | .35 |
| 57-1608 | .05 | 57-1890 | .10 | 60-121327 | .25 | 61-0076 | 1.25 |
| 57-1609 | per 100 .75 | 57-1899FA8 | .15 | 60-125137 | .20 | 61-0077 | .15 |
| 57-1610 | .05 | 57-1935 | .15 | 60-125157 | .20 | 61-0078 | .15 |
| 57-1611 | .05 | 57-1937 | .02 | 60-125327 | .25 | 61-0079 | .60 |
| 57-1620FA3 | .03 | 57-1939 | 1.25 | 60-125457 | .20 | 61-0080 | .35 |
| 57-1623FA3 | .10 | 57-1940 | .10 | 60-130327 | .25 | 61-0082 | .40 |
| 57-1624 | .05 | 57-1944 | .05 | 60-141137 | .20 | 61-0083 | .30 |
| 57-1625FA3 | .05 | 57-1945 | .05 | 60-150137 | .20 | 61-0084 | .30 |
| 57-1628 | .02 | 57-1949 | .20 | 60-150157 | .20 | 61-0086 | 1.25 |
| 57-1630 | .05 | 57-1953 | .50 | 60-150257 | .20 | 61-0087 | .50 |
| 57-1631 | .04 | 57-1954 | .75 | 60-160137 | .25 | 61-0088 | .25 |
| 57-1633 | per 100 .50 | 57-1955 | .10 | 60-160314 | .30 | 61-0089 | 1.25 |
| 57-1634 | .35 | 57-1956 | per 100 1.50 | 60-166127 | .30 | 61-0090 | .30 |
| 57-1635 | .05 | 57-1958 | .35 | 60-166157 | .30 | 61-0091 | .50 |
| 57-1637FA3 | .10 | 57-1959 | .10 | 60-170324 | .25 | 61-0092 | .75 |
| 57-1642 | .10 | 57-1960 | .10 | 60-170327 | .30 | 61-0100 | .15 |
| 57-1643 | .05 | 57-1961 | .02 | 60-172154 | .25 | 61-0101 | .15 |
| 57-1644FA5 | .05 | 57-1965 | .02 | 60-173127 | .30 | 61-0101 | .15 |
| 57-1645FE11 | .02 | 57-1966 | .40 | 60-177327 | .35 | 61-0102 | .25 |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 61-0103 | .15 | 63-0050 | 4.00 | 65-0121 | .50 | 65-0294 | 3.50 |
| 61-0104 | .20 | 63-0052 | .25 | 65-0122 | .50 | 65-0295 | 1.75 |
| 61-0105 | .20 | 63-0053 | .35 | 65-0123 | .50 | 65-0296 | .20 |
| 61-0106 | .30 | 63-0054 | .25 | 65-0124 | .50 | 65-0300 | .15 |
| 61-0107 | .30 | 63-0055 | .25 | 65-0125 | 1.25 | 65-0301 | .45 |
| 61-0108 | .15 | 63-0056 | .25 | 65-0134 | .40 | 65-0303 | 1.50 |
| 61-0109 | .15 | 63-0063 | .25 | 65-0135 | .50 | 65-0304 | 1.50 |
| 61-0110 | .15 | 63-0064 | .25 | 65-0136 | .50 | 65-0305 | 1.75 |
| 61-0111 | .15 | 63-0065 | .40 | 65-0137 | .50 | 65-0306 | 2.00 |
| 61-0112 | .25 | 63-0069 | .25 | 65-0138 | .50 | 65-0313 | 1.00 |
| 61-0113 | .20 | 63-0071 | .35 | 65-0139 | .50 | 65-0314 | 2.25 |
| 61-0114 | .15 | 63-0076 | .30 | 65-0147 | 1.10 | 65-0316 | 1.00 |
| 61-0115 | .35 | | | 65-0148 | 1.80 | 65-0317 | 1.25 |
| 61-0116 | .15 | 65-0002 | 2.20 | 65-0149 | 1.35 | 65-0318 | 2.50 |
| 61-0117 | .20 | 65-0003 | 2.20 | 65-0150 | 1.00 | 65-0319 | 1.50 |
| 61-0118 | .30 | 65-0004 | 1.75 | 65-0151 | .30 | 65-0320 | 1.75 |
| 61-0119 | .20 | 65-0005 | 1.75 | 65-0152 | 2.25 | 65-0321 | 1.75 |
| 61-0120 | .15 | 65-0006 | 1.75 | 65-0157 | .15 | 65-0323 | 1.00 |
| 61-0121 | .15 | 65-0007 | .50 | 65-0158 | .15 | 65-0326 | 2.75 |
| 61-0122 | .15 | 65-0008 | 1.75 | 65-0159 | 2.50 | 65-0337 | .20 |
| 61-0123 | .20 | 65-0009 | 1.25 | 65-0160 | 1.80 | 65-0338 | 1.50 |
| 61-0124 | .30 | 65-0013 | .50 | 65-0162 | 1.25 | 65-0339 | 1.00 |
| 61-0125 | .25 | 65-0014 | .50 | 65-0165 | .40 | 65-0340 | .25 |
| 61-0126 | .30 | 65-0015 | .50 | 65-0168 | .50 | 65-0341 | .75 |
| 61-0127 | .35 | 65-0016 | 3.00 | 65-0169 | 3.00 | 65-0345 | .40 |
| 61-0128 | .15 | 65-0020 | 1.75 | 65-0170 | .40 | 65-0347 | 2.50 |
| 61-0129 | .20 | 65-0021 | 1.75 | 65-0171 | .40 | 65-0349 | .75 |
| 61-0130 | .35 | 65-0022 | 1.15 | 65-0172 | .40 | 65-0350 | .60 |
| 61-0131 | .15 | 65-0024 | 1.65 | 65-0173 | .40 | 65-0351 | .35 |
| 61-0132 | .15 | 65-0029 | 1.25 | 65-0177 | 2.00 | 65-0352 | 1.60 |
| 61-0133 | .35 | 65-0030 | .40 | 65-0178 | 2.00 | 65-0353 | 1.85 |
| 61-0134 | .30 | 65-0031 | .50 | 65-0179 | 2.75 | 65-0354 | 1.60 |
| 61-0137 | .30 | 65-0033 | 3.00 | 65-0180 | 1.25 | 65-0356 | .40 |
| 61-0138 | .30 | 65-0034 | .35 | 65-0181 | .20 | 65-0357 | 1.25 |
| 61-0138 | .35 | 65-0035 | 1.25 | 65-0182 | 1.00 | 65-0358 | 2.25 |
| 61-0140 | .40 | 65-0037 | .25 | 65-0183 | 1.40 | 65-0359 | .90 |
| 61-0142 | .35 | 65-0039 | 1.75 | 65-0184 | .25 | 65-0360 | 2.00 |
| 61-0143 | .35 | 65-0041 | 2.00 | 65-0185 | 2.00 | 65-0362 | 1.50 |
| 61-0144 | .45 | 65-0043 | 2.50 | 65-0189 | 1.25 | 65-0363 | 1.25 |
| 61-0146 | .30 | 65-0044 | 2.00 | 65-0190 | 1.25 | 65-0364 | 1.00 |
| 61-0148 | .35 | 65-0045 | 2.50 | 65-0191 | 1.50 | 65-0365 | 1.50 |
| 61-0149 | .20 | 65-0046 | 3.25 | 65-0192 | 1.80 | 65-0366 | 1.75 |
| 61-0150 | 1.45 | 65-0047 | 1.00 | 65-0194 | .70 | 65-0367 | .60 |
| 61-0151 | .25 | 65-0048 | 1.25 | 65-0195 | 1.00 | 65-0378 | .25 |
| 61-0152 | .15 | 65-0051 | 1.00 | 65-0197 | .25 | 65-0379 | 1.00 |
| 61-0153 | .35 | 65-0052 | .50 | 65-0198 | .45 | 65-0383 | 1.60 |
| 61-0154 | .15 | 65-0053 | 1.50 | 65-0199 | .45 | 65-0386 | 1.60 |
| 61-0155 | .15 | 65-0054 | 1.50 | 65-0200 | .45 | 65-0387 | 1.75 |
| 61-0156 | .50 | 65-0055 | .50 | 65-0201 | .15 | 65-0388 | 1.00 |
| 61-0157 | .35 | 65-0056 | .50 | 65-0204 | .25 | 65-0389 | .50 |
| 61-0162 | .75 | 65-0057 | .20 | 65-0214 | 1.50 | 65-0391 | 1.25 |
| 61-0163 | .50 | 65-0058 | .50 | 65-0221 | .90 | 65-0395 | .90 |
| 61-0164 | .55 | 65-0062 | .20 | 65-0222 | .70 | 65-0398 | .40 |
| 61-0166 | .35 | 65-0063 | 1.25 | 65-0229 | .35 | 65-0399 | 1.50 |
| 61-0167 | .35 | 65-0069 | 1.75 | 65-0230 | 1.80 | 65-0400 | 1.50 |
| 61-0168 | .50 | 65-0071 | 1.10 | 65-0232 | .45 | 65-0401 | .90 |
| 61-0169 | .15 | 65-0072 | 2.00 | 65-0234 | 2.50 | 65-0402 | 1.25 |
| 61-0170 | .20 | 65-0073 | 1.10 | 65-0235 | 1.00 | 65-0403 | 2.75 |
| 61-0171 | .20 | 65-0075 | .40 | 65-0236 | 1.60 | 65-0404 | 2.25 |
| 61-0172 | .40 | 65-0077 | 1.40 | 65-0237 | 2.00 | 65-0408 | 1.25 |
| 61-0173 | .50 | 65-0079 | 1.50 | 65-0248 | .10 | 65-0409 | 1.60 |
| 61-0174 | .15 | 65-0082 | 2.20 | 65-0250 | .50 | 65-0410 | 1.85 |
| 61-0178 | .50 | 65-0083 | 1.25 | 65-0252 | .45 | 65-0415 | 1.60 |
| | | 65-0085 | 1.50 | 65-0255 | .40 | 65-0416 | .75 |
| 63-0003 | 5.65 | 65-0087 | .50 | 65-0256 | .40 | 65-0417 | .75 |
| 63-0009 | 5.65 | 65-0088 | .45 | 65-0257 | .40 | 65-0418 | 1.25 |
| 63-0011 | 5.35 | 65-0089 | .45 | 65-0258 | 1.15 | 65-0419 | 1.50 |
| 63-0012 | 5.35 | 65-0090 | .45 | 65-0260 | 2.00 | 65-0420 | .40 |
| 63-0015 | 5.35 | 65-0092 | 1.60 | 65-0262 | .30 | 65-0421 | 1.50 |
| 63-0016 | 4.65 | 65-0093 | 2.25 | 65-0264 | 1.50 | 65-0422 | .75 |
| 63-0017 | .35 | 65-0095 | 3.25 | 65-0265 | 1.50 | 65-0423 | .50 |
| 63-0019 | 3.00 | 65-0097 | 1.75 | 65-0267 | 1.75 | 65-0428 | .25 |
| 63-0022 | 5.65 | 65-0099 | 1.60 | 65-0268 | 1.40 | 65-0431 | 1.00 |
| 63-0023 | 3.35 | 65-0100 | 1.60 | 65-0270 | .80 | 65-0434 | 1.50 |
| 63-0024 | 3.65 | 65-0101 | 1.50 | 65-0271 | 1.60 | 65-0436 | .25 |
| 63-0026 | 3.35 | 65-0102 | .10 | 65-0272 | 2.75 | 65-0437 | .25 |
| 63-0028 | 3.35 | 65-0107 | 2.00 | 65-0274 | 1.50 | 65-0438 | .15 |
| 63-0030 | .35 | 65-0108 | .50 | 65-0275 | 1.85 | | |
| 63-0031 | .35 | 65-0111 | 1.75 | 65-0276 | 1.50 | | |
| 63-0035 | .25 | 65-0112 | 1.75 | 65-0277 | 1.25 | 67-0002 | 1.00 |
| 63-0036 | 3.35 | 65-0114 | 1.20 | 65-0278 | 3.50 | 67-0003 | 1.45 |
| 63-0037 | .35 | 65-0115 | 1.20 | 65-0279 | 1.00 | 67-0004 | 1.00 |
| 63-0038 | .25 | 65-0118 | 2.00 | 65-0282 | .20 | 67-0005 | 1.00 |
| 63-0047 | 4.00 | 65-0119 | 2.20 | 65-0283 | 2.20 | 67-0006 | 1.00 |
| 63-0048 | .30 | 65-0120 | 1.80 | 65-0293 | 2.50 | 67-0008 | 1.45 |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|--------------|------------|
| 67-0009 | 1.45 | 76-1056 | .20 | 77-1280 | .20 | 77-0292 | 1.25 |
| 67-0010 | 1.45 | 76-1059 | .90 | 76-1287 | .15 | 77-0301 | .20 |
| 67-0011 | .30 | 76-1062 | .15 | 76-1295 | .15 | 77-0307 | .25 |
| 67-0012 | 1.45 | 76-1063 | .20 | 76-1296 | 3.50 | 77-0317 | 2.75 |
| 67-0014 | 1.45 | 76-1074 | .25 | 76-1316 | .15 | 77-0318 | 2.50 |
| 67-0015 | 1.45 | 76-1075 | .15 | 76-1323 | .50 | 77-0323 | .40 |
| 67-0016 | 1.45 | 76-1077 | .15 | 76-1361 | 1.75 | 77-0325 | .25 |
| 67-0017 | 1.45 | 76-1078 | .25 | | | 77-0329 | .50 |
| 67-0018 | 1.45 | 76-1079 | .35 | 77-0017 | 1.75 | 77-0333 | 1.00 |
| 67-0019 | 1.45 | 76-1080 | .15 | 77-0022 | 1.00 | 77-0335 | .50 |
| 67-0020 | 1.45 | 76-1081 | 3.00 | 77-0025 | .40 | 77-0336 | .15 |
| 67-0022 | 1.85 | 76-1083 | 2.00 | 77-0026 | .35 | 77-0342 | .10 |
| 67-0025 | .30 | 76-1086 | 2.75 | 77-0028 | 1.50 | 77-0344 | 4.50 |
| 67-0026 | 1.45 | 76-1087 | 2.75 | 77-0029 | .60 | 77-0346 | .20 |
| 67-0027 | 1.45 | 76-1088 | .15 | 77-0031 | 1.00 | 77-0351 | 1.00 |
| 67-0028 | 1.45 | 76-1089 | 3.50 | 77-0034 | 2.25 | 77-0352 | .35 |
| 67-0029 | .35 | 76-1090 | 3.50 | 77-0035 | 1.35 | 77-0354 | 6.50 |
| 67-0032 | 1.00 | 76-1092 | 2.00 | 77-0039 | 1.50 | 77-0358 | .20 |
| 67-0035 | 1.95 | 76-1093 | 2.00 | 77-0042 | .20 | 77-0361 | .60 |
| 67-0036 | .30 | 76-1097 | 3.00 | 77-0049 | .25 | 77-0362 | .50 |
| 67-0037 | 1.45 | 76-1098 | 2.00 | 77-0050 | .25 | 77-0363 | 1.25 |
| 67-0038 | 1.00 | 76-1099 | 2.00 | 77-0051 | .75 | 77-0364 | .75 |
| 67-0039 | 1.45 | 76-1102 | 2.00 | 77-0052 | .20 | 77-0369 | 12.00 |
| 67-0040 | 1.80 | 76-1103 | .40 | 77-0070 | .40 | 77-0372 | .20 |
| 67-0041 | .30 | 76-1104 | .75 | 77-0087 | 1.20 | 77-0390 | .15 |
| 67-0042 | 1.45 | 76-1107 | 1.00 | 77-0091 | 11.00 | 77-0391 | 1.50 |
| 67-0043 | 1.00 | 76-1109 | 1.75 | 77-0098 | .50 | 77-0397 | 2.75 |
| 67-0046 | .35 | 76-1110 | 4.50 | 77-0099 | .40 | 77-0400 | .10 |
| 67-0047 | 1.45 | 76-1111 | .75 | 77-0102 | .30 | 77-0402 | .55 |
| 67-0048 | .90 | 76-1112 | .35 | 77-0105 | .75 | 77-0403 | .30 |
| 67-0050 | .65 | 76-1116 | .25 | 77-0106 | .10 | 77-0408 | 2.75 |
| 67-0051 | 1.00 | 76-1118 | 3.00 | 77-0108 | 3.50 | 77-0412 | 8.50 |
| 67-0052 | 1.45 | 76-1122 | .15 | 77-0111 | .10 | 77-0415 | .15 |
| 69-0002 | .15 | 76-1124 | 3.50 | 77-0112 | 6.50 | 77-0430 | 3.50 |
| 69-0004 | .15 | 76-1125 | .20 | 77-0114 | .90 | 77-0431 | 3.50 |
| | | 76-1127 | 3.00 | 77-0117 | 5.50 | 77-0432 | .15 |
| | | 76-1128 | .35 | 77-0120 | 3.50 | 77-0442 | .30 |
| 73-0006 | 4.75 | 76-1129 | .10 | 77-0126 | 1.75 | 77-0447 | .50 |
| 73-0007 | 4.75 | 76-1130 | 3.00 | 77-0141 | 1.75 | 77-0448 | .50 |
| 73-0008 | 5.25 | 76-1134 | 1.50 | 77-0143 | 2.00 | 77-0452 | 1.50 |
| 73-0009 | 5.00 | 76-1135 | 11.00 | 77-0148 | 3.50 | 77-0453 | 1.50 |
| 73-0010 | 5.25 | 76-1139 | .40 | 77-0149 | 1.00 | 77-0454 | 1.00 |
| 73-0012 | 4.25 | 76-1141 | 1.00 | 77-0151 | .15 | 77-0455 | 1.15 |
| 73-0014 | 4.25 | 76-1144 | 21.00 | 77-0156 | .25 | 77-0459 | .30 |
| 73-0015 | 4.75 | 76-1145 | .75 | 77-0157 | .10 | 77-0463 | .25 |
| 73-0016 | 7.25 | 76-1155 | 3.00 | 77-0160 | 1.50 | 77-0464 | .25 |
| 73-0019 | 5.25 | 76-1159 | 7.00 | 77-0161 | .45 | 77-0465 | .20 |
| 73-0022 | 4.50 | 76-1161 | .30 | 77-0166 | 5.50 | 77-0467 | .10 |
| 73-0024 | 4.75 | 76-1162 | 3.50 | 77-0169 | 1.50 | 77-0469 | 4.50 |
| 73-0025 | 5.25 | 76-1163 | 7.00 | 77-0171 | .65 | 77-0474FC-29 | 1.75 |
| 73-0026 | 3.75 | 76-1164 | 1.75 | 77-0172 | 1.60 | 77-0477 | .25 |
| 73-0027 | 3.75 | 76-1167 | .25 | 77-0174 | 2.25 | 77-0478 | .25 |
| 73-0029 | 4.25 | 76-1168 | 3.25 | 77-0175 | .60 | 77-0480 | 4.50 |
| 73-0030 | 5.00 | 76-1171 | .25 | 77-0178 | 10.00 | 77-0481 | 3.50 |
| 73-0036 | 4.25 | 76-1172 | .20 | 77-0179 | 9.25 | 77-0482 | 1.50 |
| 73-0038 | 4.50 | 76-1175 | 1.40 | 77-0180 | 2.25 | 77-0483 | 1.50 |
| 73-0039 | 4.75 | 76-1176 | .40 | 77-0185 | 1.50 | 77-0485 | .15 |
| 73-0040 | 5.00 | 76-1177 | .25 | 77-0192 | .15 | 77-0493 | .20 |
| 73-0042 | 5.00 | 76-1178 | .20 | 77-0195 | .25 | 77-0503 | .20 |
| 73-0043 | 4.25 | 76-1179 | .25 | 77-0197 | .50 | 77-0506 | 1.50 |
| 73-0044 | 5.75 | 76-1181 | 3.00 | 77-0198 | 1.75 | 77-0511 | 3.50 |
| 73-0045 | 4.75 | 76-1182 | 3.00 | 77-0202 | .85 | 77-0512 | 1.50 |
| 73-0047 | 4.75 | 76-1187 | 3.00 | 77-0203 | 1.75 | 77-0514 | .90 |
| 73-0048 | 4.50 | 76-1189 | 3.00 | 77-0204 | 9.50 | 77-0526 | .50 |
| 73-0049 | 5.75 | 76-1191 | 3.25 | 77-0206 | 2.00 | 77-0531 | .30 |
| 73-0050 | 5.00 | 76-1194 | 1.75 | 77-0207 | 2.00 | 77-0539 | 12.50 |
| 73-0051 | 5.00 | 76-1196 | 2.00 | 77-0215 | .50 | 77-0541 | .15 |
| 73-0052 | 4.75 | 76-1198 | .30 | 77-0217 | .20 | 77-0545 | .25 |
| 73-0053 | 3.75 | 76-1200 | 2.75 | 77-0220 | .90 | 77-0549 | 12.00 |
| 73-0054 | 4.25 | 76-1210 | 2.75 | 77-0227 | 1.25 | 77-0558 | 7.50 |
| 73-0055 | 5.25 | 76-1212 | .25 | 77-0229 | 9.00 | 77-0560 | 1.50 |
| 73-0056 | 5.00 | 76-1216 | 1.25 | 77-0230 | 3.75 | 77-0567 | 1.75 |
| 73-0058 | 4.75 | 76-1224 | 1.25 | 77-0233 | .40 | 77-0571 | 2.00 |
| 73-0059 | 4.00 | 76-1226 | .35 | 77-0247 | 1.00 | 77-0572 | 1.00 |
| 73-0062 | 4.25 | 76-1227 | .35 | 77-0248 | .40 | 77-0573 | .45 |
| 73-0064 | 5.00 | 76-1229 | .35 | 77-0249 | .35 | 77-0574 | .45 |
| 73-0066 | 4.75 | 76-1230 | 2.00 | 77-0250 | .35 | 77-0579 | .30 |
| | | 76-1234 | 1.75 | 77-0252 | .40 | 77-0580 | .30 |
| 76-1003 | 2.50 | 76-1244 | .50 | 77-0257 | 5.75 | 77-0587 | .20 |
| 76-1019 | .35 | 76-1245 | .50 | 77-0258 | 5.75 | 77-0588 | 13.00 |
| 76-1034 | .40 | 76-1246 | .25 | 77-0262 | 1.50 | 77-0590 | 5.50 |
| 76-1036 | .20 | 76-1247 | .30 | 77-0264 | 3.50 | 77-0592 | .25 |
| 76-1042 | 1.50 | 76-1248 | .50 | 77-0268 | .15 | 77-0600 | 9.00 |
| 76-1044 | .65 | 76-1256 | .75 | 77-0285 | .25 | 77-0601 | 9.25 |
| 76-1049 | .10 | 76-1278 | 1.50 | 77-0286 | 1.75 | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|----------|------------|----------|------------|----------|------------|----------|------------|
| 77-0609 | .60 | 77-0780 | 1.00 | 83-0026 | 2.50 | 91-0063 | 7.50 |
| 77-0612 | .25 | 77-0787 | .50 | 83-0027 | 2.50 | 91-0064 | 7.00 |
| 77-0613 | .30 | 77-0788 | .45 | 83-0028 | 2.50 | 91-0065 | 1.40 |
| 77-0616 | .15 | 77-0789 | .75 | 83-0029 | 2.50 | 91-0068 | 1.50 |
| 77-0617 | .20 | 77-0796 | .30 | 85-0005 | .25 | 91-0070 | 1.50 |
| 77-0618 | .60 | 77-0797 | .30 | 85-0006 | 16.00 | 91-0071 | 1.50 |
| 77-0621 | .25 | 77-0798 | .30 | 85-0008 | 24.00 | 91-0075 | 1.95 |
| 77-0623 | .40 | 77-0799 | .30 | 85-0009 | .40 | 91-0076 | 1.25 |
| 77-0625 | .15 | 77-0800 | .30 | 85-0010 | .30 | 91-0077 | 1.25 |
| 77-0626 | .85 | 77-0801 | .25 | 85-0011 | 3.00 | 91-0081 | 3.95 |
| 77-0627 | .20 | 77-0802 | 11.00 | 85-0017 | 2.25 | 91-0085 | 1.50 |
| 77-0628 | 1.25 | 77-0804 | .15 | 85-0019 | .45 | 91-0086 | 1.50 |
| 77-0630 | .85 | 77-0805 | .25 | 85-0020 | .70 | 91-0101 | 1.40 |
| 77-0631 | .20 | 77-0807 | 4.50 | 85-0021 | 19.00 | 91-0102 | 1.40 |
| 77-0633 | .15 | 77-0809 | .20 | 85-0022 | 18.50 | 91-0104 | 3.75 |
| 77-0635 | 11.75 | 77-0810 | .05 | 85-0027 | .15 | 91-0105 | 3.75 |
| 77-0636 | 13.25 | 77-0815 | 9.00 | 85-0029 | 2.00 | 91-0109 | 2.70 |
| 77-0637 | .20 | 77-0816 | .20 | 85-0030 | 3.25 | 91-0110 | 2.95 |
| 77-0638 | .40 | 77-0824 | .20 | 85-0031 | 5.00 | 91-0111 | 3.95 |
| 77-0640 | 7.75 | 77-0831 | .30 | 85-0033 | 18.00 | 91-0113 | 1.50 |
| 77-0643 | .50 | 77-0834 | 1.25 | 85-0035 | .40 | 91-0114 | 1.50 |
| 77-0644 | 5.50 | 77-0835 | .15 | 85-0038 | .35 | 91-0119 | 2.50 |
| 77-0645 | 1.80 | 77-0837 | 1.25 | 85-0040 | .35 | 91-0126 | 1.50 |
| 77-0646 | .20 | 77-0841 | 1.25 | 85-0041 | 4.50 | 91-0128 | 1.40 |
| 77-0647 | .35 | 77-0845 | .45 | 85-0042 | .55 | 91-0135 | 8.00 |
| 77-0649 | .30 | 77-0846 | .45 | 85-0043 | 22.50 | 91-0136 | 7.50 |
| 77-0650 | .50 | 77-0847 | .40 | 85-0046 | 2.75 | 91-0139 | 7.25 |
| 77-0651 | .35 | 77-0848 | .40 | 85-0047 | 4.25 | 91-0140 | 6.50 |
| 77-0654 | .15 | 77-0849 | .45 | 85-0048 | 4.25 | 91-0144 | 4.45 |
| 77-0657 | 12.00 | 77-0854 | 2.50 | 85-0052 | .30 | 91-0151 | 2.50 |
| 77-0661 | .20 | 77-0856 | .25 | 85-0054 | .15 | 91-0164 | 1.50 |
| 77-0666 | 5.25 | 77-0863 | .75 | 85-0067 | 10.50 | 91-0165 | 1.50 |
| 77-0667 | .50 | 77-0864 | .25 | 85-0069 | 8.50 | 91-0166 | 1.50 |
| 77-0669 | .15 | 77-0865 | 13.75 | 85-0078 | 15.50 | 91-0167 | 1.75 |
| 77-0676 | .50 | 77-0866 | 1.25 | 85-0079 | .60 | 91-0168 | 1.75 |
| 77-0681 | .15 | 77-0885 | .75 | 85-0082 | .50 | 91-0169 | 4.25 |
| 77-0682 | .80 | 77-0887 | .25 | 85-0083 | .40 | 91-0170 | 4.25 |
| 77-0687 | .15 | 77-0888 | .20 | 85-0087 | 1.00 | 91-0172 | 4.25 |
| 77-0688 | .25 | 77-0890 | .60 | 85-0091 | .25 | 91-0180 | 1.75 |
| 77-0692 | .20 | 77-0891 | 14.75 | 85-0093 | .20 | 91-0181 | 1.75 |
| 77-0695 | 2.50 | 77-0899 | 9.25 | 85-0097 | 3.25 | 91-0182 | 3.75 |
| 77-0698 | .30 | 77-0909 | .45 | 85-0102 | .40 | 91-0195 | 5.00 |
| 77-0701 | 4.00 | 77-0912 | 1.50 | 85-0104 | .75 | 91-0196 | 5.00 |
| 77-0704 | .60 | 77-0913 | 2.50 | 85-0106 | .60 | 91-0197 | 5.00 |
| 77-0705 | 2.25 | 77-0914 | .20 | 85-0111 | .40 | 91-0206 | 4.50 |
| 77-0706 | 7.50 | 77-0916 | .25 | 85-0112 | .30 | 91-0207 | 4.50 |
| 77-0708 | .25 | 77-0923 | .20 | 85-0113 | 10.00 | 91-0208 | 4.50 |
| 77-0709 | 4.50 | 77-0924 | .30 | 85-0114 | 5.50 | 91-0209 | 1.50 |
| 77-0710 | .15 | 77-0925 | .30 | 85-0115 | 8.00 | 91-0210 | 1.50 |
| 77-0712 | .65 | 77-0926 | .25 | 85-0117 | 8.00 | 91-0211 | 1.50 |
| 77-0715 | .50 | 77-0927 | 1.25 | 85-0118 | 3.50 | 91-0213 | 1.50 |
| 77-0719 | 2.00 | 77-0937 | .15 | 85-0121 | 10.00 | 91-0216 | 3.45 |
| 77-0721 | .20 | 77-0943 | 12.00 | 85-0122 | .25 | 91-0217 | 3.95 |
| 77-0722 | .10 | 77-0947 | 1.75 | 85-0123 | .20 | 91-0219 | 3.55 |
| 77-0723 | .40 | | | 85-0125 | .45 | 91-0220 | 4.95 |
| 77-0724 | .50 | 79-0343 | .20 | 85-0126 | .50 | 91-0227 | 4.95 |
| 77-0725 | .85 | 79-0371 | .15 | 85-0127 | 3.50 | 95-0001 | .55 |
| 77-0726 | .90 | 81-0018 | .60 | 85-0128 | .50 | 95-0015 | .20 |
| 77-0730 | 10.00 | 81-0024 | .60 | 85-0129 | 11.00 | 95-0016 | .85 |
| 77-0731 | .35 | 81-0025 | .50 | 85-0130 | 14.00 | 95-0019 | 1.25 |
| 77-0732 | 1.10 | 81-0045 | .75 | 85-0132 | 11.00 | 95-0021 | .30 |
| 77-0733 | .25 | 81-0052 | .75 | 85-0133 | 9.25 | 95-0022 | .45 |
| 77-0734 | .45 | 81-0066 | .60 | 85-0134 | 9.00 | 95-0023 | 1.00 |
| 77-0735 | .25 | 81-0088 | .30 | 85-0136 | 4.00 | 95-0024 | .15 |
| 77-0736 | .50 | 81-0091 | .60 | 85-0139 | 5.75 | 95-0025 | 2.00 |
| 77-0737 | .25 | 81-0102 | .40 | 85-0140 | 5.00 | 95-0026 | 1.25 |
| 77-0738 | .20 | 81-0143 | .60 | 85-0141 | 4.75 | 95-0028 | 1.15 |
| 77-0740 | 7.25 | 81-0177 | .50 | 85-0142 | 5.50 | 95-0030 | .60 |
| 77-0749 | .55 | 81-0192 | .50 | 85-0144 | .75 | 95-0031 | .60 |
| 77-0753 | .20 | 81-0203 | .60 | 91-0003 | 6.50 | 95-0032 | .25 |
| 77-0755 | .60 | 81-0227 | .25 | 91-0022 | 2.95 | 95-0033 | .20 |
| 77-0760 | 2.25 | 81-0233 | .10 | 91-0024 | 1.50 | 95-0034 | .60 |
| 77-0762 | 2.75 | 81-0254 | 5.00 | 91-0025 | 1.40 | 95-0036 | 1.00 |
| 77-0765 | .10 | 81-0256 | .50 | 91-0026 | 1.50 | 95-0037 | .15 |
| 77-0766 | .30 | 81-0318 | .50 | 91-0027 | 1.40 | 95-0039 | 1.75 |
| 77-0767 | .50 | | | 91-0028 | 1.50 | 95-0048 | .30 |
| 77-0769 | .50 | 83-0004 | 1.20 | 91-0035 | 1.50 | 95-0053 | .15 |
| 77-0771 | .90 | 83-0005 | 1.40 | 91-0041 | 1.40 | 95-0054 | .15 |
| 77-0772 | 1.10 | 83-0009 | .15 | 91-0042 | 1.75 | 95-0055 | .10 |
| 77-0773 | 1.00 | 83-0010 | 1.25 | 91-0043 | 1.40 | 95-0057 | 1.25 |
| 77-0774 | 1.75 | 83-0011 | .85 | 91-0046 | 2.70 | 95-0058 | .25 |
| 77-0776 | 1.00 | 83-0015 | 1.40 | 91-0055 | 7.25 | 95-0059 | 1.75 |
| 77-0777 | 1.00 | 83-0016 | .55 | 91-0058 | 1.50 | 95-0065 | 1.25 |
| 77-0778 | 1.00 | 83-0017 | 2.50 | 91-0062 | 6.25 | 95-0066 | 1.60 |
| 77-0779 | 1.00 | 83-0025 | 2.50 | | | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|-------------|--------------|-------------|--------------|---------------|-------------|----------|-------------------|
| 95-0068 | 7.00 | 97-0075 | .03 | 218-1126 | per 100 .90 | 415-1006 | .75 |
| 95-0069 | .40 | 97-0076 | per 100 1.25 | 218-1157 | .01 | 415-1007 | .05 |
| 95-0071 | 1.50 | 97-0078FA-3 | per 100 .60 | 218-1165 | .15 | 415-1008 | .15 |
| 95-0072 | 1.50 | 97-0079 | per 100 .75 | 218-1212 | .10 | 415-1009 | .60 |
| 95-0073 | .15 | 97-0082FA-3 | per 100 1.25 | | | 415-1010 | .60 |
| 95-0074 | 2.25 | 97-0085 | per 100 2.00 | 311-1000 | .45 | 415-1011 | .25 |
| 95-0075 | 1.30 | 97-0086 | per 100 2.00 | | | 415-1012 | 1.60 |
| 95-0076 | .85 | 97-0087 | .10 | 315-1000 | .90 | 415-1013 | .60 |
| 95-0085 | 1.20 | 97-0090FA-3 | per 100 1.50 | 315-1001 | 8.50 | 415-1014 | .60 |
| 95-0087 | 1.25 | 97-0091 | .05 | 315-1002 | .10 | 415-1016 | 1.25 |
| 95-0088 | 1.00 | 97-0092 | .05 | 315-1003 | .10 | 415-1017 | .60 |
| 95-0089 | .10 | 97-0094 | .05 | 315-1004 | 12.00 | 415-1019 | .35 |
| 95-0090 | .15 | 97-0097 | .05 | 315-1005 | 9.00 | 415-1020 | .65 |
| 95-0091 | 1.40 | 97-0099 | per 100 1.00 | 315-1006 | 9.00 | 415-1021 | .10 |
| 95-0097 | .35 | 97-0101 | per 100 .75 | 315-1007 | 1.00 | 415-1022 | per 100 2.50 |
| 95-0098 | .10 | 97-0102 | per 100 2.00 | 315-1008 | 8.75 | 415-1023 | 3.50 |
| 95-0100 | .10 | 97-0103 | .05 | 315-1019 | 1.15 | 415-1026 | .15 |
| 95-0101 | .90 | 97-0105FA3 | per 100 .75 | 315-1020 | .40 | 415-1027 | 5.00 |
| 95-0105 | .90 | 97-0106 | .02 | 315-1021 | 2.50 | 415-1031 | .90 |
| 95-0106 | 1.25 | 97-0108FA3 | per 100 1.25 | 315-1022 | .45 | 415-1034 | 1.00 |
| 95-0109 | .90 | 97-0110 | .02 | 315-1024 | 2.50 | 415-1035 | .10 |
| 95-0110 | 1.00 | 97-0111FA24 | per 100 .85 | 315-1025 | .60 | 415-1036 | .10 |
| 95-0111 | 1.00 | 97-0112FA4 | .02 | 315-1026 | .60 | 415-1037 | .10 |
| 95-0112 | .55 | 97-0116FA3 | per 100 1.00 | 315-1027 | .60 | 415-1038 | .10 |
| 95-0113 | .20 | 97-0118FA24 | per 100 2.50 | 315-1028 | .05 | 415-1040 | .15 |
| 95-0114 | .20 | 97-0120FA4 | per 100 2.50 | 315-1029 | .05 | 415-1041 | 2.00 |
| 95-0120 | 1.00 | 97-0121 | .01 | 315-1030 | .05 | 415-1042 | 1.75 |
| 95-0124 | 1.40 | 97-0125 | per 100 2.00 | 315-1031 | .05 | 415-1043 | .05 |
| 95-0126 | 1.25 | 97-0126 | per 100 .75 | 315-1032 | .05 | 415-1044 | .03 |
| 95-0132 | .10 | 97-0131 | .04 | 315-1033 | .05 | 415-1045 | 1.25 |
| 95-0135 | .25 | 97-0132 | .04 | 315-1034 | .05 | 415-1046 | .10 |
| 95-0137 | 1.00 | 97-0135FA3 | .05 | 315-1035 | .05 | 415-1047 | .10 |
| 95-0140 | .60 | 97-0136 | .01 | 315-1036 | .05 | 415-1048 | .25 |
| 95-0141 | .50 | 97-0137FA3 | .01 | 315-1037 | .15 | 415-1049 | .03 |
| 95-0145 | .50 | 97-0138FA3 | per 100 .50 | 315-1038 | .30 | 415-1051 | .25 |
| 95-0149 | 1.00 | 97-0138FA35 | per 100 .50 | 315-1039 | .10 | 415-1052 | .10 |
| 95-0156 | 1.00 | 97-0139FE9 | per 100 .75 | | | 415-1053 | .03 |
| 95-0157 | 1.10 | 97-0140 | per 100 1.75 | 318-1014 | 5.00 | 415-1054 | .03 |
| 95-0161 | .20 | 97-0142 | .03 | 318-1054FC-29 | 1.00 | 415-1063 | .15 |
| 95-0163 | .15 | 97-0144 | .01 | 318-1086 | 3.00 | 415-1064 | .75 |
| 95-0166 | .85 | 97-0145FA3 | .05 | 318-1097 | 4.00 | 415-1065 | 1.00 |
| 95-0167 | .10 | 97-0146 | .05 | 318-1120 | .15 | | |
| 95-0168 | .20 | 97-0147FA8 | .02 | 318-1142 | .10 | L-474A | .30 |
| 95-0170 | 1.25 | 97-0148FA3 | .03 | 318-1157 | .50 | L-543 | .10 |
| 95-0171 | .65 | 97-0150FC51 | .10 | 318-1158FC34 | .75 | L-1124A | .40 |
| 95-0172 | .30 | 97-0151FC58 | .10 | 318-1209 | .20 | L-1125 | per 100 .75 |
| 95-0173 | .10 | 97-0157 | .02 | 318-1216 | .40 | L-1126 | per 100 1.25 |
| 95-0176 | .50 | 97-0161FA7 | .10 | 318-1344 | .75 | L-1166 | .01 |
| 95-0177 | .90 | 97-0176FA3 | .01 | 318-1374 | .35 | L-1211 | 1.25 |
| 95-0181 | 1.00 | 97-0177 | .05 | 318-1395 | .75 | L-1219 | .80 |
| 95-0184 | .75 | 97-0178 | .05 | 318-1401 | .15 | L-1383 | per 100 ft. 10.00 |
| 95-0185 | 1.25 | 97-0181FA3 | .01 | 318-1402 | .15 | L-1447 | per 100 ft. .45 |
| 95-0186 | 2.25 | 97-0183 | .02 | 318-1403 | .10 | L-1486 | per 100 .40 |
| 95-0188 | .75 | 97-0191 | .25 | 318-1405 | .15 | L-1534 | per 100 ft. 1.20 |
| 95-0189 | 2.40 | 97-0198 | .03 | 318-1444 | 1.25 | L-1551 | per 100 ft. 2.75 |
| 95-0191 | 1.10 | 97-0199 | .03 | 318-1455 | .50 | L-1571 | per 100 ft. 1.05 |
| 95-0192 | .10 | 97-0202 | .03 | 318-1465 | .75 | L-1591 | per 100 ft. 3.00 |
| 95-0199 | 2.00 | 97-0203 | .20 | 318-1514 | .15 | L-1626 | .01 |
| 95-0200 | .80 | 97-0204 | .03 | 318-1693 | .20 | L-1632 | per 100 ft. 6.00 |
| 95-0210 | .75 | 97-0210 | .02 | 318-1777 | .40 | L-1640 | per 100 ft. 2.00 |
| 95-0211 | 1.00 | 97-0211 | .03 | 318-1778 | .35 | L-1641 | per 100 ft. 1.70 |
| 95-0217 | 1.25 | | | 318-1782 | 1.75 | L-1712 | per 100 ft. 1.40 |
| 95-0218 | .85 | | | 318-1813 | .35 | L-1773 | per 100 .35 |
| 95-0220 | .60 | 217-1030 | .15 | 318-1817 | .10 | L-1821 | per 100 ft. 1.00 |
| 95-0221 | .40 | 217-1057 | .10 | 318-1836 | .30 | L-1852 | 1.40 |
| | | 217-1066 | per 100 1.50 | 318-1837 | .35 | L-1921 | .55 |
| 97-0020 | per 100 .75 | 217-1067 | per 100 1.50 | 318-2011-FC46 | 1.50 | L-2176 | .15 |
| 97-0024FA-1 | per 100 .05 | 217-1068 | per 100 1.50 | 318-2038 | 1.50 | L-2179 | 1.75 |
| 97-0028 | per 100 1.75 | 217-1069 | .30 | 318-2119 | .65 | L-2183-A | .40 |
| 97-0034 | per 100 1.75 | 217-1070 | .15 | 318-2235 | .60 | L-2243 | per 100 ft. 9.00 |
| 97-0040 | .05 | 217-1089 | .25 | 318-2261 | 1.75 | L-2282 | 1.20 |
| 97-0042FA-1 | .02 | 217-1260 | .10 | 318-2264 | .75 | L-2588 | 1.60 |
| 97-0043FA-1 | .02 | 217-1298 | .03 | 318-2273 | .15 | L-2603 | 12.50 |
| 97-0048FA-3 | .02 | | | 318-2383 | .25 | L-2612 | 25.00 |
| 97-0050 | per 100 .75 | 218-1015 | per 100 .75 | 318-2401 | .45 | L-2627 | 14.00 |
| 97-0054 | per 100 .75 | 218-1047 | per 100 1.40 | 318-2431 | .60 | L-2630 | 1.75 |
| 97-0056FA-3 | per 100 .65 | 218-1070 | per 100 3.00 | 318-2506 | .50 | L-2651 | 1.60 |
| 97-0061 | .03 | 218-1072 | per 100 1.00 | | | L-2665 | .85 |
| 97-0063 | .10 | 218-1073 | .15 | 412-1005 | 7.00 | L-2666 | 1.50 |
| 97-0064 | per 100 2.00 | 218-1075 | per 100 1.75 | 412-1007 | 1.50 | L-2761 | 1.50 |
| 97-0069FA-3 | per 100 1.50 | 218-1087FA3 | .15 | 412-1017 | .20 | L-2763 | 1.25 |
| 97-0070FA-4 | per 100 1.00 | 218-1088FA3 | per 100 3.50 | 412-1019 | .30 | L-2765 | 1.25 |
| 97-0071FA-9 | .03 | 218-1089FA3 | per 100 1.25 | 412-1024 | 1.50 | L-2766 | 1.25 |
| 97-0073 | per 100 .75 | 218-1125 | .01 | 415-1005 | .03 | | |

| PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE | PART NO. | LIST PRICE |
|-----------|--------------|------------|--------------|------------|--------------|-------------|--------------|
| L-2776 | 1.35 | W-258 | per 100 .30 | W-590 | .04 | W-1400 | per 100 .50 |
| L-2778 | .40 | W-262 | per 100 1.80 | W-591 | .07 | W-1406 | per 100 1.25 |
| L-2804 | 1.35 | W-267FA8 | .02 | W-599FA-3 | per 100 .50 | W-1412 | per 100 5.00 |
| L-2835 | 1.25 | W-268FA-4 | per 100 .25 | W-601 | per 100 .25 | W-1442 | .05 |
| L-2840 | .25 | W-270FA3 | per 100 .75 | W-602 | per 100 .25 | W-1443 | per 100 1.00 |
| L-2849 | 1.25 | W-271 | per 100 .25 | W-611 | per 100 .35 | W-1444-FA-4 | per 100 1.00 |
| L-2868 | 6.25 | W-272FA9 | per 100 1.50 | W-612 | per 100 1.50 | W-1446-FA-3 | per 100 .40 |
| L-2939 | .90 | W-274 | per 100 .30 | W-614FA-3 | per 100 .40 | W-1452 | per 100 .60 |
| L-2949 | 1.40 | W-276 | per 100 .25 | W-617 | per 100 .22 | W-1457 | per 100 2.00 |
| L-2969 | ft. .15 | W-277 | per 100 2.00 | W-628 | per 100 1.75 | W-1469 | per 100 .20 |
| L-3033 | 1.00 | W-285-FA-3 | per 100 1.25 | W-630 | per 100 1.95 | W-1470 | per 100 .40 |
| L-3093 | 1.50 | W-286 | per 100 .45 | W-637 | per 100 .20 | W-1475 | per 100 1.00 |
| L-3106 | 1.00 | W-287 | per 100 .40 | W-644FA-3 | per 100 1.50 | W-1476 | per 100 .25 |
| L-3111 | 1.00 | W-289 | per 100 .60 | W-648-FA-3 | per 100 .20 | W-1485-FA-3 | per 100 .55 |
| L-3112 | 1.25 | W-291 | per 100 .40 | W-650-FA-3 | per 100 .40 | W-1494 | per 100 .30 |
| L-3113 | 1.60 | W-303 | per 100 .90 | W-658 | per 100 1.00 | W-1495 | per 100 1.50 |
| L-3160 | .90 | W-307FA-3 | per 100 .50 | W-661 | per 100 1.50 | W-1496 | per 100 1.60 |
| L-3171 | 6.50 | W-315 | per 100 .50 | W-669 | per 100 1.90 | W-1505 | .04 |
| L-3175 | .35 | W-317 | per 100 .40 | W-671 | .05 | W-1506 | per 100 2.00 |
| L-3176 | 1.00 | W-333 | per 100 1.00 | W-673 | per 100 .40 | W-1516 | per 100 1.30 |
| L-3177 | .15 | W-338 | per 100 .75 | W-674 | per 100 .50 | W-1517 | .02 |
| L-3180 | .65 | W-353 | per 100 3.00 | W-679 | per 100 .45 | W-1532 | per 100 .50 |
| L-3183 | .40 | W-359FA3 | .05 | W-684-FA-3 | per 100 1.25 | W-1538 | per 100 1.80 |
| L-3185 | .20 | W-366 | per 100 2.00 | W-685 | per 100 1.25 | W-1543FA3 | per 100 .75 |
| L-3190 | .10 | W-371FA3 | per 100 2.50 | W-686 | per 100 .35 | W-1550 | per 100 2.00 |
| L-3191 | .10 | W-372FA-3 | per 100 1.50 | W-688-FA-1 | per 100 .85 | W-1555 | per 100 .65 |
| L-3192 | .30 | W-377FA-3 | per 100 1.25 | W-708-FA-3 | per 100 1.70 | W-1564 | per 100 1.50 |
| L-3193 | .15 | W-378 | per 100 .40 | W-715 | per 100 .50 | W-1564FA-8 | .04 |
| L-3195 | .25 | W-381 | per 100 .35 | W-716 | per 100 2.00 | W-1567 | per 100 1.55 |
| L-3197 | 1.25 | W-385 | per 100 1.80 | W-729-FA-3 | per 100 .45 | W-1568 | .02 |
| L-3199 | .45 | W-392 | .04 | W-735 | per 100 .50 | W-1570 | per 100 1.25 |
| L-3202 | .40 | W-399 | per 100 .45 | W-737 | per 100 .45 | W-1571 | per 100 .75 |
| L-3206 | .35 | W-405-A | per 100 1.00 | W-739 | per 100 .50 | W-1575 | per 100 .50 |
| L-3217 | .45 | W-409 | per 100 .25 | W-745 | per 100 1.25 | W-1579-FA3 | per 100 .75 |
| L-3218 | .35 | W-410 | per 100 .15 | W-751 | per 100 .20 | W-1582-FA4 | per 100 .75 |
| L-3240 | .50 | W-412 | per 100 .35 | W-752 | per 100 .40 | W-1582FC34 | per 100 .90 |
| L3259 | per ft. .07 | W-417 | per 100 .50 | W-758 | per 100 1.00 | W-1583 | per 100 .75 |
| L-3261 | .50 | W-424 | per 100 .60 | W-763 | .03 | W-1586FA-3 | per 100 .90 |
| L3278 | 2.00 | W-425 | per 100 .85 | W-767 | per 100 .40 | W-1589 | per 100 .50 |
| L3283 | 3.75 | W-426 | per 100 3.00 | W-775 | per 100 1.50 | W-1598 | per 100 3.00 |
| L-3291 | 17.50 | W-434 | per 100 1.50 | W-782 | per 100 .85 | W-1604 | per 100 .50 |
| | | W-435 | per 100 .60 | W-783 | per 100 2.20 | W-1604FA3 | per 100 1.25 |
| W-53 | per 100 1.50 | W-436 | per 100 .80 | W-784 | per 100 1.00 | W-1604FC10 | per 100 4.00 |
| W-55 | per 100 1.20 | W-439 | per 100 .25 | W-792 | per 100 3.00 | W-1604FB24 | per 100 4.00 |
| W-78 | per 100 .45 | W-443 | per 100 2.40 | W-806 | per 100 2.00 | W-1605 | per 100 .80 |
| W-79 | per 100 .50 | W-444 | per 100 2.25 | W-808 | per 100 2.00 | W-1609 | per 100 .50 |
| W-88 | per 100 .55 | W-446 | per 100 .25 | W-814 | per 100 .75 | W-1619B | per 100 .50 |
| W-91 | per 100 .20 | W-451 | per 100 1.80 | W-821 | per 100 2.50 | W-1622 | per 100 .75 |
| W-95-FA-3 | per 100 .30 | W-452 | per 100 .60 | W-824 | per 100 2.00 | W-1624 | per 100 1.25 |
| W-98 | per 100 1.25 | W-453 | per 100 1.80 | W-825 | per 100 .95 | W-1628 | per 100 .50 |
| W-99 | per 100 1.00 | W-454 | per 100 2.00 | W-826 | per 100 1.50 | W-1629 | per 100 1.75 |
| W-110 | per 100 .35 | W-461 | per 100 1.00 | W-831 | per 100 .25 | W-1635 | per 100 1.00 |
| W-116 | per 100 5.00 | W-464 | per 100 .55 | W-832 | per 100 .25 | W-1638FAs | .05 |
| W-124-FA3 | per 100 .55 | W-467 | per 100 3.00 | W-834 | per 100 2.75 | W-1641 | .02 |
| W-128 | per 100 1.00 | W-468 | per 100 3.60 | W-839 | .03 | W-1645 | per 100 .30 |
| W-137 | per 100 .30 | W-470 | per 100 1.85 | W-844 | per 100 .50 | W-1650 | per 100 .25 |
| W-141 | per 100 .20 | W-476 | per 100 .35 | W-846 | .10 | W-1665 | per 100 .30 |
| W-145 | per 100 .30 | W-479 | per 100 .30 | W-848 | per 100 .55 | W-1667 | .04 |
| W-147 | per 100 .30 | W-480 | per 100 .55 | W-881-FA-1 | per 100 1.00 | W-1668 | per 100 1.50 |
| W-149 | per 100 .45 | W-481 | per 100 2.00 | W-894 | per 100 1.00 | W-1669 | per 100 .40 |
| W-150 | per 100 .50 | W-483 | per 100 .35 | W-895 | per 100 2.00 | W-1671 | per 100 .40 |
| W-151 | per 100 .20 | W-488 | per 100 .35 | W-895FA3 | .05 | W-1676 | per 100 .80 |
| W-152 | per 100 .20 | W-490FA-4 | per 100 2.80 | W-899FA9 | per 100 .50 | W-1677 | .03 |
| W-159FA1 | per 100 .75 | W-492 | per 100 .40 | W-917 | per 100 .40 | W-1679 | per 100 .90 |
| W-160 | per 100 .30 | W-493 | per 100 .50 | W-950 | per 100 .12 | W-1683 | per 100 .40 |
| W-161 | per 100 .75 | W-494 | per 100 .50 | W-1004 | .04 | W-1686FA3 | .05 |
| W-161FA3 | per 100 .75 | W-496 | per 100 .25 | W-1031 | per 100 .20 | W-1687 | per 100 .70 |
| W-174 | per 100 1.50 | W-506 | per 100 1.25 | W-1074 | per 100 .25 | W-1688 | per 100 2.50 |
| W-181 | per 100 .45 | W-515 | per 100 .50 | W-1307 | per 100 .20 | W-1689-FA-4 | per 100 1.75 |
| W-183 | per 100 .75 | W-516 | per 100 .40 | W-1312 | per 100 1.75 | W-1695 | per 100 .60 |
| W-204FA-3 | per 100 .45 | W-518 | per 100 1.75 | W-1313 | .03 | W-1698 | per 100 2.00 |
| W-206 | per 100 .35 | W-523 | per 100 1.85 | W-1318 | per 100 1.90 | W-1699 | .03 |
| W-207 | per 100 .35 | W-532 | per 100 .35 | W-1321 | per 100 1.60 | W-1700 | per 100 1.95 |
| V-208 | per 100 .35 | W-533 | per 100 .35 | W-1331 | per 100 .20 | W-1701 | per 100 2.00 |
| W-209 | per 100 .35 | W-534 | per 100 .90 | W-1333 | per 100 2.50 | W-1702FA3 | per 100 .75 |
| W-212 | per 100 .35 | W-545 | per 100 .65 | W-1345 | per 100 2.75 | W-1709 | per 100 2.40 |
| W-216 | per 100 .35 | W-546 | per 100 .35 | W-1352 | per 100 1.25 | W-1714 | per 100 .75 |
| W-219FA3 | per 100 .35 | W-560FA9 | per 100 .75 | W-1358 | per 100 2.60 | W-1715 | .04 |
| W-222 | per 100 .50 | W-563 | per 100 1.90 | W-1366 | per 100 .40 | W-1716 | per 100 1.95 |
| W228 | per 100 .75 | W-565 | .10 | W-1374 | per 100 .05 | W-1721 | per 100 .75 |
| W-230 | per 100 .30 | W-566 | per 100 1.50 | W-1375 | per 100 .35 | W-1725 | .15 |
| W-239 | per 100 .75 | W-568 | per 100 3.50 | W-1390 | per 100 .50 | W-1727 | per 100 6.00 |
| W-242 | per 100 1.00 | W-578 | per 100 .95 | W-1397 | per 100 1.00 | W-1729 | per 100 1.50 |
| W-252 | per 100 1.80 | | | | | W-1732 | per 100 .40 |

| PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE | PART No. | LIST PRICE |
|-------------|------------|----------|-------------|----------|------------|-------------|--------------|
| W-1734 | per 100 | .50 | W-1941 | per 100 | 2.00 | W-2091FA-8 | .20 |
| W-1736 | per 100 | .80 | W-1943 | per 100 | .10 | W-2092FA-8 | .25 |
| W-1742 | per 100 | 4.00 | W-1944 | per 100 | .10 | W-2096 | per 100 .50 |
| W-1752 | per 100 | .50 | W-1946 | per 100 | .02 | W-2100 | per 100 .10 |
| W-1754FA-8 | per 100 | 2.50 | W-1958 | per 100 | .40 | W-2101 | per 100 .06 |
| W-1757 | per 100 | .03 | W-1968 | per 100 | 1.75 | W-2102 | per 100 .10 |
| W-1758 | per 100 | 4.00 | W-1972 | per 100 | .60 | W-2103 | per 100 .90 |
| W-1767 | per 100 | .04 | W-1975-FA-1 | per 100 | 1.25 | W-2105-FA3 | .10 |
| W-1774-FA-8 | per 100 | .10 | W-1984 | per 100 | 1.00 | W-2106 | per 100 .75 |
| W-1780 | per 100 | .90 | W-1988FA-3 | per 100 | 1.50 | W-2109FA9 | per 100 .75 |
| W-1782 | per 100 | 2.50 | W-1991 | per 100 | 1.00 | W-2108FA3 | per 100 1.75 |
| W-1791 | per 100 | .75 | W-1997 | per 100 | 3.00 | W-2110FA3 | per 100 1.25 |
| W-1792 | per 100 | 2.00 | W-2000 | per 100 | .03 | W-2129FG-1 | .02 |
| W-1794FA24 | per 100 | .60 | W-2002 | per 100 | .50 | W-2130 | per 100 1.50 |
| W-1802 | per 100 | .03 | W-2005 | per 100 | .10 | W-2134 | per 100 1.00 |
| W-1804 | per 100 | 1.20 | W-2014 | per 100 | .50 | W-2135 | per 100 .45 |
| W-1806 | per 100 | .02 | W-2016 | per 100 | 1.00 | W-2136 | per 100 1.00 |
| W-1820FB-26 | per 100 | 2.50 | W-2017FA-9 | per 100 | 1.25 | W-2138 | per 100 .75 |
| W-1821 | per 100 | .60 | W-2020 | per 100 | .10 | W-2139 | per 100 .60 |
| W-1822 | per 100 | 1.10 | W-2021FA-3 | per 100 | .75 | W-2140 | per 100 2.25 |
| W-1823 | per 100 | 2.50 | W-2023FA-9 | per 100 | .50 | W-2150 | per 100 1.75 |
| W-1826 | per 100 | 2.00 | W-2027 | per 100 | .75 | W-2157 | per 100 1.35 |
| W-1828 | per 100 | 5.00 | W-2028 | per 100 | 2.00 | W-2158FA3 | per 100 1.00 |
| W-1834 | per 100 | .90 | W-2029 | per 100 | .50 | W-2159 | per 100 .15 |
| W-1835FG-1 | per 100 | 2.00 | W-2030 | per 100 | 1.25 | W-2168 | per 100 .75 |
| W-1836 | per 100 | 3.00 | W-2032 | per 100 | .01 | W-2169 | per 100 1.35 |
| W-1837 | per 100 | 2.00 | W-2033FA-9 | per 100 | 2.00 | W-2176FA-4 | per 100 1.25 |
| W-1841 | per 100 | 2.15 | W-2038 | per 100 | 1.50 | W-2177 | per 100 .50 |
| W-1846 | per 100 | .05 | W-2041FA-9 | per 100 | 1.00 | W-2179 | per 100 .75 |
| W-1848 | per 100 | 1.20 | W-2043FA3 | per 100 | 1.00 | W-2183 | per 100 .15 |
| W-1851FC36 | per 100 | .05 | W-2051 | per 100 | .95 | W-2185 | per 100 3.00 |
| W-1852 | per 100 | 1.00 | W-2052-FA9 | per 100 | 1.75 | W-2189 | per 100 2.50 |
| W-1853 | per 100 | 3.00 | W-2054-FA9 | per 100 | .75 | W-2190 | per 100 .04 |
| W-1866FA3 | per 100 | 2.00 | W-2060 | per 100 | 1.00 | W-2192 | per 100 4.00 |
| W-1880FA17 | per 100 | 2.00 | W-2062 | per 100 | .90 | W-2194 | per 100 1.00 |
| W-1885 | per 100 | 1.25 | W-2067-FA3 | per 100 | 2.00 | W-2195 | per 100 .95 |
| W-1886 | per 100 | .10 | W-2068 | per 100 | 2.00 | W-2201 | per 100 .03 |
| W-1907 | per 100 | 4.00 | W-2071FB-26 | per 100 | 2.00 | W-2202 | per 100 1.50 |
| W-1914 | per 100 | .50 | W-2072FB-26 | per 100 | 1.50 | W-2203 | per 100 1.50 |
| W-1921 | per 100 | 1.50 | W-2073FB-26 | per 100 | 1.75 | W-2204FA8 | per 100 1.50 |
| W-1922 | per 100 | 1.35 | W-2074 | per 100 | .05 | W-2208FE7 | per 100 .75 |
| W-1925 | per 100 | 2.50 | W-2076FA9 | per 100 | .50 | W-2209FA9 | per 100 .75 |
| W-1935FA-4 | per 100 | 1.20 | W-2077 | per 100 | .02 | W-2210 | per 100 1.75 |
| W-1937 | per 100 | 2.50 | W-2082 | per 100 | 2.25 | W-2212FA35 | per 100 1.00 |
| W-1938 | per 100 | 3.00 | W-2090 | per 100 | 1.00 | W-2214 | per 100 1.50 |
| | | | | | | W-2219 | per 100 .15 |
| | | | | | | W-2220 | per 100 .10 |
| | | | | | | W-2222-FA3 | per 100 .35 |
| | | | | | | W-2224 | per 100 1.00 |
| | | | | | | W-2225 | per 100 .02 |
| | | | | | | W-2226 | per 100 .05 |
| | | | | | | W-2228 | per 100 2.00 |
| | | | | | | W-2229-FA9 | per 100 1.50 |
| | | | | | | W-2232-FC50 | per 100 .05 |
| | | | | | | W-2235 | per 100 2.00 |
| | | | | | | W-2236 | per 100 .10 |
| | | | | | | W-2239 | per 100 2.50 |
| | | | | | | W-2243 | per 100 .75 |
| | | | | | | W-2245 | per 100 .70 |
| | | | | | | W-2246 | per 100 1.25 |
| | | | | | | W-2258 | per 100 .04 |
| | | | | | | Z-627 | per 100 1.00 |
| | | | | | | Z-630 | per 100 1.00 |
| | | | | | | Z-632 | per 100 1.00 |
| | | | | | | Z-633 | per 100 1.00 |
| | | | | | | Z-634 | per 100 1.00 |
| | | | | | | Z-635 | per 100 1.00 |
| | | | | | | Z-636 | per 100 1.00 |
| | | | | | | Z-637 | per 100 1.00 |
| | | | | | | Z-638 | per 100 1.00 |
| | | | | | | Z-642 | per 100 1.00 |
| | | | | | | Z-644 | per 100 1.00 |
| | | | | | | Z-650 | per 100 1.00 |
| | | | | | | Z-654 | per 100 1.00 |
| | | | | | | Z-658 | per 100 1.00 |
| | | | | | | Z-659 | per 100 1.00 |
| | | | | | | Z-660 | per 100 1.00 |
| | | | | | | Z-666 | per 100 1.00 |
| | | | | | | Z-667 | per 100 1.00 |
| | | | | | | Z-677 | per 100 1.00 |
| | | | | | | Z-682 | per 100 1.00 |
| | | | | | | Z-683 | per 100 1.00 |
| | | | | | | Z-687 | per 100 1.00 |
| | | | | | | Z-764 | per 100 1.00 |
| | | | | | | Z-789 | per 100 1.00 |
| | | | | | | Z-932 | per 100 1.00 |
| | | | | | | Z-933 | per 100 1.00 |
| | | | | | | Z-943 | per 100 1.00 |
| | | | | | | Z-977 | per 100 1.00 |

philcoradio.com

philcoradio.com