

◀ TABLE OF CONTENTS ▶

GENERAL INFORMATION

	Page
Trouble Shooting by Signal Tracing	1
Identifying Power Transformer Leads	3
Identifying Rectifier Sockets and "B" Supply Leads	4
Testing "B" Supply Filter Circuits	4

1950 RADIOS AND RADIO-PHONOGRAPHS

Model	
50-520	9
50-522	17
50-522-I	17
50-524	17
50-526	26
50-527	27
50-527-I	27
50-620	35
50-621	43
50-920	47
50-921	47
50-922	47
50-925	53
50-925 (Code 123)	65
50-926	65
50-1420	73
50-1421	81
50-1422	81
50-1423	82
50-1424	84
50-1718	88
50-1720	92
50-1721	95
50-1723	95
50-1724	95
50-1725	103

1950 TROPIC RADIOS AND RADIO-PHONOGRAPHS

3010 and 3010-1	117
3010 and 3010-1 (Codes 123,124, and 125)	121
3012	125
3113	129
3212	133
3213	137
3411	141
3454	145
3461	141
3462	149

RECORD CHANGER

M-20	153
------------	-----