

PHILCO RADIO-CLOCK, MODEL 51-538

A separate service manual was not issued on this model, because it is the same as Model 51-537, except for the cabinet. The service manual for Models 51-537 and 51-537-I applies to Model 51-538, with the additions to the parts list given below.

REPLACEMENT PARTS LIST

The replacement parts list for Models 51-537 and 51-537-I applies to Model 51-538, with the additions given below.

Description	Service Part No.
Cabinet, white	10745-4
Clock and cable	76-6725
Clock knob, AUTO-OFF-ON	54-4736-5

Description	Service Part No.
Clock knob, DELAYED OFF	54-4736-5
Clock knob, AUTO SET	54-4736-6
Clock knob, TIME SET	54-4736-7
Clock socket	27-6273
Jewel	54-4304-1
Knob, volume	27-4815-7
Receptacle, appliance, a-c	76-3931
Scale	54-5055-4

PRODUCTION CHANGES

Code 122, Run 1

Same changes as for Models 51-537 and 51-537-I, Code 122, Run 1.