PHILCO RADIO-PHONOGRAPH MODEL 51-1736

The service information on Model 51-1732 applies to Model 51-1736, with the exceptions given below.

REPLACEMENT PARTS LIST

The replacement parts list for Model 51-1732 applies to Model 51-1736, with the differences indicated below.

Reference Symbol	Description	Service Part No.
LAI	Loop aerial	27-4785-18
LS1	Speaker	36-1610-9

MISCELLANEOUS

Description	Service Part No
Cabinet, Model 51-1736	10824-4
Bullet catch (2)	45-6002
Dial scale	54-5102
Dome (4)	3363-2
Doors, matched set of 2	
Door pull (2)	
Knife hinge, left hand (2)	
Knife hinge, right hand (2)	
Strike plate (2)	



RECORD CHANGER M-22

